



དཔལ་ལྷན་འབྲུག་གཞུང་། དངལ་རྩིས་ལྷན་ཁག།  
 Royal Government of Bhutan, Ministry of Finance  
 མཉེན་གཉེན་འཛོལ་རྒྱུ་དང་གོང་འཕེལ་སྤེལ་ཚོད་། རྒྱལ་ཡོངས་གཞུང་ཚན་ལས་ཁུངས།  
**Procurement Management and Development Division**



Home Dashboard APP Tender CMS Committees My Account Help

Wednesday, 25 September, 2024, 15:17:18 BST

Last Login : Wednesday, 25 September, 2024, 11:06:05 BST

Welcome, Kinley Buda [Role] | Logout

Tender >> My Tender >> My Tenders/Proposals (Live) >> Tender/Proposal Dashboard >> Opening Process >> View Comparative Report

View Comparative Report

Print Save As Excel Go Back To Dashboard

**Tender Detail**

Tender ID : 18629  
 Closing Date and Time : 14-Sep-2024 16:10  
 Procuring Agency : Dzongkhag Administration Bumthang  
 Brief : Supply of vehicle spare parts and maintenance for the FY 2024-2025  
 Tender Status : Being evaluated

Invitation Reference No. : JKD/Pro-01/2024-2025/261-13  
 Opening Date and Time : 14-Sep-2024 16:10  
 Procurement Category : Goods

[View Notice](#)

Bid Submission Closing Date is thirty (30) minutes prior to Bid Opening Date. For Tender Id: 18629 the Closing Date is 14-Sep-2024 16:10 and Bid Opening Date is 14-Sep-2024 16:40

Package No	Package Description
JKD/Pro-01/2024-2025/261-13	Supply of vehicle spare parts and maintenance

The Bhutan Standards Bureau (BSB) certification requirements followed by words "or equivalent or higher" with which the goods, equipment, materials or workmanship shall comply in their prod

Schedule of Items and Priced Quotation (Form e-SG-1)

Item No.	Name and Description of Item	Unit	Quantity	Point of Delivery	Delivery Period [In Days]	Technical Specification and Standards required	Warranty Period from the date of Acceptance [in days]	Make/Model and Country of Origin				Unit Price in Figure [In Nu.]				Unit Price in Word:		
								Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works	Kuenzom Automobile Workshop	Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works	Kuenzom Automobile Workshop	Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma L Auto En Works
1.0	Arm Bush Lower	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1850.000	0.000	0.000	ZERO	ONE THOUSAND EIGHT HUNDRED FIFTY	ZERO
2.0	Arm Bush Upper	Set	1.000	Respective Procuring Agency	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1950.000	0.000	0.000	ZERO	ONE THOUSAND NINE	ZERO

				Office under Bumthang Dzongkhag													HUNDRED FIFTY	
3.0	Arm Lower	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	9500.000	0.000	0.000	ZERO	NINE THOUSAND FIVE HUNDRED	ZERO
4.0	Arm Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	8950.000	0.000	0.000	ZERO	EIGHT THOUSAND NINE HUNDRED FIFTY	ZERO
5.0	AC Belt	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	3000.000	0.000	0.000	ZERO	THREE THOUSAND	ZERO
6.0	Acceleator Cable	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	3000.000	550.000	0.000	ZERO	THREE THOUSAND	FIVE HUNDRI FIFTY
7.0	Air Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	2950.000	1900.000	0.000	ZERO	TWO THOUSAND NINE HUNDRED FIFTY	ONE THOUS/ NINE HUNDRI
8.0	Anabond	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	450.000	70.000	0.000	ZERO	FOUR HUNDRED FIFTY	SEVENT
9.0	Axle	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	16000.000	2500.000	0.000	ZERO	SIXTEEN THOUSAND	TWO THOUS/ FIVE HUNDRI
10.0	Axle Oil Seal Outer	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1800.000	750.000	0.000	ZERO	ONE THOUSAND EIGHT HUNDRED	SEVEN HUNDRI FIFTY
11.0	Axle Tube Oil Seal	No	1.000	Respective Procuring Agency	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1850.000	0.000	0.000	ZERO	ONE THOUSAND EIGHT	ZERO



				Office under Bumthang Dzongkhag														HUNDRED FIFTY	
12.0	Back Light	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	8950.000	1250.000	0.000	ZERO		EIGHT THOUSAND NINE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED FIFTY
13.0	Back Light Bulb	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	400.000	50.000	0.000	ZERO		FOUR HUNDRED	FIFTY
14.0	Battery	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	14500.000	10950.000	0.000	ZERO		FOURTEEN THOUSAND FIVE HUNDRED	TEN THOUSAND NINE HUNDRED FIFTY
15.0	Ball Joint Lower	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	3000.000	0.000	0.000	ZERO		THREE THOUSAND	ZERO
16.0	Ball Joint Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	3000.000	0.000	0.000	ZERO		THREE THOUSAND	ZERO
17.0	Brake Booster	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	14500.000	0.000	0.000	ZERO		FOURTEEN THOUSAND FIVE HUNDRED	ZERO
18.0	Brake Bucket Kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	3950.000	0.000	0.000	ZERO		THREE THOUSAND NINE HUNDRED FIFTY	ZERO
19.0	Brake Hub Front	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	8950.000	0.000	0.000	ZERO		EIGHT THOUSAND NINE HUNDRED FIFTY	ZERO
20.0	Brake Hub Rear	Set	1.000	Respective Procuring Agency	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	8500.000	2550.000	0.000	ZERO		EIGHT THOUSAND	TWO THOUSAND FIVE

*[Handwritten signature]*

*[Handwritten signature]*

*[Handwritten signature]*

*[Handwritten signature]*

*[Handwritten signature]*

*[Handwritten signature]*

				Office under Bumthang Dzongkhag												FIVE HUNDRED	HUNDRI FIFTY	
21.0	Brake Oil	Lts	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1350.000	180.000	0.000	ZERO	ONE THOUSAND THREE HUNDRED FIFTY	ONE HUNDRI EIGHTY
22.0	Brake Disc	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	7950.000	6500.000	0.000	ZERO	SEVEN THOUSAND NINE HUNDRED FIFTY	SIX THOUS/ FIVE HUNDRI
23.0	Brake Pad	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	6450.000	0.000	0.000	ZERO	SIX THOUSAND FOUR HUNDRED FIFTY	ZERO
24.0	Brake Shoe	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	7850.000	2850.000	0.000	ZERO	SEVEN THOUSAND EIGHT HUNDRED FIFTY	TWO THOUS/ EIGHT HUNDRI FIFTY
25.0	Cam Shaft Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	3950.000	1550.000	0.000	ZERO	THREE THOUSAND NINE HUNDRED FIFTY	ONE THOUS/ FIVE HUNDRI FIFTY
26.0	Center Bolt	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	750.000	0.000	0.000	ZERO	SEVEN HUNDRED FIFTY	ZERO
27.0	Connecting Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	3500.000	2300.000	0.000	ZERO	THREE THOUSAND FIVE HUNDRED	TWO THOUS/ THREE HUNDRI
28.0	Coolant	Lts	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	995.000	380.000	0.000	ZERO	NINE HUNDRED NINETY FIVE	THREE HUNDRI EIGHTY
29.0	Cross Bearing	set	1.000	Respective Procuring Agency	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	2950.000	0.000	0.000	ZERO	TWO THOUSAND NINE	ZERO



				Office under Bumthang Dzongkhag														HUNDRED FIFTY	
30.0	Crown & Tail Assy	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	18500.000	0.000	0.000	ZERO		EIGHTEEN THOUSAND FIVE HUNDRED	ZERO
31.0	CV Joint Assembly	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	9950.000	0.000	0.000	ZERO		NINE THOUSAND NINE HUNDRED FIFTY	ZERO
32.0	Check nut lock	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	350.000	750.000	0.000	ZERO		THREE HUNDRED FIFTY	SEVEN HUNDRED FIFTY
33.0	Clutch Cylinder Lower	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	7850.000	0.000	0.000	ZERO		SEVEN THOUSAND EIGHT HUNDRED FIFTY	ZERO
34.0	Clutch Cylinder Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	7850.000	0.000	0.000	ZERO		SEVEN THOUSAND EIGHT HUNDRED FIFTY	ZERO
35.0	Clutch Plate	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	7850.000	7500.000	0.000	ZERO		SEVEN THOUSAND EIGHT HUNDRED FIFTY	SEVEN THOUSAND FIVE HUNDRED FIFTY
36.0	Connection Rod	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	9500.000	0.000	0.000	ZERO		NINE THOUSAND FIVE HUNDRED	ZERO
37.0	Crank Shaft	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	23500.000	0.000	0.000	ZERO		TWENTY THREE THOUSAND FIVE HUNDRED	ZERO

*[Handwritten signature]*

*[Handwritten mark]*

*[Handwritten mark]*

*[Handwritten signature]*

*[Handwritten signature]*

38.0	Dhoti	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	150.000	10.000	0.000	ZERO	ONE HUNDRED FIFTY	TEN
39.0	Dust Guard	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	3500.000	0.000	0.000	ZERO	THREE THOUSAND FIVE HUNDRED	ZERO
40.0	Disel Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1250.000	250.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED FIFTY	TWO HUNDRI FIFTY
41.0	Engine Mounting	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1100.000	0.000	0.000	ZERO	ONE THOUSAND ONE HUNDRED	ZERO
42.0	Engine Oil Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1200.000	750.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	SEVEN HUNDRI FIFTY
43.0	Fan Belt	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	2450.000	550.000	0.000	ZERO	TWO THOUSAND FOUR HUNDRED FIFTY	FIVE HUNDRI FIFTY
44.0	Feed Pump	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	30000.000	2750.000	0.000	ZERO	THIRTY THOUSAND	TWO THOUS/ SEVEN HUNDRI FIFTY
45.0	Fuel Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1250.000	550.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED FIFTY	FIVE HUNDRI FIFTY
46.0	Fuel Supply Pump	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	29500.000	0.000	0.000	ZERO	TWENTY NINE THOUSAND FIVE HUNDRED	ZERO



47.0	Fog Light	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	8450,000	0.000	0.000	ZERO	EIGHT THOUSAND FOUR HUNDRED FIFTY	ZERO
48.0	Fuse	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	450,000	15,000	0.000	ZERO	FOUR HUNDRED FIFTY	FIFTEEN
49.0	Bear Box	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	33500,000	0.000	0.000	ZERO	THIRTY THREE THOUSAND FIVE HUNDRED	ZERO
50.0	Grease	Kg	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	700,000	380,000	0.000	ZERO	SEVEN HUNDRED	THREE HUNDRI EIGHTY
51.0	Glow Plug	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	2300,000	0.000	0.000	ZERO	TWO THOUSAND THREE HUNDRED	ZERO
52.0	Hand Brake Cable	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	6850,000	0.000	0.000	ZERO	SIX THOUSAND EIGHT HUNDRED FIFTY	ZERO
53.0	Head Gasket	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	3500,000	3500,000	0.000	ZERO	THREE THOUSAND FIVE HUNDRED	THREE THOUS/ FIVE HUNDRI
54.0	Head light Set	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	9500,000	3550,000	0.000	ZERO	NINE THOUSAND FIVE HUNDRED	THREE THOUS/ FIVE HUNDRI FIFTY
55.0	Head Light Bulb	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	450,000	300,000	0.000	ZERO	FOUR HUNDRED FIFTY	THREE HUNDRI

56.0	Hub Oil Seal	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1200.000	750.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	SEVEN HUNDRI FIFTY
57.0	Hub Splender	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	6850.000	9800.000	0.000	ZERO	SIX THOUSAND EIGHT HUNDRED FIFTY	NINE THOUS/ EIGHT HUNDRI
58.0	Horn	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	6500.000	1450.000	0.000	ZERO	SIX THOUSAND FIVE HUNDRED	ONE THOUS/ FOUR HUNDRI FIFTY
59.0	Hub Bearing F Inner	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	4850.000	2550.000	0.000	ZERO	FOUR THOUSAND EIGHT HUNDRED FIFTY	TWO THOUS/ FIVE HUNDRI FIFTY
60.0	Hub Bearing F Out	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	4950.000	2200.000	0.000	ZERO	FOUR THOUSAND NINE HUNDRED FIFTY	TWO THOUS/ TWO HUNDRI
61.0	Hub Check Nut	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1950.000	950.000	0.000	ZERO	ONE THOUSAND NINE HUNDRED FIFTY	NINE HUNDRI FIFTY
62.0	Intake valve	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	3000.000	0.000	0.000	ZERO	THREE THOUSAND	ZERO
63.0	Key Lock Set	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	7850.000	1050.000	0.000	ZERO	SEVEN THOUSAND EIGHT HUNDRED FIFTY	ONE THOUS/ FIFTY
64.0	Kimpin Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	4500.000	0.000	0.000	ZERO	FOUR THOUSAND FIVE HUNDRED	ZERO



65.0	King Pin Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	4850.000	0.000	0.000	ZERO	FOUR THOUSAND EIGHT HUNDRED FIFTY	ZERO
66.0	King pin kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	3450.000	0.000	0.000	ZERO	THREE THOUSAND FOUR HUNDRED FIFTY	ZERO
67.0	Link Rod	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	8500.000	0.000	0.000	ZERO	EIGHT THOUSAND FIVE HUNDRED	ZERO
68.0	Link Bush Front	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1950.000	0.000	0.000	ZERO	ONE THOUSAND NINE HUNDRED FIFTY	ZERO
69.0	Link Bush Rear	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1850.000	0.000	0.000	ZERO	ONE THOUSAND EIGHT HUNDRED FIFTY	ZERO
70.0	Master Cylinder Kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	3850.000	0.000	0.000	ZERO	THREE THOUSAND EIGHT HUNDRED FIFTY	ZERO
71.0	Master Cylinder	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	8950.000	0.000	0.000	ZERO	EIGHT THOUSAND NINE HUNDRED FIFTY	ZERO
72.0	Main Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	6400.000	3500.000	0.000	ZERO	SIX THOUSAND FOUR HUNDRED	THREE THOUSAND FIVE HUNDRED
73.0	Main Bearing Oil Seal	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1450.000	1750.000	0.000	ZERO	ONE THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND SEVEN HUNDRED FIFTY

74.0	Mobile Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1200.000	850,000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	EIGHT HUNDRI FIFTY
75.0	Nuts and Bolts(4 Wheel)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	3950.000	0.000	ZERO	ZERO	THREE THOUSAND NINE HUNDRED FIFTY	ZERO
76.0	Oil Supply Pump	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	8950.000	4500,000	ZERO	ZERO	EIGHT THOUSAND NINE HUNDRED FIFTY	FOUR THOUS/ FIVE HUNDRI
77.0	Power Steering Belt	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	2000,000	0.000	ZERO	ZERO	TWO THOUSAND	ZERO
78.0	Power Steering Oil	ltrs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	750,000	0.000	ZERO	ZERO	SEVEN HUNDRED FIFTY	ZERO
79.0	Pressure Plate	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	8450.000	7800,000	ZERO	ZERO	EIGHT THOUSAND FOUR HUNDRED FIFTY	SEVEN THOUS/ EIGHT HUNDRI
80.0	Piston	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	6850,000	0.000	ZERO	ZERO	SIX THOUSAND EIGHT HUNDRED FIFTY	ZERO
81.0	Piston Ring	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	4500.000	1550,000	ZERO	ZERO	FOUR THOUSAND FIVE HUNDRED	ONE THOUS/ FIVE HUNDRI FIFTY
82.0	Shaft yoke & Teeth	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	7450,000	0.000	ZERO	ZERO	SEVEN THOUSAND FOUR HUNDRED FIFTY	ZERO



83.0	Radiator Cap	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1250.000	350.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED FIFTY	THREE HUNDRI FIFTY
84.0	Rear Axle Corn	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	7850.000	0.000	0.000	ZERO	SEVEN THOUSAND EIGHT HUNDRED FIFTY	ZERO
85.0	Rear Differential Assy	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	18950.000	0.000	0.000	ZERO	EIGHTEEN THOUSAND NINE HUNDRED FIFTY	ZERO
86.0	Release Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	2350.000	1650.000	0.000	ZERO	TWO THOUSAND THREE HUNDRED FIFTY	ONE THOUS/ SIX HUNDRI FIFTY
87.0	Spark Plug	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1750.000	0.000	0.000	ZERO	ONE THOUSAND SEVEN HUNDRED FIFTY	ZERO
88.0	Self Armaure	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	5850.000	4500.000	0.000	ZERO	FIVE THOUSAND EIGHT HUNDRED FIFTY	FOUR THOUS/ FIVE HUNDRI
89.0	Self Carbon	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1450.000	1250.000	0.000	ZERO	ONE THOUSAND FOUR HUNDRED FIFTY	ONE THOUS/ TWO HUNDRI FIFTY
90.0	Self Carnon Rocker	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1950.000	1100.000	0.000	ZERO	ONE THOUSAND NINE HUNDRED FIFTY	ONE THOUS/ ONE HUNDRI
91.0	Self Plunge	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	2350.000	0.000	0.000	ZERO	TWO THOUSAND THREE HUNDRED FIFTY	ZERO

92.0	Shock Absorber Bush	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	750,000	0.000	0.000	0.000	0.000	ZERO	SEVEN HUNDRED FIFTY	ZERO
93.0	Shock Absorber Front	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	5350,000	0.000	0.000	0.000	0.000	ZERO	FIVE THOUSAND THREE HUNDRED FIFTY	ZERO
94.0	Shock Absorber Rear	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	5500,000	0.000	0.000	0.000	0.000	ZERO	FIVE THOUSAND FIVE HUNDRED	ZERO
95.0	Shakle Pin Assy	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	3450,000	0.000	0.000	0.000	0.000	ZERO	THREE THOUSAND FOUR HUNDRED FIFTY	ZERO
96.0	Spring Bush	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	850,000	0.000	0.000	0.000	0.000	ZERO	EIGHT HUNDRED FIFTY	ZERO
97.0	Spring Bush Metal	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1100,000	0.000	0.000	0.000	0.000	ZERO	ONE THOUSAND ONE HUNDRED	ZERO
98.0	Spring Main Rear	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	3950,000	0.000	0.000	0.000	0.000	ZERO	THREE THOUSAND NINE HUNDRED FIFTY	ZERO
99.0	Spring Main -2nd	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	3500,000	0.000	0.000	0.000	0.000	ZERO	THREE THOUSAND FIVE HUNDRED	ZERO
100.0	Spring Main-3rd	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	3400,000	0.000	0.000	0.000	0.000	ZERO	THREE THOUSAND FOUR HUNDRED	ZERO



101.0	Spring Main-4th	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	0.000	3000.000	0.000	0.000	0.000	0.000	0.000	THREE THOUSAND	ZERO
102.0	Spring Main-5th	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	0.000	3000.000	0.000	0.000	0.000	0.000	0.000	THREE THOUSAND	ZERO
103.0	Stabilizer Bar Bush -Front	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	0.000	1450.000	0.000	0.000	0.000	0.000	0.000	ONE THOUSAND FOUR HUNDRED FIFTY	ZERO
104.0	Stabilizer Bar Bush-Rear	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	0.000	1450.000	0.000	0.000	0.000	0.000	0.000	ONE THOUSAND FOUR HUNDRED FIFTY	ZERO
105.0	Steering Damper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	0.000	4500.000	0.000	0.000	0.000	0.000	0.000	FOUR THOUSAND FIVE HUNDRED	ZERO
106.0	Side Light	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	0.000	4950.000	550.000	0.000	0.000	0.000	0.000	FOUR THOUSAND NINE HUNDRED FIFTY	FIVE HUNDRI FIFTY
107.0	Side Light Bulb	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	0.000	500.000	50.000	0.000	0.000	0.000	0.000	FIVE HUNDRED	FIFTY
108.0	Side Light Clamp	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	0.000	4000.000	0.000	0.000	0.000	0.000	0.000	FOUR THOUSAND	ZERO
109.0	Spring Clamp	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	0.000	1850.000	0.000	0.000	0.000	0.000	0.000	ONE THOUSAND EIGHT HUNDRED FIFTY	ZERO

*[Handwritten signatures]*

*[Handwritten signature]*

*[Handwritten mark]*

*[Handwritten signature]*

110.0	Tail Inner Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	4450,000	0.000	0.000	0.000	FOUR THOUSAND FOUR HUNDRED FIFTY	ZERO
111.0	Tail Outer Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	4000,000	0.000	0.000	0.000	FOUR THOUSAND	ZERO
112.0	Tail Oil Seal	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1450,000	0.000	0.000	0.000	ONE THOUSAND FOUR HUNDRED FIFTY	ZERO
113.0	Tie Rod End- Big	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	5850,000	4550,000	0.000	0.000	FIVE THOUSAND EIGHT HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRI FIFTY
114.0	Tie Rod End- Small	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	5350,000	3450,000	0.000	0.000	FIVE THOUSAND THREE HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRI FIFTY
115.0	Timing Belt	Pcs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	2750,000	0.000	0.000	0.000	TWO THOUSAND SEVEN HUNDRED FIFTY	ZERO
116.0	U-Bolt	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1850,000	0.000	0.000	0.000	ONE THOUSAND EIGHT HUNDRED FIFTY	ZERO
117.0	Water pump	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	7850,000	4500,000	0.000	0.000	SEVEN THOUSAND EIGHT HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRI
118.0	Wheel Alignment	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1500,000	350,000	0.000	0.000	ONE THOUSAND FIVE HUNDRED	THREE HUNDRI FIFTY



119.0	Wheel Cylinder Assy	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	8950.000	0.000	0.000	ZERO	EIGHT THOUSAND NINE HUNDRED FIFTY	ZERO
120.0	Wheel Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	4500.000	3400.000	0.000	ZERO	FOUR THOUSAND FIVE HUNDRED	THREE THOUSAND FOUR HUNDRI
121.0	Wiper Blade	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	2500.000	0.000	0.000	ZERO	TWO THOUSAND FIVE HUNDRED	ZERO
122.0	Air cleaner filter changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	500.000	100.000	0.000	ZERO	FIVE HUNDRED	ONE HUNDRI
123.0	Axle oil seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	500.000	1550.000	0.000	ZERO	FIVE HUNDRED	ONE THOUSAND FIVE HUNDRI FIFTY
124.0	Ball joint changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	950.000	0.000	0.000	ZERO	NINE HUNDRED FIFTY	ZERO
125.0	Battery charging (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	500.000	100.000	0.000	ZERO	FIVE HUNDRED	ONE HUNDRI
126.0	Brake adjusting (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1500.000	400.000	0.000	ZERO	ONE THOUSAND FIVE HUNDRED	FOUR HUNDRI
127.0	Brake cable changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1200.000	0.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO

128.0	Brake Pad changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1200.000	0.000	0.000	0.000	ONE THOUSAND TWO HUNDRED	ZERO
129.0	Brake servicing 4 wheel (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	2450.000	1100.000	0.000	0.000	TWO THOUSAND FOUR HUNDRED FIFTY	ONE THOUS/ ONE HUNDRI
130.0	Brake Shoe Changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1250.000	1750.000	0.000	0.000	ONE THOUSAND TWO HUNDRED FIFTY	ONE THOUS/ SEVEN HUNDRI FIFTY
131.0	Chain spocket changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1250.000	0.000	0.000	0.000	ONE THOUSAND TWO HUNDRED FIFTY	ZERO
132.0	Clutch cable changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	950.000	0.000	0.000	0.000	NINE HUNDRED FIFTY	ZERO
133.0	Clutch Kit Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	950.000	0.000	0.000	0.000	NINE HUNDRED FIFTY	ZERO
134.0	Clutch plate/pressure plate changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	4500.000	9500.000	0.000	0.000	FOUR THOUSAND FIVE HUNDRED	NINE THOUS/ FIVE HUNDRI
135.0	Clutch release bearing changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1200.000	9500.000	0.000	0.000	ONE THOUSAND TWO HUNDRED	NINE THOUS/ FIVE HUNDRI
136.0	Complete electrical line checking (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	3500.000	1750.000	0.000	0.000	THREE THOUSAND FIVE HUNDRED	ONE THOUS/ SEVEN HUNDRI FIFTY



137.0	Cross bearing Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1200.000	0.000	0.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO
138.0	Crown overhauling (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	3850.000	0.000	0.000	0.000	ZERO	THREE THOUSAND EIGHT HUNDRED FIFTY	ZERO
139.0	CV joint Boot changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1200.000	0.000	0.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO
140.0	CV Joint changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1200.000	0.000	0.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO
141.0	CV joint oil seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1200.000	0.000	0.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO
142.0	Diesel filter Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1200.000	150.000	0.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	ONE HUNDRI FIFTY
143.0	Driver shaft oil seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1200.000	0.000	0.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO
144.0	Engine Oil Changing with oil filter (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1200.000	350.000	0.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	THREE HUNDRI FIFTY
145.0	Engine over hauling (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	5450.000	25000.000	0.000	0.000	ZERO	FIVE THOUSAND FOUR HUNDRED FIFTY	TWENTY THOUS/ FIVE THOUS/

146.0	Fan belt changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1200.000	250.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	TWO HUNDRI FIFTY
147.0	Front bumper opening & fitting (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	2450.000	0.000	0.000	ZERO	TWO THOUSAND FOUR HUNDRED FIFTY	ZERO
148.0	Gear Box mounting & dismounting (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	5500.000	0.000	0.000	ZERO	FIVE THOUSAND FIVE HUNDRED	ZERO
149.0	Gear oil changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1250.000	450.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED FIFTY	FOUR HUNDRI FIFTY
150.0	Hub greasing (Service Charge)	4 Side	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	2500.000	2000.000	0.000	ZERO	TWO THOUSAND FIVE HUNDRED	TWO THOUS,
151.0	King pin greasing (Service Charge)	2 Side	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1500.000	0.000	0.000	ZERO	ONE THOUSAND FIVE HUNDRED	ZERO
152.0	Knuckle arm fitting (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1450.000	0.000	0.000	ZERO	ONE THOUSAND FOUR HUNDRED FIFTY	ZERO
153.0	Master Cylinder Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1950.000	0.000	0.000	ZERO	ONE THOUSAND NINE HUNDRED FIFTY	ZERO
154.0	Number Plate new making (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	2450.000	350.000	0.000	ZERO	TWO THOUSAND FOUR HUNDRED FIFTY	THREE HUNDRI FIFTY



155.0	Oil Seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1200,000	100,000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	ONE HUNDRI
156.0	Power steering belt changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1200,000	0.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO
157.0	Radiator Servicing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	3950,000	750,000	0.000	ZERO	THREE THOUSAND NINE HUNDRED FIFTY	SEVEN HUNDRI FIFTY
158.0	Removing & Fitting of spring assy (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	2450,000	0.000	0.000	ZERO	TWO THOUSAND FOUR HUNDRED FIFTY	ZERO
159.0	Self starter overhauling (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	3450,000	1250,000	0.000	ZERO	THREE THOUSAND FOUR TWO HUNDRED FIFTY	ONE THOUS THOUS HUNDRI FIFTY
160.0	Shock absorber changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1250,000	0.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED FIFTY	ZERO
161.0	Spring Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1250,000	0.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED FIFTY	ZERO
162.0	Spring Greasing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1950,000	450,000	0.000	ZERO	ONE THOUSAND NINE HUNDRED FIFTY	FOUR HUNDRI FIFTY
163.0	Spring pad changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1500,000	0.000	0.000	ZERO	ONE THOUSAND FIVE HUNDRED	ZERO

164.0	Stabilizer bush changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1200.000	0.000	0.000	0.000	ONE THOUSAND TWO HUNDRED	ZERO
165.0	Stabilizer link assy changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1500.000	0.000	0.000	0.000	ONE THOUSAND FIVE HUNDRED	ZERO
166.0	Steering Rack end assy (Link)changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1500.000	0.000	0.000	0.000	ONE THOUSAND FIVE HUNDRED	ZERO
167.0	suspension arm changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1850.000	0.000	0.000	0.000	ONE THOUSAND EIGHT HUNDRED FIFTY	ZERO
168.0	Tail pinion oil seal changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1200.000	0.000	0.000	0.000	ONE THOUSAND TWO HUNDRED	ZERO
169.0	Tappet adjustment (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	2350.000	450.000	0.000	0.000	TWO THOUSAND THREE HUNDRED FIFTY	FOUR HUNDRI FIFTY
170.0	Tie rod end changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1450.000	1750.000	0.000	0.000	ONE THOUSAND FOUR HUNDRED FIFTY	ONE THOUS/ SEVEN HUNDRI FIFTY
171.0	Timing belt changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1950.000	0.000	0.000	0.000	ONE THOUSAND NINE HUNDRED FIFTY	ZERO
172.0	Tyre Changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	0.0	India	Bhutan	INDIA	0.000	1450.000	400.000	0.000	0.000	ONE THOUSAND FOUR HUNDRED FIFTY	FOUR HUNDRI



173.0	Vane pump changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1500.000	3500.000	0.000	ZERO	ONE THOUSAND FIVE HUNDRED	THREE THOUSAND FIVE HUNDRI
174.0	Welding (Service Charge)	M	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	2450.000	100.000	0.000	ZERO	TWO THOUSAND FOUR HUNDRED FIFTY	ONE HUNDRI
175.0	Wheel Alignment (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1500.000	350.000	0.000	ZERO	ONE THOUSAND FIVE HUNDRED	THREE HUNDRI FIFTY
176.0	Whole body greasing (Service Charge)	Whole body	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	5000.000	750.000	0.000	ZERO	FIVE THOUSAND	SEVEN HUNDRI FIFTY
177.0	Wind shield glass fitting (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	5500.000	0.000	0.000	ZERO	FIVE THOUSAND FIVE HUNDRED	ZERO
178.0	Wiper alignment (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	1200.000	0.000	0.000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO
179.0	Wiper blade changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	0.0	India	Bhutan	INDIA	0.000	300.000	0.000	0.000	ZERO	THREE HUNDRED	ZERO
							<b>Grand Total</b>											

Handwritten notes in blue ink: "Awards did to M/S Yungka Automobile" with a signature and a checkmark.

System Generated Report based on the tender submitted by the Bidders / Consultants



Handwritten signature and stamp in blue ink at the top right corner.