



དཔལ་ལྷན་འབྲུག་གཞུང་། དངུལ་རྩིས་ལྷན་ཁག།
 Royal Government of Bhutan, Ministry of Finance
 མཐོ་གྲུབ་འཛིན་རྫོང་དང་གོང་འཕེལ་ལྟེ་ཚན། རྒྱལ་ཡོངས་གཞུང་ཆས་ལས་ཁུངས།
 Procurement Management and Development Division



Home Dashboard APP Tender CMS Workflow Committees My Account Help

Welcome, Ngawang Chopel [Roles] | Logout

Wednesday, 25 September, 2024, 12:29:00 BST

Last Login : Wednesday, 25 September, 2024, 10:21:09 BST

Tender >> My Tender >> My Tenders/Proposals (Live) >> Tender/Proposal Dashboard >> Opening Process >> View Comparative Report

Print Save As Excel Go Back To Dashboard

View Comparative Report

Tender Detail		Invitation Reference No. : JKD/Pro-01/2024-2025/261-13
Tender ID : 18629	Closing Date and Time : 14-Sep-2024 16:10	Opening Date and Time : 14-Sep-2024 16:10
Procuring Agency : Dzongkhag Administration Bumthang	Brief : <u>Supply of vehicle spare parts and maintenance for the FY 2024-2025</u>	Procurement Category : Goods
Tender Status : Being evaluated	View Notice	

Bid Submission Closing Date is thirty (30) minutes prior to Bid Opening Date. For Tender Id: 18629 the Closing Date is 14-Sep-2024 16:10 and Bid Opening Date is 14-Sep-2024 16:40

Package No	Package Description
JKD/Pro-01/2024-2025/261-13	Supply of vehicle spare parts and maintenance

Schedule of Items and Priced Quotation **CEES POOL, DCM, BUS AND JUMBO TATA**
 The Bhutan Standards Bureau (BSB) certification requirements followed by words "or equivalent or higher" with which the goods, equipment, materials or workmanship shall comply in their pr

Schedule of Items and Priced Quotation (Form e-SG-1)

Item No.	Name and Description of Item	Unit	Quantity	Point of Delivery	Delivery Period [In Days]	Technical Specification and Standards required	Warranty Period from the date of Acceptance [in days]	Make/Model and Country of Origin				Unit Price in Figure [In Nu.]				Unit Price in Work		
								Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works	Kuenzom Automobile Workshop	Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works	Kuenzom Automobile Workshop	Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Auto E Works
1.0	Arm Bush Lower	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	5000.000	1450.000	1250.000	ZERO	FIVE THOUSAND	ONE THOUS FOUR HUNDRED FIFTY

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

2.0	Arm Bush Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	5000.000	1450.000	950.000	ZERO	FIVE THOUSAND	ONE THOUSAND FOUR HUNDRED FIFTY
3.0	Arm Lower	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	27500.000	0.000	0.000	ZERO	TWENTY SEVEN THOUSAND FIVE HUNDRED	ZERO
4.0	Arm Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	27500.000	0.000	0.000	ZERO	TWENTY SEVEN THOUSAND FIVE HUNDRED	ZERO
5.0	AC Belt	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	8450.000	0.000	850.000	ZERO	EIGHT THOUSAND FOUR HUNDRED FIFTY	ZERO
6.0	Acceleator Cable	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	7950.000	1950.000	980.000	FOUR HUNDRED	SEVEN THOUSAND NINE HUNDRED FIFTY	ONE THOUSAND NINE HUNDRED FIFTY
7.0	Air Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2875.000	6450.000	3500.000	3250.000	TWO THOUSAND EIGHT HUNDRED SEVENTY FIVE	SIX THOUSAND FOUR HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED
8.0	Anabond	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	185.000	450.000	70.000	90.000	ONE HUNDRED EIGHTY FIVE	FOUR HUNDRED FIFTY	SEVEN
9.0	Axle	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	6500.000	39500.000	6500.000	14500.000	SIX THOUSAND FIVE HUNDRED	THIRTY NINE THOUSAND FIVE HUNDRED	SIX THOUSAND FIVE HUNDRED
10.0	Axle Oil Seal Outer	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	3850.000	750.000	950.000	FOUR HUNDRED	THREE THOUSAND EIGHT HUNDRED FIFTY	SEVEN HUNDRED FIFTY

11.0	Axle Tube Oil Seal	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	3850,000	750,000	850,000	THREE HUNDRED	THREE THOUSAND EIGHT HUNDRED FIFTY	SEVEN HUND FIFTY
12.0	Back Light	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1450,000	15950,000	1350,000	2200,000	ONE THOUSAND FOUR HUNDRED FIFTY	FIFTEEN THOUSAND NINE HUNDRED FIFTY	ONE THOUS THREE HUND FIFTY
13.0	Back Light Bulb	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	75,000	750,000	25,000	20,000	SEVENTY FIVE	SEVEN HUNDRED FIFTY	TWEN' FIVE
14.0	Battery	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	9500,000	19500,000	8750,000	8125,000	NINE THOUSAND FIVE HUNDRED	NINETEEN THOUSAND FIVE HUNDRED	EIGHT THOUS SEVEN HUND FIFTY
15.0	Ball Joint Lower	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	8500,000	0,000	2250,000	ZERO	EIGHT THOUSAND FIVE HUNDRED	ZERO
16.0	Ball Joint Upper	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	8850,000	0,000	1950,000	ZERO	EIGHT THOUSAND EIGHT HUNDRED FIFTY	ZERO
17.0	Brake Booster	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	5500,000	17500,000	4500,000	32000,000	FIVE THOUSAND FIVE HUNDRED	SEVENTEEN THOUSAND FIVE HUNDRED	FOUR THOUS FIVE HUND FIFTY
18.0	Brake Bucket Kit	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	50,000	8450,000	50,000	550,000	FIFTY	EIGHT THOUSAND FOUR HUNDRED FIFTY	FIFTY
19.0	Brake Hub Front	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	3000,000	17500,000	2950,000	0,000	THREE THOUSAND	SEVENTEEN THOUSAND FIVE HUNDRED	TWO THOUS SEVEN HUND FIFTY

20.0	Brake Hub Rear	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	3000.000	18500.000	2950.000	0.000	THREE THOUSAND	EIGHTEEN THOUSAND FIVE HUNDRED	TWO THOUSAND NINE HUNDRED FIFTY
21.0	Brake Oil	Lts	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300.000	1350.000	190.000	350.000	THREE HUNDRED	ONE THOUSAND THREE HUNDRED FIFTY	ONE HUNDRED NINETEEN
22.0	Brake Disc	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0.000	21500.000	0.000	0.000	ZERO	TWENTY ONE THOUSAND FIVE HUNDRED	ZERO
23.0	Brake Pad	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0.000	19500.000	0.000	5.000	ZERO	NINETEEN THOUSAND FIVE HUNDRED	ZERO
24.0	Brake Shoe	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2750.000	22500.000	1900.000	8500.000	TWO THOUSAND SEVEN HUNDRED FIFTY	TWENTY TWO THOUSAND FIVE HUNDRED	ONE THOUSAND NINE HUNDRED
25.0	Cam Shaft Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	800.000	16500.000	2500.000	850.000	EIGHT HUNDRED	SIXTEEN THOUSAND FIVE HUNDRED	TWO THOUSAND FIVE HUNDRED
26.0	Center Bolt	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	450.000	4500.000	300.000	50.000	FOUR HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRED	THREE HUNDRED
27.0	Connecting Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	800.000	16450.000	3400.000	750.000	EIGHT HUNDRED	SIXTEEN THOUSAND FOUR HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED
28.0	Coolant	Lts	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	250.000	1200.000	380.000	225.000	TWO HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	THREE HUNDRED EIGHT

29.0	Cross Bearing	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2350.000	4950.000	1200.000	4550.000	TWO THOUSAND THREE HUNDRED FIFTY	FOUR THOUSAND NINE HUNDRED FIFTY	ONE THOUS TWO HUND
30.0	Crown & Tail Assy	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	4000.000	84500.000	250000.000	29800.000	FOUR THOUSAND	EIGHTY FOUR THOUSAND FIVE HUNDRED	TWEN FIVE THOUS
31.0	CV Joint Assembly	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	165000.000	0.000	5.000	ZERO	SIXTEEN THOUSAND FIVE HUNDRED	ZERO
32.0	Check nut lock	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	150.000	750.000	750.000	250.000	ONE HUNDRED FIFTY	SEVEN HUNDRED FIFTY	SEVEN HUND FIFTY
33.0	Clutch Cylinder Lower	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	450.000	165000.000	1950.000	5500.000	FOUR HUNDRED FIFTY	SIXTEEN THOUSAND FIVE HUNDRED	ONE THOUS NINE HUND FIFTY
34.0	Clutch Cylinder Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	875.000	175000.000	3400.000	12500.000	EIGHT HUNDRED SEVENTY FIVE	SEVENTEEN THOUSAND FIVE HUNDRED	THREE THOUS FOUR HUND
35.0	Clutch Plate	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	8500.000	185000.000	5850.000	162000.000	EIGHT THOUSAND FIVE HUNDRED	EIGHTEEN THOUSAND FIVE HUNDRED	FIVE THOUS EIGHT HUND FIFTY
36.0	Connection Rod	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1200.000	195000.000	0.000	7500.000	ONE THOUSAND TWO HUNDRED	NINETEEN THOUSAND FIVE HUNDRED	ZERO
37.0	Crank Shaft	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	110000.000	695000.000	0.000	0.000	ELEVEN THOUSAND	SIXTY EIGHT THOUSAND FIVE HUNDRED	ZERO

38.0	Dhoti	Pcs	1*000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	50,000	150,000	10,000	10,000	FIFTY	ONE HUNDRED FIFTY	TEN
39.0	Dust Guard	Pcs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	400,000	5450,000	10,000	650,000	FOUR HUNDRED	FIVE THOUSAND FOUR HUNDRED FIFTY	SIX HUNDRED FIFTY
40.0	Disel Filter	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	3850,000	450,000	1850,000	SIX HUNDRED FIFTY	THREE THOUSAND EIGHT HUNDRED FIFTY	FOUR HUNDRED FIFTY
41.0	Engine Mounting	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	2300,000	1980,000	3200,000	SEVEN HUNDRED FIFTY	TWO THOUSAND THREE HUNDRED	ONE THOUSAND NINE HUNDRED EIGHT
42.0	Engine Oil Filter	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	3850,000	950,000	1250,000	SIX HUNDRED FIFTY	THREE THOUSAND EIGHT HUNDRED FIFTY	NINE HUNDRED FIFTY
43.0	Fan Belt	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	600,000	4950,000	850,000	2950,000	SIX HUNDRED	FOUR THOUSAND NINE HUNDRED FIFTY	EIGHT HUNDRED FIFTY
44.0	Feed Pump	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	4950,000	2500,000	1450,000	SEVEN HUNDRED FIFTY	FORTY NINE THOUSAND FIVE HUNDRED	TWO THOUSAND FIVE HUNDRED
45.0	Fuel Filter	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	600,000	3950,000	650,000	1550,000	SIX HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	SIX HUNDRED FIFTY
46.0	Fuel Supply Pump	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	4950,000	350,000	650,000	SIX HUNDRED FIFTY	FORTY NINE THOUSAND FIVE HUNDRED	THREE HUNDRED FIFTY

47.0	Fog Light	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	19850.000	1550.000	2200.000	SEVEN HUNDRED FIFTY	NINETEEN THOUSAND EIGHT HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED FIFTY
48.0	Fuse	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	25.000	850.000	15.000	10.000	TWENTY FIVE	EIGHT HUNDRED FIFTY	FIFTEE
49.0	Bear Box	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	74500.000	0.000	0.000	THREE HUNDRED	SEVENTY FOUR THOUSAND FIVE HUNDRED	ZERO
50.0	Grease	Kg	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	450.000	850.000	350.000	450.000	FOUR HUNDRED FIFTY	EIGHT HUNDRED FIFTY	THREE HUNDRED FIFTY
51.0	Glow Plug	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	700.000	4950.000	0.000	1850.000	SEVEN HUNDRED	FOUR THOUSAND NINE HUNDRED FIFTY	ZERO
52.0	Hand Brake Cable	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3750.000	19500.000	450.000	1250.000	THREE THOUSAND SEVEN HUNDRED FIFTY	NINETEEN THOUSAND FIVE HUNDRED	FOUR HUNDRED FIFTY
53.0	Head Gasket	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1300.000	9500.000	750.000	4500.000	ONE THOUSAND THREE HUNDRED	NINE THOUSAND FIVE HUNDRED	SEVEN HUNDRED FIFTY
54.0	Head light Set	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1650.000	18500.000	2500.000	3200.000	ONE THOUSAND SIX HUNDRED FIFTY	EIGHTEEN THOUSAND FIVE HUNDRED	TWO THOUSAND FIVE HUNDRED
55.0	Head Light Bulb	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	375.000	750.000	5500.000	150.000	THREE HUNDRED SEVENTY FIVE	SEVEN HUNDRED FIFTY	FIVE THOUSAND FIVE HUNDRED

56.0	Hub Oil Seal	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	450,000	2750,000	950,000	650,000	FOUR HUNDRED FIFTY	TWO THOUSAND SEVEN HUNDRED FIFTY	NINE HUNDRED FIFTY
57.0	Hub Splender	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	3500,000	19500,000	3500,000	20,000	THREE THOUSAND FIVE HUNDRED	NINETEEN THOUSAND FIVE HUNDRED	THREE THOUSAND FIVE HUNDRED
58.0	Horn	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	12000,000	1750,000	850,000	SEVEN HUNDRED FIFTY	TWELVE THOUSAND	ONE THOUSAND SEVEN HUNDRED FIFTY
59.0	Hub Bearing F Inner	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1950,000	16500,000	3500,000	1850,000	ONE THOUSAND NINE HUNDRED FIFTY	SIXTEEN THOUSAND FIVE HUNDRED	THREE THOUSAND FIVE HUNDRED
60.0	Hub Bearing F Out	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1950,000	16450,000	3450,000	1950,000	ONE THOUSAND NINE HUNDRED FIFTY	SIXTEEN THOUSAND FOUR HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED FIFTY
61.0	Hub Check Nut	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	100,000	3950,000	350,000	250,000	ONE HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	THREE HUNDRED FIFTY
62.0	Intake valve	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	900,000	8950,000	0,000	850,000	NINE HUNDRED	EIGHT THOUSAND NINE HUNDRED FIFTY	ZERO
63.0	Key Lock Set	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1340,000	11000,000	0,000	8500,000	ONE THOUSAND THREE HUNDRED FORTY	ELEVEN THOUSAND	ZERO
64.0	Kimpin Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2650,000	9950,000	1250,000	8500,000	TWO THOUSAND SIX HUNDRED FIFTY	NINE THOUSAND NINE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED FIFTY

65.0	King Pin Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	900.000	13500.000	1250.000	6500.000	NINE HUNDRED	THIRTEEN THOUSAND FIVE HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY
66.0	King pin kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	550.000	6450.000	350.000	2200.000	FIVE HUNDRED FIFTY	SIX THOUSAND FOUR HUNDRED FIFTY	THREE HUNDRED FIFTY
67.0	Link Rod	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	23500.000	150.000	5.000	ZERO	TWENTY THREE THOUSAND FIVE HUNDRED	ONE HUNDRED FIFTY
68.0	Link Bush Front	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	4450.000	150.000	5.000	ZERO	FOUR THOUSAND FOUR HUNDRED FIFTY	ONE HUNDRED FIFTY
69.0	Link Bush Rear	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	4550.000	200.000	5.000	ZERO	FOUR THOUSAND FIVE HUNDRED FIFTY	TWO HUNDRED FIFTY
70.0	Master Cylinder Kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	450.000	7950.000	250.000	4500.000	FOUR HUNDRED FIFTY	SEVEN THOUSAND NINE HUNDRED FIFTY	TWO HUNDRED FIFTY
71.0	Master Cylinder	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	700.000	22450.000	4500.000	12500.000	SEVEN HUNDRED	TWENTY TWO THOUSAND FOUR HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRED FIFTY
72.0	Main Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	975.000	7450.000	4500.000	950.000	NINE HUNDRED SEVENTY FIVE	SEVEN THOUSAND FOUR HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRED FIFTY
73.0	Main Bearing Oil Seal	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	950.000	2350.000	550.000	1450.000	NINE HUNDRED FIFTY	TWO THOUSAND THREE HUNDRED FIFTY	FIVE HUNDRED FIFTY

74.0	Mobile Filter	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	3850,000	950,000	950,000	950,000	SIX HUNDRED FIFTY	THREE THOUSAND EIGHT HUNDRED FIFTY	NINE HUNDRED FIFTY
75.0	Nuts and Bolts(4 Wheel)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	8950,000	200,000	10,000	10,000	THREE HUNDRED	EIGHT THOUSAND NINE HUNDRED FIFTY	TWO HUNDRED
76.0	Oil Supply Pump	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	975,000	32500,000	1200,000	550,000	550,000	NINE HUNDRED SEVENTY FIVE	THIRTY TWO THOUSAND FIVE HUNDRED	ONE THOUSAND TWO HUNDRED
77.0	Power Steering Belt	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	5450,000	1100,000	1250,000	1250,000	SIX HUNDRED FIFTY	FIVE THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND ONE HUNDRED
78.0	Power Steering Oil	ltrs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	450,000	1200,000	350,000	550,000	550,000	FOUR HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	THREE HUNDRED FIFTY
79.0	Pressure Plate	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	8750,000	29500,000	6500,000	14500,000	14500,000	EIGHT THOUSAND SEVEN HUNDRED FIFTY	TWENTY NINE THOUSAND FIVE HUNDRED	SIX THOUSAND FIVE HUNDRED
80.0	Piston	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	7000,000	19500,000	0,000	6500,000	6500,000	SEVEN THOUSAND	NINETEEN THOUSAND FIVE HUNDRED	ZERO
81.0	Piston Ring	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	21500,000	0,000	6500,000	6500,000	SEVEN HUNDRED FIFTY	TWENTY ONE THOUSAND FIVE HUNDRED	ZERO
82.0	Shaft yoke & Teeth	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	3250,000	19500,000	3500,000	4580,000	4580,000	THREE THOUSAND TWO HUNDRED FIFTY	NINETEEN THOUSAND FIVE HUNDRED	THREE THOUSAND FIVE HUNDRED

83.0	Radiator Cap	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	400,000	1450,000	250,000	450,000	FOUR HUNDRED	ONE THOUSAND FOUR HUNDRED FIFTY	TWO THOUSAND FIFTY
84.0	Rear Axle Corn	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	800,000	29500,000	150,000	1200,000	EIGHT HUNDRED	TWENTY NINE THOUSAND FIVE HUNDRED	ONE HUND FIFTY
85.0	Rear Differential Assy	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	4500,000	68600,000	0,000	0,000	FOUR THOUSAND FIVE HUNDRED	SIXTY EIGHT THOUSAND SIX HUNDRED	ZERO
86.0	Release Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1875,000	5950,000	1750,000	2250,000	ONE THOUSAND EIGHT HUNDRED SEVENTY FIVE	FIVE THOUSAND NINE HUNDRED FIFTY	ONE THOUS SEVEN HUND FIFTY
87.0	Spark Plug	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	4450,000	0,000	20,000	ZERO	FOUR THOUSAND FOUR HUNDRED FIFTY	ZERO
88.0	Self Armaure	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2100,000	18450,000	2200,000	4500,000	TWO THOUSAND ONE HUNDRED	EIGHTEEN THOUSAND FOUR HUNDRED FIFTY	TWO THOUS TWO HUND F
89.0	Self Carbon	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	700,000	3950,000	1550,000	1450,000	SEVEN HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	ONE THOUS FIVE HUND FIFTY
90.0	Self Carnon Rocker	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	800,000	4500,000	550,000	1250,000	EIGHT HUNDRED	FOUR THOUSAND FIVE HUNDRED	FIVE HUND FIFTY
91.0	Self Plunge	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	975,000	5500,000	450,000	1200,000	NINE HUNDRED SEVENTY FIVE	FIVE THOUSAND FIVE HUNDRED	FOUR HUND FIFTY

92.0	Shock Absorber Bush	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	100,000	1450,000	550,000	120,000	ONE HUNDRED	ONE THOUSAND FOUR HUNDRED FIFTY	FIVE HUNDRED FIFTY
93.0	Shock Absorber Front	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2600,000	22450,000	1750,000	4550,000	TWO THOUSAND SIX HUNDRED	TWENTY TWO THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND SEVEN HUNDRED FIFTY
94.0	Shock Absorber Rear	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2600,000	23500,000	1750,000	3950,000	TWO THOUSAND SIX HUNDRED	TWENTY THREE THOUSAND FIVE HUNDRED	ONE THOUSAND SEVEN HUNDRED FIFTY
95.0	Shackle Pin Assy	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	450,000	16450,000	1650,000	550,000	FOUR HUNDRED FIFTY	SIXTEEN THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND SIX HUNDRED FIFTY
96.0	Spring Bush	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	150,000	2850,000	150,000	150,000	ONE HUNDRED FIFTY	TWO THOUSAND EIGHT HUNDRED FIFTY	ONE HUNDRED FIFTY
97.0	Spring Bush Metal	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	3500,000	550,000	950,000	SIX HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED	FIVE HUNDRED FIFTY
98.0	Spring Main Rear	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	3650,000	9450,000	3500,000	3200,000	THREE THOUSAND SIX HUNDRED FIFTY	NINE THOUSAND FOUR HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED
99.0	Spring Main -2nd	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	3500,000	9000,000	2850,000	2800,000	THREE THOUSAND FIVE HUNDRED	NINE THOUSAND	TWO THOUSAND EIGHT HUNDRED FIFTY
100.0	Spring Main-3rd	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	3200,000	9000,000	1350,000	2500,000	THREE THOUSAND TWO HUNDRED	NINE THOUSAND	ONE THOUSAND THREE HUNDRED FIFTY

101.0	Spring Main-4th	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2975.000	8850.000	1200.000	2200.000	TWO THOUSAND NINE HUNDRED SEVENTY FIVE	EIGHT THOUSAND EIGHT HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED
102.0	Spring Main-5th	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2750.000	8500.000	1100.000	1800.000	TWO THOUSAND SEVEN HUNDRED FIFTY	EIGHT THOUSAND FIVE HUNDRED	ONE THOUSAND ONE HUNDRED
103.0	Stabilizer Bar Bush -Front	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	100.000	3450.000	450.000	20.000	ONE HUNDRED	THREE THOUSAND FOUR HUNDRED FIFTY	FOUR HUNDRED FIFTY
104.0	Stabilizer Bar Bush-Rear	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	100.000	3750.000	750.000	20.000	ONE HUNDRED	THREE THOUSAND SEVEN HUNDRED FIFTY	SEVEN HUNDRED FIFTY
105.0	Steering Damper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3000.000	16450.000	3500.000	2250.000	THREE THOUSAND	SIXTEEN THOUSAND FOUR HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED
106.0	Side Light	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	14500.000	50.000	650.000	SIX HUNDRED FIFTY	FOURTEEN THOUSAND FIVE HUNDRED	FIFTY
107.0	Side Light Bulb	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	75.000	500.000	25.000	20.000	SEVENTY FIVE	FIVE HUNDRED	TWENTY FIVE
108.0	Side Light Clamp	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	8500.000	50.000	350.000	FIFTY	EIGHT THOUSAND FIVE HUNDRED	FIFTY
109.0	Spring Clamp	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	4500.000	50.000	450.000	TWO HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRED	FIFTY

110.0	Tail Inner Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	950,000	12500,000	1750,000	1850,000	NINE HUNDRED FIFTY	TWELVE THOUSAND FIVE HUNDRED	ONE THOUSAND SEVEN HUNDRED FIFTY
111.0	Tail Outer Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	950,000	12500,000	1950,000	2200,000	NINE HUNDRED FIFTY	TWELVE THOUSAND FIVE HUNDRED	ONE THOUSAND NINE HUNDRED FIFTY
112.0	Tail Oil Seal	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	550,000	2500,000	750,000	550,000	FIVE HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED	SEVEN HUNDRED FIFTY
113.0	Tie Rod End-Big	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1850,000	18950,000	2300,000	3950,000	ONE THOUSAND EIGHT HUNDRED FIFTY	EIGHTEEN THOUSAND NINE HUNDRED FIFTY	TWO THOUSAND THREE HUNDRED
114.0	Tie Rod End-Small	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1850,000	18500,000	2200,000	3950,000	ONE THOUSAND EIGHT HUNDRED FIFTY	EIGHTEEN THOUSAND FIVE HUNDRED	TWO THOUSAND TWO HUNDRED
115.0	Timing Belt	Pcs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1850,000	5350,000	450,000	5,000	ONE THOUSAND EIGHT HUNDRED FIFTY	FIVE THOUSAND THREE HUNDRED FIFTY	FOUR HUNDRED FIFTY
116.0	U-Bolt	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	375,000	3950,000	450,000	550,000	THREE HUNDRED SEVENTY FIVE	THREE THOUSAND NINE HUNDRED FIFTY	FOUR HUNDRED FIFTY
117.0	Water pump	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2500,000	16450,000	4500,000	6800,000	TWO THOUSAND FIVE HUNDRED	SIXTEEN THOUSAND FOUR HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRED
118.0	Wheel Alignment	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	350,000	3350,000	350,000	400,000	THREE HUNDRED FIFTY	THREE THOUSAND THREE HUNDRED FIFTY	THREE HUNDRED FIFTY

119.0	Wheel Cylinder Assy	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1900.000	26500.000	2500.000	5250.000	ONE THOUSAND NINE HUNDRED	TWENTY SIX THOUSAND FIVE HUNDRED	TWO THOUSAND FIVE HUNDRED
120.0	Wheel Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1950.000	18950.000	2300.000	2950.000	ONE THOUSAND NINE HUNDRED FIFTY	EIGHTEEN THOUSAND NINE HUNDRED FIFTY	TWO THOUSAND THREE HUNDRED
121.0	Wiper Blade	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	850.000	3450.000	750.000	500.000	EIGHT HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED FIFTY	SEVEN HUNDRED FIFTY
122.0	Air cleaner filter changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	500.000	50.000	50.000	FIFTY	FIVE HUNDRED	FIFTY
123.0	Axle oil seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	500.000	750.000	250.000	THREE HUNDRED	FIVE HUNDRED	SEVEN HUNDRED FIFTY
124.0	Ball joint changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	950.000	0.000	450.000	ZERO	NINE HUNDRED FIFTY	ZERO
125.0	Battery charging (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	100.000	500.000	250.000	50.000	ONE HUNDRED	FIVE HUNDRED	TWO HUNDRED FIFTY
126.0	Brake adjusting (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	1500.000	400.000	200.000	TWO HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	FOUR HUNDRED
127.0	Brake cable changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	275.000	1200.000	250.000	150.000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND TWO HUNDRED	TWO HUNDRED FIFTY

GP

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

128.0	Brake Pad changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	1200.000	0.000	5.000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED	ZERO
129.0	Brake servicing 4 wheel (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	800.000	2450.000	1800.000	200.000	EIGHT HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND EIGHT HUNDRED FIFTY
130.0	Brake Shoe Changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	1450.000	1450.000	300.000	FOUR HUNDRED	ONE THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY
131.0	Chain spocket changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	1450.000	0.000	500.000	SIX HUNDRED FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	ZERO
132.0	Clutch cable changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	1450.000	0.000	250.000	TWO HUNDRED FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	ZERO
133.0	Clutch Kit Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	200.000	1200.000	250.000	50.000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED	TWO HUNDRED FIFTY
134.0	Clutch plate/pressure plate changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	5000.000	4500.000	4500.000	2400.000	FIVE THOUSAND	FOUR THOUSAND FIVE HUNDRED	FOUR THOUSAND FIVE HUNDRED
135.0	Clutch release bearing changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1500.000	1200.000	4500.000	1100.000	ONE THOUSAND FIVE HUNDRED	ONE THOUSAND TWO HUNDRED	FOUR THOUSAND FIVE HUNDRED
136.0	Complete electrical line checking (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	350.000	3500.000	3400.000	200.000	THREE HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED	THREE THOUSAND FIVE HUNDRED

137.0	Cross bearing Changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	1200,000	550,000	250,000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED	FIVE HUNDRED FIFTY
138.0	Crown overhauling (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	3850,000	65000,000	980,000	SEVEN HUNDRED FIFTY	THREE THOUSAND EIGHT HUNDRED FIFTY	SIX THOUSAND FIVE HUNDRED FIFTY
139.0	CV joint Boot changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	1200,000	0,000	5,000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO
140.0	CV Joint changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	1200,000	0,000	5,000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO
141.0	CV joint oil seal changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	1200,000	0,000	350,000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO
142.0	Diesel filter Changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	250,000	1200,000	150,000	150,000	TWO HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	ONE HUNDRED FIFTY
143.0	Driver shaft oil seal changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	365,000	1200,000	0,000	20,000	THREE HUNDRED SIXTY FIVE	ONE THOUSAND TWO HUNDRED	ZERO
144.0	Engine Oil Changing with oil filter (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	400,000	1200,000	350,000	200,000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED	THREE HUNDRED FIFTY
145.0	Engine overhauling (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	6500,000	5950,000	45000,000	2400,000	SIX THOUSAND FIVE HUNDRED	FIVE THOUSAND NINE HUNDRED FIFTY	FORTY FIVE THOUSAND

146.0	Fan belt changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	200,000	1200,000	450,000	250,000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED	FOUR HUNDRED FIFTY
147.0	Front bumper opening & fitting (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	500,000	2450,000	450,000	350,000	FIVE HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	FOUR HUNDRED FIFTY
148.0	Gear Box mounting & dismounting (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	275,000	5500,000	1750,000	550,000	TWO HUNDRED SEVENTY FIVE	FIVE THOUSAND FIVE HUNDRED	ONE THOUSAND SEVEN HUNDRED FIFTY
149.0	Gear oil changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	200,000	1250,000	250,000	200,000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	TWO HUNDRED FIFTY
150.0	Hub greasing (Service Charge)	4 Side	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	900,000	2500,000	2800,000	550,000	NINE HUNDRED	TWO THOUSAND FIVE HUNDRED	TWO THOUSAND EIGHT HUNDRED
151.0	King pin greasing (Service Charge)	2 Side	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	800,000	1500,000	2550,000	250,000	EIGHT HUNDRED	ONE THOUSAND FIVE HUNDRED	TWO THOUSAND FIVE HUNDRED FIFTY
152.0	Knuckle arm fitting (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	250,000	1450,000	1750,000	20,000	TWO HUNDRED FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND SEVEN HUNDRED FIFTY
153.0	Master Cylinder Changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	175,000	1950,000	750,000	450,000	ONE HUNDRED SEVENTY FIVE	ONE THOUSAND NINE HUNDRED FIFTY	SEVEN HUNDRED FIFTY
154.0	Number Plate new making (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	2450,000	350,000	400,000	SIX HUNDRED FIFTY	TWO THOUSAND FOUR HUNDRED FIFTY	THREE HUNDRED FIFTY

155.0	Oil Seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1200.000	250.000	350.000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED	TWO HUND FIFTY
156.0	Power steering belt changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	200.000	1200.000	550.000	250.000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED	FIVE HUND FIFTY
157.0	Radiator Servicing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1500.000	3950.000	650.000	1100.000	ONE THOUSAND FIVE HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	SIX HUND FIFTY
158.0	Removing & Fitting of spring assy (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	2450.000	1250.000	450.000	FOUR HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	ONE THOUS TWO HUND FIFTY
159.0	Self starter overhauling (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1500.000	3450.000	1250.000	1100.000	ONE THOUSAND FIVE HUNDRED	THREE THOUSAND FOUR HUNDRED FIFTY	ONE THOUS TWO HUND FIFTY
160.0	Shock absorber changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1250.000	500.000	150.000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	FIVE HUND FIFTY
161.0	Spring Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	350.000	1250.000	1250.000	450.000	THREE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED FIFTY	ONE THOUS TWO HUND FIFTY
162.0	Spring Greasing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	275.000	1950.000	550.000	200.000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND NINE HUNDRED FIFTY	FIVE HUND FIFTY
163.0	Spring pad changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	120.000	1500.000	450.000	400.000	ONE HUNDRED TWENTY	ONE THOUSAND FIVE HUNDRED	FOUR HUND FIFTY

164.0	Stabilizer bush changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	50,000	1200,000	450,000	20,000	FIFTY	ONE THOUSAND TWO HUNDRED	FOUR HUNDRED FIFTY
165.0	Stabilizer link assy changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	250,000	1500,000	450,000	20,000	TWO HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	FOUR HUNDRED FIFTY
166.0	Steering Rack end assy (Link)changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	1500,000	1200,000	350,000	THREE HUNDRED	ONE THOUSAND FIVE HUNDRED	ONE THOUSAND TWO HUNDRED
167.0	suspension arm changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	1850,000	0,000	250,000	ZERO	ONE THOUSAND EIGHT HUNDRED FIFTY	ZERO
168.0	Tall pinion oil seal changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	325,000	1200,000	2500,000	250,000	THREE HUNDRED TWENTY FIVE	ONE THOUSAND TWO HUNDRED	TWO THOUSAND FIVE HUNDRED
169.0	Tappet adjustment (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	500,000	2350,000	250,000	200,000	FIVE HUNDRED	TWO THOUSAND THREE HUNDRED FIFTY	TWO HUNDRED FIFTY
170.0	Tie rod end changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	275,000	1450,000	1500,000	350,000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED
171.0	Timing belt changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	1950,000	0,000	850,000	SEVEN HUNDRED FIFTY	ONE THOUSAND NINE HUNDRED FIFTY	ZERO
172.0	Tyre Changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	1450,000	200,000	200,000	SEVEN HUNDRED FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	TWO HUNDRED

173.0	Vane pump changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1500.000	4500.000	250.000	THREE HUNDRED	ONE THOUSAND FIVE HUNDRED	FOUR THOUSAND FIVE HUNDRED
174.0	Welding (Service Charge)	M	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	2450.000	100.000	100.000	ZERO	TWO THOUSAND FOUR HUNDRED FIFTY	ONE HUNDRED
175.0	Wheel Alignment (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	350.000	1500.000	350.000	400.000	THREE HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	THREE HUNDRED FIFTY
176.0	Whole body greasing (Service Charge)	Whole body	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	800.000	5000.000	750.000	250.000	EIGHT HUNDRED	FIVE THOUSAND	SEVEN HUNDRED FIFTY
177.0	Wind shield glass fitting (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2500.000	5500.000	3500.000	1200.000	TWO THOUSAND FIVE HUNDRED	FIVE THOUSAND FIVE HUNDRED	THREE THOUSAND FIVE HUNDRED
178.0	Wiper alignment (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	100.000	1200.000	150.000	50.000	ONE HUNDRED	ONE THOUSAND TWO HUNDRED	ONE HUNDRED FIFTY
179.0	Wiper blade changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	300.000	50.000	20.000	FIFTY	THREE HUNDRED	FIFTY
							Grand Total											

1 ⊗ Awarded to Keenrom Automobile

System Generated Report based on the tender submitted by the Bidders / Consultants

Home | About e-GP | Contact Us | Terms and Conditions | e-Learning



[Handwritten signature]

[Handwritten signature]

[Handwritten signature]