



དཔལ་ལྷན་འབྲུག་གཞུང་། དངུལ་རྩིས་ལྷན་ཁག།
 Royal Government of Bhutan, Ministry of Finance



མཐོ་གྲུབ་འཛོལ་སྐྱོད་དང་གོང་འཕེལ་ལྗེ་ཚན། རྒྱལ་ཡོངས་གཞུང་ཚས་ལས་ཁུངས།
 Procurement Management and Development Division

Tender >> My Tender >> My Tenders/Proposals (Live) >> Tender/Proposal Dashboard >> Opening Process >> View Comparative Report

View Comparative Report

Print Save As Excel Go Back To Dashboard

Tender Detail

Tender ID : 18629 Invitation Reference No. : JKD/Pro-01/2024-2025/261-13
 Closing Date and Time : 14-Sep-2024 16:10 Opening Date and Time : 14-Sep-2024 16:10
 Procuring Agency : Dzongkhag Administration Bumthang Procurement Category : Goods
 Brief : Supply of vehicle spare parts and maintenance for the FY 2024-2025
 Tender Status : Being evaluated

[View Notice](#)

Bid Submission Closing Date is thirty (30) minutes prior to Bid Opening Date. For Tender Id: 18629 the Closing Date is 14-Sep-2024 16:10 and Bid Opening Date is 14-Sep-2024 16:40

Package No	Package Description
JKD/Pro-01/2024-2025/261-13	Supply of vehicle spare parts and maintenance

Schedule of Items and Priced Quotation **MARUTI VAN**
 The Bhutan Standards Bureau (BSB) certification requirements followed by words "or equivalent or higher" with which the goods, equipment, materials or workmanship shall comply in their prod

Schedule of Items and Priced Quotation (Form e-SG-1)

Item No.	Name and Description of Item	Unit	Quantity	Point of Delivery	Delivery Period [In Days]	Technical Specification and Standards required	Warranty Period from the date of Acceptance [in days]	Make/Model and Country of Origin				Unit Price in Figure [In Nu.]				Unit Price in Words		
								Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works	Kuenzom Automobile Workshop	Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works	Kuenzom Automobile Workshop	Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works
10	Arm Bush Lower	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	200,000	1350,000	20,000	20,000	TWO HUNDRED	ONE THOUSAND THREE HUNDRED FIFTY	TWENTY
	Arm Bush Upper	Set	1,000	Respective Procuring Agency	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	200,000	1250,000	50,000	20,000	TWO HUNDRED	ONE THOUSAND TWO	FIFTY

Handwritten signature

30

Handwritten signature

Handwritten signature

Handwritten signature

Handwritten signature

Handwritten signature

				Office under Bumthang Dzongkhag												HUNDRED FIFTY		
	Arm Lower	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	850.000	7950.000	20.000	1080.000	EIGHT HUNDRED FIFTY	SEVEN THOUSAND NINE HUNDRED FIFTY	TWENTY
4.0	Arm Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	7850.000	20.000	20.000	SEVEN HUNDRED FIFTY	SEVEN THOUSAND EIGHT HUNDRED FIFTY	TWENTY
5.0	AC Belt	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	1950.000	0.000	350.000	ZERO	ONE THOUSAND NINE HUNDRED FIFTY	ZERO
6.0	Acceleator Cable	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	1850.000	0.000	480.000	TWO HUNDRED FIFTY	ONE THOUSAND EIGHT HUNDRED FIFTY	ZERO
7.0	Air Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	2000.000	0.000	580.000	SIX HUNDRED FIFTY	TWO THOUSAND	ZERO
8.0	Anabond	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	185.000	450.000	70.000	90.000	ONE HUNDRED EIGHTY FIVE	FOUR HUNDRED FIFTY	SEVENTY
9.0	Axle	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1500.000	7850.000	0.000	2950.000	ONE THOUSAND FIVE HUNDRED	SEVEN THOUSAND EIGHT HUNDRED FIFTY	ZERO
10.0	Axle Oil Seal Outer	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	950.000	100.000	150.000	TWO HUNDRED FIFTY	NINE HUNDRED FIFTY	ONE HUNDRE

11.0	Axle Tube Oil Seal	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	200,000	950,000	100,000	80,000	TWO HUNDRED	NINE HUNDRED FIFTY	ONE HUNDRE
12.0	Back Light	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	6500,000	350,000	680,000	SEVEN HUNDRED FIFTY	SIX THOUSAND FIVE HUNDRED	THREE HUNDRE FIFTY
13.0	Back Light Bulb	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	50,000	400,000	25,000	20,000	FIFTY	FOUR HUNDRED	TWENTY FIVE
14.0	Battery	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	4850,000	9950,000	4500,000	4950,000	FOUR THOUSAND EIGHT HUNDRED FIFTY	NINE THOUSAND NINE HUNDRED FIFTY	FOUR THOUSA FIVE HUNDRE
15.0	Ball Joint Lower	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	700,000	2500,000	0,000	20,000	SEVEN HUNDRED	TWO THOUSAND FIVE HUNDRED	ZERO
16.0	Ball Joint Upper	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	2500,000	0,000	20,000	SIX HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED	ZERO
17.0	Brake Booster	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	3000,000	8950,000	1700,000	8900,000	THREE THOUSAND	EIGHT THOUSAND NINE HUNDRED FIFTY	ONE THOUSA SEVEN HUNDRE
18.0	Brake Bucket Kit	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	50,000	2500,000	15,000	55,000	FIFTY	TWO THOUSAND FIVE HUNDRED	FIFTEEN
19.0	Brake Hub Front	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1800,000	7500,000	950,000	0,000	ONE THOUSAND EIGHT HUNDRED	SEVEN THOUSAND FIVE HUNDRED	NINE HUNDRE FIFTY

20.0	Brake Hub Rear	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1500.000	7500.000	1550.000	0.000	ONE THOUSAND FIVE HUNDRED	SEVEN THOUSAND FIVE HUNDRED	ONE THOUSAND FIVE HUNDRE FIFTY
21.0	Brake Oil	Lts	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300.000	1350.000	180.000	200.000	THREE HUNDRED	ONE THOUSAND THREE HUNDRED FIFTY	ONE HUNDRE EIGHTY
22.0	Brake Disc	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1200.000	4500.000	950.000	2250.000	ONE THOUSAND TWO HUNDRED	FOUR THOUSAND FIVE HUNDRED	NINE HUNDRE FIFTY
23.0	Brake Pad	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1350.000	3950.000	950.000	2450.000	ONE THOUSAND THREE HUNDRED FIFTY	THREE THOUSAND NINE HUNDRED FIFTY	NINE HUNDRE FIFTY
24.0	Brake Shoe	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1750.000	4450.000	1100.000	1480.000	ONE THOUSAND SEVEN HUNDRED FIFTY	FOUR THOUSAND FOUR HUNDRED FIFTY	ONE THOUSA ONE HUNDRE
25.0	Cam Shaft Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650.000	2500.000	100.000	250.000	SIX HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED	ONE HUNDRE
26.0	Center Bolt	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	125.000	750.000	750.000	50.000	ONE HUNDRED TWENTY FIVE	SEVEN HUNDRED FIFTY	SEVEN HUNDRE FIFTY
27.0	Connecting Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750.000	2350.000	350.000	450.000	SEVEN HUNDRED FIFTY	TWO THOUSAND THREE HUNDRED FIFTY	THREE HUNDRE FIFTY
28.0	Coolant	Lts	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	250.000	995.000	490.000	225.000	TWO HUNDRED FIFTY	NINE HUNDRED NINETY FIVE	FOUR HUNDRE NINETY

29.0	Cross Bearing	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1350.000	2350.000	9500.000	1390.000	ONE THOUSAND THREE HUNDRED FIFTY	TWO THOUSAND THREE HUNDRED FIFTY	NINE THOUSAND FIVE HUNDRE
30.0	Crown & Tail Assy	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3000.000	23500.000	0.000	8500.000	THREE THOUSAND	TWENTY THREE THOUSAND FIVE HUNDRED	ZERO
31.0	CV Joint Assembly	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	5450.000	200.000	5.000	ZERO	FIVE THOUSAND FOUR HUNDRED FIFTY	TWO HUNDRE
32.0	Check nut lock	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	350.000	0.000	50.000	FIFTY	THREE HUNDRED FIFTY	ZERO
33.0	Clutch Cylinder Lower	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	450.000	5500.000	0.000	1850.000	FOUR HUNDRED FIFTY	FIVE THOUSAND FIVE HUNDRED	ZERO
34.0	Clutch Cylinder Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	600.000	5450.000	1750.000	3550.000	SIX HUNDRED	FIVE THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND SEVEN HUNDRE FIFTY
35.0	Clutch Plate	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2100.000	4850.000	850.000	1560.000	TWO THOUSAND ONE HUNDRED	FOUR THOUSAND EIGHT HUNDRED FIFTY	EIGHT HUNDRE FIFTY
36.0	Connection Rod	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	4500.000	750.000	590.000	SIX HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRED	SEVEN HUNDRE FIFTY
37.0	Crank Shaft	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	4000.000	9450.000	750.000	5950.000	FOUR THOUSAND	NINE THOUSAND FOUR HUNDRED FIFTY	SEVEN HUNDRE FIFTY

38.0	Dhoti	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	150.000	10.000	10.000	FIFTY	ONE HUNDRED FIFTY	TEN
39.0	Dust Guard	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	2850.000	550.000	550.000	THREE HUNDRED	TWO THOUSAND EIGHT HUNDRED FIFTY	FIVE HUNDRE FIFTY
40.0	Disel Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	700.000	0.000	550.000	ZERO	SEVEN HUNDRED	ZERO
41.0	Engine Mounting	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	450.000	500.000	550.000	650.000	FOUR HUNDRED FIFTY	FIVE HUNDRED	FIVE HUNDRE FIFTY
42.0	Engine Oil Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	200.000	850.000	180.000	150.000	TWO HUNDRED	EIGHT HUNDRED FIFTY	ONE HUNDRE EIGHTY
43.0	Fan Belt	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1750.000	160.000	250.000	THREE HUNDRED	ONE THOUSAND SEVEN HUNDRED FIFTY	ONE HUNDRE SIXTY
44.0	Feed Pump	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	11450.000	0.000	650.000	ZERO	ELEVEN THOUSAND FOUR HUNDRED FIFTY	ZERO
45.0	Fuel Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	700.000	450.000	550.000	SIX HUNDRED FIFTY	SEVEN HUNDRED	FOUR HUNDRE FIFTY
46.0	Fuel Supply Pump	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	500.000	11000.000	1750.000	350.000	FIVE HUNDRED	ELEVEN THOUSAND	ONE THOUSA SEVEN HUNDRE FIFTY

47.0	Fog Light	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	6000.000	1650.000	1250.000	SEVEN HUNDRED FIFTY	SIX THOUSAND	ONE THOUSAND SIX HUNDRE FIFTY
48.0	Fuse	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	25.000	300.000	15.000	10.000	TWENTY FIVE	THREE HUNDRED	FIFTEEN
49.0	Bear Box	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	175.000	29500.000	0.000	14500.000	ONE HUNDRED SEVENTY FIVE	TWENTY NINE THOUSAND FIVE HUNDRED	ZERO
50.0	Grease	Kg	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	450.000	700.000	350.000	300.000	FOUR HUNDRED FIFTY	SEVEN HUNDRED	THREE HUNDRE FIFTY
51.0	Glow Plug	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	1850.000	0.000	5.000	ZERO	ONE THOUSAND EIGHT HUNDRED FIFTY	ZERO
52.0	Hand Brake Cable	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1200.000	3950.000	550.000	1150.000	ONE THOUSAND TWO HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	FIVE HUNDRE FIFTY
53.0	Head Gasket	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	450.000	2850.000	650.000	580.000	FOUR HUNDRED FIFTY	TWO THOUSAND EIGHT HUNDRED FIFTY	SIX HUNDRE FIFTY
54.0	Head light Set	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2500.000	6500.000	4500.000	1450.000	TWO THOUSAND FIVE HUNDRED	SIX THOUSAND FIVE HUNDRED	FOUR THOUSAND FIVE HUNDRE
55.0	Head Light Bulb	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	375.000	450.000	300.000	150.000	THREE HUNDRED SEVENTY FIVE	FOUR HUNDRED FIFTY	THREE HUNDRE

56.0	Hub Oil Seal	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	850,000	50,000	150,000	THREE HUNDRED	EIGHT HUNDRED FIFTY	FIFTY
57.0	Hub Splender	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1650,000	4500,000	0.000	20,000	ONE THOUSAND SIX HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRED	ZERO
58.0	Horn	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	4950,000	980,000	800,000	SIX HUNDRED FIFTY	FOUR THOUSAND NINE HUNDRED FIFTY	NINE HUNDRE EIGHTY
59.0	Hub Bearing F Inner	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1300,000	3450,000	950,000	480,000	ONE THOUSAND THREE HUNDRED	THREE THOUSAND FOUR HUNDRED FIFTY	NINE HUNDRE FIFTY
60.0	Hub Bearing F Out	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1300,000	3500,000	350,000	380,000	ONE THOUSAND THREE HUNDRED	THREE THOUSAND FIVE HUNDRED	THREE HUNDRE FIFTY
61.0	Hub Check Nut	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	100,000	1200,000	50,000	120,000	ONE HUNDRED	ONE THOUSAND TWO HUNDRED	FIFTY
62.0	Intake valve	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	600,000	1995,000	1750,000	350,000	SIX HUNDRED	ONE THOUSAND NINE HUNDRED NINETY FIVE	ONE THOUSAND SEVEN HUNDRE FIFTY
63.0	Key Lock Set	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1100,000	4850,000	2600,000	4550,000	ONE THOUSAND ONE HUNDRED	FOUR THOUSAND EIGHT HUNDRED FIFTY	TWO THOUSAND SIX HUNDRE
64.0	Kimpin Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0.000	3950,000	0.000	5,000	ZERO	THREE THOUSAND NINE HUNDRED FIFTY	ZERO

65.0	King Pin Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	Bhutan	INDIA	0,000	3950,000	0,000	5,000	ZERO	THREE THOUSAND NINE HUNDRED FIFTY	ZERO
66.0	King pin kit	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	Bhutan	INDIA	0,000	2500,000	0,000	5,000	ZERO	TWO THOUSAND FIVE HUNDRED	ZERO
67.0	Link Rod	Pcs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	Bhutan	INDIA	650,000	4350,000	0,000	5,000	SIX HUNDRED FIFTY	FOUR THOUSAND THREE HUNDRED FIFTY	ZERO
68.0	Link Bush Front	Pcs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	Bhutan	INDIA	50,000	1200,000	0,000	5,000	FIFTY	ONE THOUSAND TWO HUNDRED	ZERO
69.0	Link Bush Rear	Pcs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	Bhutan	INDIA	50,000	1200,000	0,000	5,000	FIFTY	ONE THOUSAND TWO HUNDRED	ZERO
70.0	Master Cylinder Kit	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	Bhutan	INDIA	200,000	2350,000	50,000	1850,000	TWO HUNDRED	TWO THOUSAND THREE HUNDRED FIFTY	FIFTY
71.0	Master Cylinder	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	Bhutan	INDIA	400,000	5850,000	1750,000	5980,000	FOUR HUNDRED	FIVE THOUSAND EIGHT HUNDRED FIFTY	ONE THOUSAND SEVEN HUNDRE FIFTY
72.0	Main Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	Bhutan	INDIA	650,000	3450,000	550,000	650,000	SIX HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED FIFTY	FIVE HUNDRE FIFTY
73.0	Main Bearing Oil Seal	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	Bhutan	INDIA	300,000	950,000	150,000	850,000	THREE HUNDRED	NINE HUNDRED FIFTY	ONE HUNDRE FIFTY

74.0	Mobile Filter	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	200,000	850,000	180,000	150,000	TWO HUNDRED	EIGHT HUNDRED FIFTY	ONE HUNDRE EIGHTY
75.0	Nuts and Bolts(4 Wheel)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	200,000	3000,000	50,000	10,000	TWO HUNDRED	THREE THOUSAND	FIFTY
76.0	Oil Supply Pump	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	500,000	6850,000	0,000	250,000	FIVE HUNDRED	SIX THOUSAND EIGHT HUNDRED FIFTY	ZERO
77.0	Power Steering Belt	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	1850,000	0,000	350,000	THREE HUNDRED	ONE THOUSAND EIGHT HUNDRED FIFTY	ZERO
78.0	Power Steering Oil	ltrs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	450,000	750,000	0,000	550,000	FOUR HUNDRED FIFTY	SEVEN HUNDRED FIFTY	ZERO
79.0	Pressure Plate	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2300,000	5000,000	2150,000	1850,000	TWO THOUSAND THREE HUNDRED	FIVE THOUSAND	TWO THOUSAND ONE HUNDRE FIFTY
80.0	Piston	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2500,000	3450,000	5500,000	2450,000	TWO THOUSAND FIVE HUNDRED	THREE THOUSAND FOUR HUNDRED FIFTY	FIVE THOUSAND FIVE HUNDRE
81.0	Piston Ring	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	550,000	3000,000	1250,000	1980,000	FIVE HUNDRED FIFTY	THREE THOUSAND	ONE THOUSAND TWO HUNDRE FIFTY
82.0	Shaft yoke & Teeth	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2650,000	3950,000	750,000	2150,000	TWO THOUSAND SIX HUNDRED FIFTY	THREE THOUSAND NINE HUNDRED FIFTY	SEVEN THOUSAND FIFTY

83.0	Radiator Cap	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	200.000	950.000	250.000	150.000	TWO HUNDRED	NINE HUNDRED FIFTY	TWO HUNDRE FIFTY
84.0	Rear Axle Corn	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	4950.000	350.000	350.000	THREE HUNDRED	FOUR THOUSAND NINE HUNDRED FIFTY	THREE HUNDRE FIFTY
85.0	Rear Differential Assy	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2000.000	27500.000	4500.000	9500.000	TWO THOUSAND	TWENTY SEVEN THOUSAND FIVE HUNDRED	FOUR THOUSAND FIVE HUNDRE
86.0	Release Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	875.000	2000.000	650.000	980.000	EIGHT HUNDRED SEVENTY FIVE	TWO THOUSAND	SIX HUNDRE FIFTY
87.0	Spark Plug	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	1450.000	400.000	180.000	TWO HUNDRED FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	FOUR HUNDRE
88.0	Self Armaure	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1850.000	4500.000	1350.000	1450.000	ONE THOUSAND EIGHT HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRED	ONE THOUSAND THREE HUNDRE FIFTY
89.0	Self Carbon	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	450.000	995.000	350.000	550.000	FOUR HUNDRED FIFTY	NINE HUNDRED NINETY FIVE	THREE HUNDRE FIFTY
90.0	Self Carnon Rocker	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	1200.000	200.000	120.000	SIX HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	TWO HUNDRE
91.0	Self Plunge	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	800.000	1450.000	150.000	450.000	EIGHT HUNDRED	ONE THOUSAND FOUR HUNDRED FIFTY	ONE HUNDRE FIFTY

92.0	Shock Absorber Bush	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	750.000	150.000	60.000	FIFTY	SEVEN HUNDRED FIFTY	ONE HUNDRE FIFTY
93.0	Shock Absorber Front	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3000.000	4000.000	4400.000	3250.000	THREE THOUSAND	FOUR THOUSAND	FOUR THOUSAND FOUR HUNDRE
94.0	Shock Absorber Rear	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	4500.000	950.000	980.000	SEVEN HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRED	NINE HUNDRE FIFTY
95.0	Shakle Pin Assy	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	2300.000	350.000	350.000	THREE HUNDRED	TWO THOUSAND THREE HUNDRED	THREE HUNDRE FIFTY
96.0	Spring Bush	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	700.000	60.000	60.000	FIFTY	SEVEN HUNDRED	FIFTY
97.0	Spring Bush Metal	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	200.000	900.000	190.000	250.000	TWO HUNDRED	NINE HUNDRED	ONE HUNDRE NINETY
98.0	Spring Main Rear	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2300.000	3500.000	1350.000	1250.000	TWO THOUSAND THREE HUNDRED	THREE THOUSAND FIVE HUNDRED	ONE THOUSA THREE HUNDRE FIFTY
99.0	Spring Main -2nd	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2000.000	3300.000	1100.000	1250.000	TWO THOUSAND	THREE THOUSAND THREE HUNDRED	ONE THOUSA ONE HUNDRE
100.0	Spring Main-3rd	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1750.000	3000.000	650.000	1100.000	ONE THOUSAND SEVEN HUNDRED FIFTY	THREE THOUSAND	SIX HUNDRE FIFTY










101.0	Spring Main-4th	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1550.000	2500.000	350.000	950.000	ONE THOUSAND FIVE HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED	THREE HUNDRE FIFTY
102.0	Spring Main-5th	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1300.000	2500.000	350.000	850.000	ONE THOUSAND THREE HUNDRED	TWO THOUSAND FIVE HUNDRED	THREE HUNDRE FIFTY
103.0	Stabilizer Bar Bush -Front	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	1450.000	50.000	280.000	FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	FIFTY
104.0	Stabilizer Bar Bush-Rear	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	1450.000	100.000	5.000	FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	ONE HUNDRE
105.0	Steering Damper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	875.000	3850.000	950.000	1250.000	EIGHT HUNDRED SEVENTY FIVE	THREE THOUSAND EIGHT HUNDRED FIFTY	NINE HUNDRE FIFTY
106.0	Side Light	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	3950.000	20.000	5.000	THREE HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	TWENTY
107.0	Side Light Bulb	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	500.000	25.000	20.000	FIFTY	FIVE HUNDRED	TWENTY FIVE
108.0	Side Light Clamp	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	3500.000	20.000	20.000	FIFTY	THREE THOUSAND FIVE HUNDRED	TWENTY
109.0	Spring Clamp	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	120.000	1850.000	50.000	35.000	ONE HUNDRED TWENTY	ONE THOUSAND EIGHT HUNDRED FIFTY	FIFTY

110.0	Tail Inner Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	3000,000	450,000	1450,000	SIX HUNDRED FIFTY	THREE THOUSAND	FOUR HUNDRE FIFTY
111.0	Tail Outer Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	600,000	2850,000	450,000	1250,000	SIX HUNDRED	TWO THOUSAND EIGHT HUNDRED FIFTY	FOUR HUNDRE FIFTY
112.0	Tail Oil Seal	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	250,000	950,000	150,000	250,000	TWO HUNDRED FIFTY	NINE HUNDRED FIFTY	ONE HUNDRE FIFTY
113.0	Tie Rod End-Big	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	3450,000	750,000	680,000	SIX HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED FIFTY	SEVEN HUNDRE FIFTY
114.0	Tie Rod End-Small	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	3000,000	250,000	680,000	SIX HUNDRED FIFTY	THREE THOUSAND	TWO HUNDRE FIFTY
115.0	Timing Belt	Pcs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	800,000	1950,000	350,000	850,000	EIGHT HUNDRED	ONE THOUSAND NINE HUNDRED FIFTY	THREE HUNDRE FIFTY
116.0	U-Bolt	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	150,000	1200,000	200,000	250,000	ONE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	TWO HUNDRE
117.0	Water pump	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1650,000	4950,000	1650,000	2450,000	ONE THOUSAND SIX HUNDRED FIFTY	FOUR THOUSAND NINE HUNDRED FIFTY	ONE THOUSA SIX HUNDRE FIFTY
118.0	Wheel Alignment	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	350,000	1500,000	250,000	400,000	THREE HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	TWO HUNDRE FIFTY

119.0	Wheel Cylinder Assy	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	5950,000	750,000	680,000	SIX HUNDRED FIFTY	FIVE THOUSAND NINE HUNDRED FIFTY	SEVEN HUNDRE FIFTY
120.0	Wheel Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1350,000	2000,000	950,000	1450,000	ONE THOUSAND THREE HUNDRED FIFTY	TWO THOUSAND	NINE HUNDRE FIFTY
121.0	Wiper Blade	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	1850,000	500,000	500,000	SEVEN HUNDRED FIFTY	ONE THOUSAND EIGHT HUNDRED FIFTY	FIVE HUNDRE
122.0	Air cleaner filter changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	50,000	500,000	50,000	50,000	FIFTY	FIVE HUNDRED	FIFTY
123.0	Axle oil seal changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	500,000	350,000	200,000	THREE HUNDRED	FIVE HUNDRED	THREE HUNDRE FIFTY
124.0	Ball joint changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	950,000	0,000	5,000	THREE HUNDRED	NINE HUNDRED FIFTY	ZERO
125.0	Battery charging (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	100,000	500,000	100,000	50,000	ONE HUNDRED	FIVE HUNDRED	ONE HUNDRE
126.0	Brake adjusting (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	250,000	1500,000	50,000	200,000	TWO HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	FIFTY
127.0	Brake cable changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	275,000	1200,000	350,000	150,000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND TWO HUNDRED	THREE HUNDRE FIFTY

128.0	Brake Pad changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	1200.000	300.000	200.000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED	THREE HUNDRE
129.0	Brake servicing 4 wheel (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	800.000	2450.000	700.000	200.000	EIGHT HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	SEVEN HUNDRE
130.0	Brake Shoe Changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	1250.000	700.000	300.000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	SEVEN HUNDRE
131.0	Chain sprocket changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1250.000	0.000	550.000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	ZERO
132.0	Clutch cable changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	950.000	250.000	150.000	TWO HUNDRED FIFTY	NINE HUNDRED FIFTY	TWO HUNDRE FIFTY
133.0	Clutch Kit Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	200.000	950.000	50.000	250.000	TWO HUNDRED	NINE HUNDRED FIFTY	FIFTY
134.0	Clutch plate/pressure plate changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3000.000	4500.000	950.000	950.000	THREE THOUSAND	FOUR THOUSAND FIVE HUNDRED	NINE HUNDRE FIFTY
135.0	Clutch release bearing changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	550.000	1200.000	950.000	550.000	FIVE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	NINE HUNDRE FIFTY
136.0	Complete electrical line checking (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	350.000	3500.000	1500.000	150.000	THREE HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED	ONE THOUSA FIVE HUNDRE

137.0	Cross bearing Changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	1200,000	350,000	250,000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED	THREE HUNDRE FIFTY
138.0	Crown overhauling (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	3850,000	1600,000	850,000	SEVEN HUNDRED FIFTY	THREE THOUSAND EIGHT HUNDRED FIFTY	ONE THOUSAND SIX HUNDRE
139.0	CV joint Boot changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	350,000	1200,000	0,000	5,000	THREE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	ZERO
140.0	CV Joint changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	400,000	1200,000	0,000	5,000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED	ZERO
141.0	CV joint oil seal changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	1200,000	0,000	120,000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED	ZERO
142.0	Diesel filter Changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	250,000	1200,000	0,000	150,000	TWO HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	ZERO
143.0	Driver shaft oil seal changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	365,000	1200,000	0,000	150,000	THREE HUNDRED SIXTY FIVE	ONE THOUSAND TWO HUNDRED	ZERO
144.0	Engine Oil Changing with oil filter (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	400,000	1200,000	150,000	150,000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED	ONE HUNDRE FIFTY
145.0	Engine over hauling (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	3000,000	5450,000	7500,000	2400,000	THREE THOUSAND	FIVE THOUSAND FOUR HUNDRED FIFTY	SEVEN THOUSAND FIVE HUNDRE

146.0	Fan ball changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	India	200,000	1200,000	150,000	150,000	150,000	TWO HUNDRED	TWO THOUSAND TWO HUNDRED	ONE THOUSAND FIFTY	
147.0	Front bumper opening & fitting (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	India	500,000	2450,000	350,000	250,000	350,000	FIVE HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	THREE HUNDRE FIFTY	
148.0	Gear Box mounting & dismantling (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	India	275,000	5500,000	350,000	850,000	350,000	TWO HUNDRED SEVENTY FIVE	FIVE THOUSAND FIVE HUNDRED	THREE HUNDRE FIFTY	
149.0	Gear oil changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	India	200,000	1250,000	150,000	200,000	150,000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	ONE HUNDRE FIFTY	
150.0	Hub greasing (Service Charge)	4 Side	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	India	450,000	2500,000	400,000	150,000	400,000	FOUR HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED	FOUR HUNDRE	
151.0	King pin greasing (Service Charge)	2 Side	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	India	0,000	1500,000	0,000	20,000	0,000	ZERO	ONE THOUSAND FIVE HUNDRED	ZERO	
152.0	Knuckle arm fitting (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	India	0,000	1450,000	0,000	20,000	0,000	ZERO	ONE THOUSAND FOUR HUNDRED FIFTY	ZERO	
153.0	Master Cylinder Changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	India	175,000	1950,000	450,000	300,000	450,000	ONE HUNDRED SEVENTY FIVE	ONE THOUSAND NINE HUNDRED FIFTY	FOUR HUNDRE FIFTY	
154.0	Number Plate new making (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	India	India	India	650,000	2450,000	350,000	400,000	350,000	SIX HUNDRED FIFTY	TWO THOUSAND FOUR HUNDRED FIFTY	THREE HUNDRE FIFTY	

155.0	Oil Seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1200.000	150.000	200.000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED	ONE HUNDRE FIFTY
156.0	Power steering belt changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	200.000	1200.000	0.000	150.000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED	ZERO
157.0	Radiator Servicing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1500.000	3950.000	350.000	1100.000	ONE THOUSAND FIVE HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	THREE HUNDRE FIFTY
158.0	Removing & Fitting of spring assy (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	2450.000	350.000	350.000	FOUR HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	THREE HUNDRE FIFTY
159.0	Self starter overhauling (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1500.000	3450.000	750.000	1100.000	ONE THOUSAND FIVE HUNDRED	THREE THOUSAND FOUR HUNDRED FIFTY	SEVEN HUNDRE FIFTY
160.0	Shock absorber changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1250.000	350.000	150.000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	THREE HUNDRE FIFTY
161.0	Spring Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	350.000	1250.000	350.000	200.000	THREE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED FIFTY	THREE HUNDRE FIFTY
162.0	Spring Greasing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	275.000	1950.000	50.000	20.000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND NINE HUNDRED FIFTY	FIFTY
163.0	Spring pad changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	120.000	1500.000	150.000	200.000	ONE HUNDRED TWENTY	ONE THOUSAND FIVE HUNDRED	ONE HUNDRE FIFTY

164.0	Stabilizer bush changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	1200.000	50.000	20.000	FIFTY	ONE THOUSAND TWO HUNDRED	FIFTY
165.0	Stabilizer link assy changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	1500.000	50.000	20.000	TWO HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	FIFTY
166.0	Steering Rack end assy (Link)changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1500.000	550.000	300.000	THREE HUNDRED	ONE THOUSAND FIVE HUNDRED	FIVE HUNDRE FIFTY
167.0	suspension arm changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1850.000	350.000	350.000	THREE HUNDRED	ONE THOUSAND EIGHT HUNDRED FIFTY	THREE HUNDRE FIFTY
168.0	Tail pinion oil seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	325.000	1200.000	250.000	200.000	THREE HUNDRED TWENTY FIVE	ONE THOUSAND TWO HUNDRED	TWO HUNDRE FIFTY
169.0	Tappet adjustement (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	500.000	2350.000	250.000	200.000	FIVE HUNDRED	TWO THOUSAND THREE HUNDRED FIFTY	TWO HUNDRE FIFTY
170.0	Tie rod end changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	275.000	1450.000	350.000	300.000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND FOUR HUNDRED FIFTY	THREE HUNDRE FIFTY
171.0	Timing belt changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	500.000	1950.000	350.000	750.000	FIVE HUNDRED	ONE THOUSAND NINE HUNDRED FIFTY	THREE HUNDRE FIFTY
172.0	Tyre Changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1450.000	150.000	200.000	THREE HUNDRED	ONE THOUSAND FOUR HUNDRED FIFTY	ONE HUNDRE FIFTY

173.0	Vane pump changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1500.000	450.000	200.000	THREE HUNDRED	ONE THOUSAND FIVE HUNDRED	FOUR HUNDRE FIFTY
174.0	Welding (Service Charge)	M	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	2450.000	100.000	100.000	ZERO	TWO THOUSAND FOUR HUNDRED FIFTY	ONE HUNDRE
175.0	Wheel Alignment (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	350.000	1500.000	350.000	400.000	THREE HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	THREE HUNDRE FIFTY
176.0	Whole body greasing (Service Charge)	Whole body	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	5000.000	200.000	200.000	FOUR HUNDRED	FIVE THOUSAND	TWO HUNDRE
177.0	Wind sheldid glass fitting (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1500.000	5500.000	400.000	550.000	ONE THOUSAND FIVE HUNDRED	FIVE THOUSAND FIVE HUNDRED	FOUR HUNDRE
178.0	Wiper alignment (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	100.000	1200.000	50.000	50.000	ONE HUNDRED	ONE THOUSAND TWO HUNDRED	FIFTY
179.0	Wiper blade changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	300.000	50.000	50.000	FIFTY	THREE HUNDRED	FIFTY
							Grand Total											

System Generated Report based on the tender submitted by the Bidders / Consultants

Home | About e-GP | Contact Us | Terms and Conditions | e-Learning



Version: 3.3.1