



དཔལ་ལྷན་འབྲུག་གཞུང་། དངུལ་རྩིས་ལྷན་ཁག།
 Royal Government of Bhutan, Ministry of Finance



མཐོ་གྲུབ་འཛིན་རྒྱུང་དང་གོང་འཕེལ་ལྗེ་ཚོན། རྒྱལ་ཡོངས་གཞུང་ཆས་ལས་ཁུངས།
 Procurement Management and Development Division

Home Dashboard APP Tender CMS Workflow Committees My Account Help
 Wednesday, 25 September, 2024, 13:06:50 BST

Last Login : Wednesday, 25 September, 2024, 10:21:09 BST

Welcome, Ngawang Chopel [Roles] | Logout

Tender >> My Tender >> My Tenders/Proposals (Live) >> Tender/Proposal Dashboard >> Opening Process >> View Comparative Report

Print Save As Excel Go Back To Dashboard

View Comparative Report

Tender Detail		Invitation Reference No. : JKD/Pro-01/2024-2025/261-13
Tender ID : 18629	Closing Date and Time : 14-Sep-2024 16:10	Opening Date and Time : 14-Sep-2024 16:10
Procuring Agency : Dzongkhag Administration Bumthang	Brief : <u>Supply of vehicle spare parts and maintenance for the FY 2024-2025</u>	Procurement Category : Goods
Tender Status : Being evaluated	View Notice	

Bid Submission Closing Date is thirty (30) minutes prior to Bid Opening Date. For Tender Id: 18629 the Closing Date is 14-Sep-2024 16:10 and Bid Opening Date is 14-Sep-2024 16:40

Package No	Package Description
JKD/Pro-01/2024-2025/261-13	Supply of vehicle spare parts and maintenance

Schedule of Items and Priced Quotation **SCORPIO**

The Bhutan Standards Bureau (BSB) certification requirements followed by words "or equivalent or higher" with which the goods, equipment, materials or workmanship shall comply in their proc

Schedule of Items and Priced Quotation (Form e-SG-1)

Item No.	Name and Description of Item	Unit	Quantity	Point of Delivery	Delivery Period [In Days]	Technical Specification and Standards required	Warranty Period from the date of Acceptance [in days]	Make/Model and Country of Origin				Unit Price in Figure [In Nu.]				Unit Price in Word			
								Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works	Kuenzom Automobile Workshop	Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works	Kuenzom Automobile Workshop	Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works	Karma I Auto Er Works
1.0	Arm Bush Lower	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	550.000	2450.000	1200.000	480.000	FIVE HUNDRED FIFTY	TWO THOUSAND FOUR HUNDRED FIFTY	ONE THOUS. TWO HUNDR	

2.0	Arm Bush Upper	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	550,000	2450,000	1450,000	580,000	FIVE HUNDRED FIFTY	TWO THOUSAND FOUR HUNDRED FIFTY	ONE THOUS, FOUR HUNDR FIFTY
3.0	Arm Lower	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	6500,000	19500,000	1200,000	2950,000	SIX THOUSAND FIVE HUNDRED	NINETEEN THOUSAND FIVE HUNDRED	ONE THOUS, TWO HUNDR
4.0	Arm Upper	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	5500,000	19500,000	1450,000	3200,000	FIVE THOUSAND FIVE HUNDRED	NINETEEN THOUSAND FIVE HUNDRED	ONE THOUS, FOUR HUNDR FIFTY
5.0	AC Belt	Pcs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	550,000	4950,000	1350,000	250,000	FIVE HUNDRED FIFTY	FOUR THOUSAND NINE HUNDRED FIFTY	ONE THOUS, THREE HUNDR FIFTY
6.0	Accelerator Cable	Pcs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	3950,000	550,000	680,000	THREE HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	FIVE HUNDR FIFTY
7.0	Air Filter	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	950,000	3450,000	1550,000	580,000	NINE HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED FIFTY	ONE THOUS, FIVE HUNDR FIFTY
8.0	Anabond	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	185,000	450,000	70,000	90,000	ONE HUNDRED EIGHTY FIVE	FOUR HUNDRED FIFTY	SEVEN
9.0	Axle	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	4000,000	19500,000	4500,000	6200,000	FOUR THOUSAND	NINETEEN THOUSAND FIVE HUNDRED	FOUR THOUS, FIVE HUNDR
10.0	Axle Oil Seal Outer	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	2350,000	750,000	150,000	THREE HUNDRED	TWO THOUSAND THREE HUNDRED FIFTY	SEVEN HUNDR FIFTY

11.0	Axle Tube Oil Seal	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	2350.000	650.000	200.000	THREE HUNDRED	TWO THOUSAND THREE HUNDRED FIFTY	SIX THOUSAND HUNDR FIFTY
12.0	Back Light	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1300.000	11000.000	2500.000	650.000	ONE THOUSAND THREE HUNDRED	ELEVEN THOUSAND	TWO THOUS, FIVE HUNDR
13.0	Back Light Bulb	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	75.000	400.000	50.000	20.000	SEVENTY FIVE	FOUR HUNDRED	FIFTY
14.0	Battery	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	9500.000	14950.000	8750.000	8125.000	NINE THOUSAND FIVE HUNDRED	FOURTEEN THOUSAND NINE HUNDRED FIFTY	EIGHT THOUS, SEVEN HUNDR FIFTY
15.0	Ball Joint Lower	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1740.000	4450.000	2200.000	1250.000	ONE THOUSAND SEVEN HUNDRED FORTY	FOUR THOUSAND FOUR HUNDRED FIFTY	TWO THOUS, TWO HUNDR
16.0	Ball Joint Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1650.000	4250.000	2200.000	1350.000	ONE THOUSAND SIX HUNDRED FIFTY	FOUR THOUSAND TWO HUNDRED FIFTY	TWO THOUS, TWO HUNDR
17.0	Brake Booster	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	5500.000	18500.000	4500.000	12500.000	FIVE THOUSAND FIVE HUNDRED	EIGHTEEN THOUSAND FIVE HUNDRED	FOUR THOUS, FIVE HUNDR
18.0	Brake Bucket Kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	4450.000	50.000	550.000	FIFTY	FOUR THOUSAND FOUR HUNDRED FIFTY	FIFTY
19.0	Brake Hub Front	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3000.000	12450.000	0.000	0.000	THREE THOUSAND	TWELVE THOUSAND FOUR HUNDRED FIFTY	ZERO

20.0	Brake Hub Rear	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	3000,000	12450,000	4500,000	0,000	THREE THOUSAND	THREE THOUSAND	TWELVE THOUSAND FOUR HUNDRED FIFTY	FOUR THOUS, FIVE HUNDR
21.0	Brake Oil	Lts	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	1350,000	180,000	250,000	THREE HUNDRED	ONE THOUSAND THREE HUNDRED FIFTY	ONE THOUSAND THREE HUNDRED FIFTY	ONE HUNDR EIGHTY
22.0	Brake Disc	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2300,000	13450,000	2100,000	2950,000	TWO THOUSAND THREE HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	THIRTEEN THOUSAND FOUR HUNDRED FIFTY	TWO THOUS, ONE HUNDR
23.0	Brake Pad	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1950,000	9500,000	2950,000	5250,000	ONE THOUSAND NINE HUNDRED FIFTY	ONE THOUSAND NINE HUNDRED FIFTY	NINE THOUSAND FIVE HUNDRED FIFTY	TWO THOUS, NINE HUNDR FIFTY
24.0	Brake Shoe	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2100,000	11000,000	3100,000	6200,000	TWO THOUSAND ONE HUNDRED	TWO THOUSAND ONE HUNDRED	ELEVEN THOUSAND	THREE THOUS, ONE HUNDR
25.0	Cam Shaft Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	7500,000	2100,000	350,000	SEVEN HUNDRED FIFTY	SEVEN HUNDRED FIFTY	SEVEN THOUSAND FIVE HUNDRED	TWO THOUS, ONE HUNDR
26.0	Center Bolt	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	150,000	750,000	150,000	50,000	ONE HUNDRED FIFTY	ONE HUNDRED FIFTY	SEVEN HUNDRED FIFTY	ONE HUNDR FIFTY
27.0	Connecting Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1200,000	7500,000	2450,000	650,000	ONE THOUSAND TWO HUNDRED	ONE THOUSAND TWO HUNDRED	SEVEN THOUSAND FIVE HUNDRED	TWO THOUS, FOUR HUNDR FIFTY
28.0	Coolant	Lts	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	250,000	995,000	380,000	225,000	TWO HUNDRED FIFTY	TWO HUNDRED FIFTY	NINE HUNDRED NINETY FIVE	THREE HUNDR EIGHTY

29.0	Cross Bearing	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1350,000	3450,000	850,000	1450,000	ONE THOUSAND THREE HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED FIFTY	EIGHT HUNDR FIFTY
30.0	Crown & Tail Assy	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	4000,000	42500,000	0,000	11800,000	FOUR THOUSAND	FORTY TWO THOUSAND FIVE HUNDRED	ZERO
31.0	CV Joint Assembly	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	7500,000	22350,000	14500,000	12500,000	SEVEN THOUSAND FIVE HUNDRED	TWENTY TWO THOUSAND THREE HUNDRED FIFTY	FOURTI THOUS, FIVE HUNDR
32.0	Check nut lock	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	100,000	350,000	350,000	150,000	ONE HUNDRED	THREE HUNDRED FIFTY	THREE HUNDR FIFTY
33.0	Clutch Cylinder Lower	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	10500,000	1550,000	2250,000	SIX HUNDRED FIFTY	TEN THOUSAND FIVE HUNDRED	ONE THOUS, FIVE HUNDR FIFTY
34.0	Clutch Cylinder Upper	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	10450,000	3500,000	5890,000	SIX HUNDRED FIFTY	TEN THOUSAND FOUR HUNDRED FIFTY	THREE THOUS, FIVE HUNDR
35.0	Clutch Plate	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	7500,000	9950,000	2850,000	10500,000	SEVEN THOUSAND FIVE HUNDRED	NINE THOUSAND NINE HUNDRED FIFTY	TWO THOUS, EIGHT HUNDR FIFTY
36.0	Connection Rod	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1450,000	9500,000	3500,000	650,000	ONE THOUSAND FOUR HUNDRED FIFTY	NINE THOUSAND FIVE HUNDRED	THREE THOUS, FIVE HUNDR
37.0	Crank Shaft	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	8500,000	29500,000	14500,000	0,000	EIGHT THOUSAND FIVE HUNDRED	TWENTY NINE THOUSAND FIVE HUNDRED	FOURTI THOUS, FIVE HUNDR

38.0	Dhoti	Pcs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	50,000	150,000	10,000	10,000	10,000	FIFTY	ONE HUNDRED FIFTY	TEN	
39.0	Dust Guard	Pcs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	450,000	3500,000	250,000	650,000	250,000	650,000	FOUR HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED	TWO HUNDR FIFTY
40.0	Disel Filter	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	550,000	1350,000	110,000	550,000	110,000	550,000	FIVE HUNDRED FIFTY	ONE THOUSAND THREE HUNDRED FIFTY	ONE HUNDR TEN
41.0	Engine Mounting	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	1650,000	2100,000	850,000	2100,000	850,000	SIX HUNDRED FIFTY	ONE THOUSAND SIX HUNDRED FIFTY	TWO THOUS, ONE HUNDR
42.0	Engine Oil Filter	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	550,000	1200,000	450,000	850,000	450,000	850,000	FIVE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	FOUR HUNDR FIFTY
43.0	Fan Belt	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	2850,000	950,000	2200,000	950,000	2200,000	SIX HUNDRED FIFTY	TWO THOUSAND EIGHT HUNDRED FIFTY	NINE HUNDR FIFTY
44.0	Feed Pump	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	700,000	34500,000	1250,000	1250,000	1250,000	1250,000	SEVEN HUNDRED	THIRTY FOUR THOUSAND FIVE HUNDRED	ONE THOUS, TWO HUNDR FIFTY
45.0	Fuel Filter	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	550,000	1250,000	110,000	550,000	110,000	550,000	FIVE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED FIFTY	ONE HUNDR TEN
46.0	Fuel Supply Pump	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1200,000	35000,000	0,000	1250,000	0,000	1250,000	ONE THOUSAND TWO HUNDRED	THIRTY FIVE THOUSAND	ZERO

47.0	Fog Light	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	8950,000	1750,000	2200,000	SEVEN HUNDRED FIFTY	EIGHT THOUSAND NINE HUNDRED FIFTY	ONE THOUS, SEVEN HUNDR FIFTY
48.0	Fuse	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	25,000	450,000	15,000	10,000	TWENTY FIVE	FOUR HUNDRED FIFTY	FIFTEEI
49.0	Bear Box	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	600,000	38500,000	0,000	0,000	SIX HUNDRED	THIRTY EIGHT THOUSAND FIVE HUNDRED	ZERO
50.0	Grease	Kg	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	450,000	700,000	380,000	450,000	FOUR HUNDRED FIFTY	SEVEN HUNDRED	THREE HUNDR EIGHTY
51.0	Glow Plug	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	2500,000	4500,000	2250,000	SIX HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED	FOUR THOUS, FIVE HUNDR
52.0	Hand Brake Cable	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1475,000	8950,000	1850,000	1150,000	ONE THOUSAND FOUR HUNDRED SEVENTY FIVE	EIGHT THOUSAND NINE HUNDRED FIFTY	ONE THOUS, EIGHT HUNDR FIFTY
53.0	Head Gasket	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	3950,000	1950,000	3850,000	SIX HUNDRED FIFTY	THREE THOUSAND NINE HUNDRED FIFTY	ONE THOUS, NINE HUNDR FIFTY
54.0	Head light Set	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2500,000	11000,000	4850,000	4950,000	TWO THOUSAND FIVE HUNDRED	ELEVEN THOUSAND	FOUR THOUS, EIGHT HUNDR FIFTY
55.0	Head Light Bulb	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	375,000	450,000	300,000	150,000	THREE HUNDRED SEVENTY FIVE	FOUR HUNDRED FIFTY	THREE HUNDR

56.0	Hub Oil Seal	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	1895.000	650.000	250.000	FOUR HUNDRED	ONE THOUSAND EIGHT HUNDRED NINETY FIVE	SIX HUNDRED FIFTY
57.0	Hub Splender	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	4000.000	9450.000	3500.000	180.000	FOUR THOUSAND	NINE THOUSAND FOUR HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED
58.0	Horn	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	850.000	6500.000	1750.000	750.000	EIGHT HUNDRED FIFTY	SIX THOUSAND FIVE HUNDRED	ONE THOUSAND SEVEN HUNDRED FIFTY
59.0	Hub Bearing F Inner	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1650.000	6500.000	2450.000	1850.000	ONE THOUSAND SIX HUNDRED FIFTY	SIX THOUSAND FIVE HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY
60.0	Hub Bearing F Out	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1650.000	6500.000	2350.000	1750.000	ONE THOUSAND SIX HUNDRED FIFTY	SIX THOUSAND FIVE HUNDRED	TWO THOUSAND THREE HUNDRED FIFTY
61.0	Hub Check Nut	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	100.000	2500.000	450.000	150.000	ONE HUNDRED	TWO THOUSAND FIVE HUNDRED	FOUR HUNDRED FIFTY
62.0	Intake valve	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	975.000	3450.000	0.000	850.000	NINE HUNDRED SEVENTY FIVE	THREE THOUSAND FOUR HUNDRED FIFTY	ZERO
63.0	Key Lock Set	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1650.000	9500.000	3550.000	9800.000	ONE THOUSAND SIX HUNDRED FIFTY	NINE THOUSAND FIVE HUNDRED	THREE THOUSAND FIVE HUNDRED FIFTY
64.0	Kimpin Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	4950.000	0.000	20.000	ZERO	FOUR THOUSAND NINE HUNDRED FIFTY	ZERO

65.0	King Pin Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	4850.000	0.000	20.000	ZERO	FOUR THOUSAND EIGHT HUNDRED FIFTY	ZERO
66.0	King pin kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	3450.000	0.000	20.000	ZERO	THREE THOUSAND FOUR HUNDRED FIFTY	ZERO
67.0	Link Rod	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1600.000	11000.000	550.000	1850.000	ONE THOUSAND SIX HUNDRED	ELEVEN THOUSAND	FIVE HUNDR FIFTY
68.0	Link Bush Front	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	2450.000	50.000	120.000	FIFTY	TWO THOUSAND FOUR HUNDRED FIFTY	FIFTY
69.0	Link Bush Rear	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	2500.000	50.000	60.000	FIFTY	TWO THOUSAND FIVE HUNDRED	FIFTY
70.0	Master Cylinder Kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	275.000	4450.000	50.000	550.000	TWO HUNDRED SEVENTY FIVE	FOUR THOUSAND FOUR HUNDRED FIFTY	FIFTY
71.0	Master Cylinder	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	9950.000	4500.000	8500.000	SEVEN HUNDRED FIFTY	NINE THOUSAND NINE HUNDRED FIFTY	FOUR THOUS. FIVE HUNDR
72.0	Main Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1600.000	7500.000	3550.000	850.000	ONE THOUSAND SIX HUNDRED	SEVEN THOUSAND FIVE HUNDRED	THREE THOUS. FIVE HUNDR FIFTY
73.0	Main Bearing Oil Seal	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	2250.000	1750.000	1320.000	SIX HUNDRED FIFTY	TWO THOUSAND TWO HUNDRED FIFTY	ONE THOUS. SEVEN HUNDR FIFTY

74.0	Mobile Filter	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	550,000	1,200,000	450,000	280,000	FIVE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	FOUR HUNDR FIFTY
75.0	Nuts and Bolts(4 Wheel)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	200,000	3,950,000	300,000	10,000	TWO HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	THREE HUNDR
76.0	Oil Supply Pump	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1,300,000	3,450,000	3,450,000	1,250,000	ONE THOUSAND THREE HUNDRED	THIRTY FOUR THOUSAND FIVE HUNDRED	THREE THOUS. FOUR HUNDR FIFTY
77.0	Power Steering Belt	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	600,000	3,000,000	350,000	350,000	SIX HUNDRED	THREE THOUSAND	THREE HUNDR FIFTY
78.0	Power Steering Oil	ltrs	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	450,000	750,000	350,000	650,000	FOUR HUNDRED FIFTY	SEVEN HUNDRED FIFTY	THREE HUNDR FIFTY
79.0	Pressure Plate	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	850,000	1,045,000	450,000	12,500,000	EIGHT THOUSAND FIVE HUNDRED	TEN THOUSAND FOUR HUNDRED FIFTY	FOUR THOUS. FIVE HUNDR
80.0	Piston	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	750,000	0,000	650,000	SEVEN THOUSAND FIVE HUNDRED	SEVEN THOUSAND FIVE HUNDRED	ZERO
81.0	Piston Ring	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	6,850,000	950,000	7,400,000	SIX HUNDRED FIFTY	SIX THOUSAND EIGHT HUNDRED FIFTY	NINE HUNDR FIFTY
82.0	Shaft yoke & Teeth	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	4,000,000	9,500,000	2,400,000	3,950,000	FOUR THOUSAND	NINE THOUSAND FIVE HUNDRED	TWO THOUS. FOUR HUNDR

83.0	Radiator Cap	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1250.000	250.000	450.000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	TWO HUNDR FIFTY
84.0	Rear Axle Corn	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	9450.000	50.000	650.000	SIX HUNDRED FIFTY	NINE THOUSAND FOUR HUNDRED FIFTY	FIFTY
85.0	Rear Differential Assy	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3750.000	44500.000	0.000	0.000	THREE THOUSAND SEVEN HUNDRED FIFTY	FORTY FOUR THOUSAND FIVE HUNDRED	ZERO
86.0	Release Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1750.000	2450.000	950.000	1850.000	ONE THOUSAND SEVEN HUNDRED FIFTY	TWO THOUSAND FOUR HUNDRED FIFTY	NINE HUNDR FIFTY
87.0	Spark Plug	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	2000.000	0.000	450.000	ZERO	TWO THOUSAND	ZERO
88.0	Self Armaure	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2000.000	9250.000	1350.000	3550.000	TWO THOUSAND	NINE THOUSAND TWO HUNDRED FIFTY	ONE THOUS, THREE HUNDR FIFTY
89.0	Self Carbon	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	550.000	1850.000	950.000	1250.000	FIVE HUNDRED FIFTY	ONE THOUSAND EIGHT HUNDRED FIFTY	NINE HUNDR FIFTY
90.0	Self Carnon Rocker	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	900.000	2000.000	550.000	550.000	NINE HUNDRED	TWO THOUSAND	FIVE HUNDR FIFTY
91.0	Self Plunge	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	850.000	2950.000	200.000	450.000	EIGHT HUNDRED FIFTY	TWO THOUSAND NINE HUNDRED FIFTY	TWO HUNDR

92.0	Shock Absorber Bush	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	50,000	750,000	50,000	120,000	FIFTY	SEVEN HUNDRED FIFTY	FIFTY
93.0	Shock Absorber Front	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1850,000	6500,000	1650,000	2450,000	ONE THOUSAND EIGHT HUNDRED FIFTY	SIX THOUSAND FIVE HUNDRED	ONE THOUS, SIX HUNDR FIFTY
94.0	Shock Absorber Rear	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1850,000	6850,000	1650,000	1980,000	ONE THOUSAND EIGHT HUNDRED FIFTY	SIX THOUSAND EIGHT HUNDRED FIFTY	ONE THOUS, SIX HUNDR FIFTY
95.0	Shackle Pin Assy	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	450,000	3450,000	550,000	350,000	FOUR HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED FIFTY	FIVE HUNDR FIFTY
96.0	Spring Bush	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	50,000	850,000	100,000	150,000	FIFTY	EIGHT HUNDRED FIFTY	ONE HUNDR
97.0	Spring Bush Metal	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	1100,000	200,000	580,000	THREE HUNDRED	ONE THOUSAND ONE HUNDRED	TWO HUNDR
98.0	Spring Main Rear	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1850,000	4450,000	1750,000	1450,000	ONE THOUSAND EIGHT HUNDRED FIFTY	FOUR THOUSAND FOUR HUNDRED FIFTY	ONE THOUS, SEVEN HUNDR FIFTY
99.0	Spring Main -2nd	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1750,000	4000,000	1550,000	1250,000	ONE THOUSAND SEVEN HUNDRED FIFTY	FOUR THOUSAND	ONE THOUS, FIVE HUNDR FIFTY
100.0	Spring Main-3rd	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1650,000	3850,000	950,000	1200,000	ONE THOUSAND SIX HUNDRED FIFTY	THREE THOUSAND EIGHT HUNDRED FIFTY	NINE HUNDR FIFTY

101.0	Spring Main-4th	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1500.000	3450.000	550.000	1050.000	ONE THOUSAND FIVE HUNDRED	THREE THOUSAND FOUR HUNDRED FIFTY	FIVE HUNDR FIFTY
102.0	Spring Main-5th	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1350.000	3300.000	550.000	1050.000	ONE THOUSAND THREE HUNDRED FIFTY	THREE THOUSAND THREE HUNDRED	FIVE HUNDR FIFTY
103.0	Stabilizer Bar Bush -Front	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	1450.000	100.000	150.000	FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	ONE HUNDR
104.0	Stabilizer Bar Bush-Rear	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	1450.000	450.000	5.000	FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	FOUR HUNDR FIFTY
105.0	Steering Damper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2000.000	5950.000	1450.000	2350.000	TWO THOUSAND	FIVE THOUSAND NINE HUNDRED FIFTY	ONE THOUS, FOUR HUNDR FIFTY
106.0	Side Light	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	6850.000	50.000	5.000	SIX HUNDRED FIFTY	SIX THOUSAND EIGHT HUNDRED FIFTY	FIFTY
107.0	Side Light Bulb	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	500.000	50.000	20.000	FIFTY	FIVE HUNDRED	FIFTY
108.0	Side Light Clamp	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	35.000	4450.000	50.000	250.000	THIRTY FIVE	FOUR THOUSAND FOUR HUNDRED FIFTY	FIFTY
109.0	Spring Clamp	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	150.000	2000.000	50.000	350.000	ONE HUNDRED FIFTY	TWO THOUSAND	FIFTY

110.0	Tail Inner Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	India	India	Bhutan	INDIA	750.000	4950.000	1450.000	2250.000	SEVEN HUNDRED FIFTY	FOUR THOUSAND NINE HUNDRED FIFTY	ONE THOUS. FOUR HUNDR FIFTY
111.0	Tail Outer Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	India	India	Bhutan	INDIA	700.000	4950.000	1750.000	2950.000	SEVEN HUNDRED	FOUR THOUSAND NINE HUNDRED FIFTY	ONE THOUS. SEVEN HUNDR FIFTY
112.0	Tail Oil Seal	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	India	India	Bhutan	INDIA	400.000	1995.000	550.000	350.000	FOUR HUNDRED	ONE THOUSAND NINE HUNDRED NINETY FIVE	FIVE HUNDR FIFTY
113.0	Tie Rod End-Big	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	India	India	Bhutan	INDIA	1350.000	7950.000	1250.000	3250.000	ONE THOUSAND THREE HUNDRED FIFTY	SEVEN THOUSAND NINE HUNDRED FIFTY	ONE THOUS. TWO HUNDR FIFTY
114.0	Tie Rod End-Small	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	India	India	Bhutan	INDIA	1350.000	7850.000	1200.000	3250.000	ONE THOUSAND THREE HUNDRED FIFTY	SEVEN THOUSAND EIGHT HUNDRED FIFTY	ONE THOUS. TWO HUNDR
115.0	Timing Belt	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	India	India	Bhutan	INDIA	1750.000	3350.000	550.000	5.000	ONE THOUSAND SEVEN HUNDRED FIFTY	THREE THOUSAND THREE HUNDRED FIFTY	FIVE HUNDR FIFTY
116.0	U-Bolt	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	India	India	Bhutan	INDIA	150.000	2450.000	180.000	350.000	ONE HUNDRED FIFTY	TWO THOUSAND FOUR HUNDRED FIFTY	ONE HUNDR EIGHTY
117.0	Water pump	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	India	India	Bhutan	INDIA	4500.000	9500.000	3100.000	6800.000	FOUR THOUSAND FIVE HUNDRED	NINE THOUSAND FIVE HUNDRED	THREE THOUS. ONE HUNDR
118.0	Wheel Alignment	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	India	India	Bhutan	INDIA	350.000	1500.000	350.000	400.000	THREE HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	THREE HUNDR FIFTY

119.0	Wheel Cylinder Assy	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1200.000	11450.000	2250.000	2450.000	ONE THOUSAND TWO HUNDRED	ELEVEN THOUSAND FOUR HUNDRED FIFTY	TWO THOUS, TWO HUNDR FIFTY
120.0	Wheel Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1450.000	4950.000	2550.000	1950.000	ONE THOUSAND FOUR HUNDRED FIFTY	FOUR THOUSAND NINE HUNDRED FIFTY	TWO THOUS, FIVE HUNDR FIFTY
121.0	Wiper Blade	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	2500.000	500.000	500.000	SEVEN HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED	FIVE HUNDR
122.0	Air cleaner filter changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	500.000	50.000	50.000	FIFTY	FIVE HUNDRED	FIFTY
123.0	Axle oil seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	500.000	550.000	200.000	THREE HUNDRED	FIVE HUNDRED	FIVE HUNDR FIFTY
124.0	Ball joint changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	950.000	950.000	250.000	ZERO	NINE HUNDRED FIFTY	NINE HUNDR FIFTY
125.0	Battery charging (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	100.000	500.000	100.000	50.000	ONE HUNDRED	FIVE HUNDRED	ONE HUNDR
126.0	Brake adjusting (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	1500.000	100.000	200.000	TWO HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	ONE HUNDR
127.0	Brake cable changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	275.000	1200.000	650.000	150.000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND TWO HUNDRED	SIX HUNDR FIFTY

128.0	Brake Pad changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	1200.000	400.000	200.000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED	FOUR HUNDR
129.0	Brake servicing 4 wheel (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	800.000	2450.000	800.000	200.000	EIGHT HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	EIGHT HUNDR
130.0	Brake Shoe Changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	1250.000	700.000	350.000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	SEVEN HUNDR
131.0	Chain spocket changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	1250.000	0.000	950.000	SIX HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED FIFTY	ZERO
132.0	Clutch cable changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	950.000	100.000	250.000	TWO HUNDRED FIFTY	NINE HUNDRED FIFTY	ONE HUNDR
133.0	Clutch Kit Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	200.000	950.000	100.000	350.000	TWO HUNDRED	NINE HUNDRED FIFTY	ONE HUNDR
134.0	Clutch plate/pressure plate changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	5000.000	4500.000	3500.000	1400.000	FIVE THOUSAND	FOUR THOUSAND FIVE HUNDRED	THREE THOUS. FIVE HUNDR
135.0	Clutch release bearing changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1500.000	1200.000	3500.000	1100.000	ONE THOUSAND FIVE HUNDRED	ONE THOUSAND TWO HUNDRED	THREE THOUS. FIVE HUNDR
136.0	Complete electrical line checking (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	350.000	3500.000	1200.000	200.000	THREE HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED	ONE THOUS. TWO HUNDR

137.0	Cross bearing Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1200.000	400.000	250.000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED	FOUR HUNDR
138.0	Crown overhauling (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	3850.000	4500.000	850.000	SEVEN HUNDRED FIFTY	THREE THOUSAND EIGHT HUNDRED FIFTY	FOUR THOUS, FIVE HUNDR
139.0	CV joint Boot changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	350.000	1200.000	1200.000	150.000	THREE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	ONE THOUS, TWO HUNDR
140.0	CV Joint changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	1200.000	1200.000	250.000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED	ONE THOUS, TWO HUNDR
141.0	CV joint oil seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1200.000	1200.000	350.000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED	ONE THOUS, TWO HUNDR
142.0	Diesel filter Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	1200.000	150.000	150.000	TWO HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	ONE HUNDR FIFTY
143.0	Driver shaft oil seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	365.000	1200.000	1200.000	250.000	THREE HUNDRED SIXTY FIVE	ONE THOUSAND TWO HUNDRED	ONE THOUS, TWO HUNDR
144.0	Engine Oil Changing with oil filter (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	1200.000	200.000	200.000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED	TWO HUNDR
145.0	Engine over hauling (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	6500.000	5450.000	35000.000	2400.000	SIX THOUSAND FIVE HUNDRED	FIVE THOUSAND FOUR HUNDRED FIFTY	THIRTY FIVE THOUS,

146.0	Fan belt changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	200.000	1200.000	250.000	150.000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED	TWO HUNDR FIFTY
147.0	Front bumper opening & fitting (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	500.000	2450.000	450.000	350.000	FIVE HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	FOUR HUNDR FIFTY
148.0	Gear Box mounting & dismounting (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	275.000	5500.000	1550.000	350.000	TWO HUNDRED SEVENTY FIVE	FIVE THOUSAND FIVE HUNDRED	ONE THOUS, FIVE HUNDR FIFTY
149.0	Gear oil changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	200.000	1250.000	250.000	150.000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	TWO HUNDR FIFTY
150.0	Hub greasing (Service Charge)	4 Side	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	450.000	2500.000	2600.000	350.000	FOUR HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED	TWO THOUS, SIX HUNDR
151.0	King pin greasing (Service Charge)	2 Side	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	1500.000	2850.000	20.000	ZERO	ONE THOUSAND FIVE HUNDRED	TWO THOUS, EIGHT HUNDR FIFTY
152.0	Knuckle arm fitting (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	1450.000	1200.000	20.000	ZERO	ONE THOUSAND FOUR HUNDRED FIFTY	ONE THOUS, TWO HUNDR
153.0	Master Cylinder Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	175.000	1950.000	450.000	350.000	ONE HUNDRED SEVENTY FIVE	ONE THOUSAND NINE HUNDRED FIFTY	FOUR HUNDR FIFTY
154.0	Number Plate new making (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	2450.000	350.000	400.000	SIX HUNDRED FIFTY	TWO THOUSAND FOUR HUNDRED FIFTY	THREE HUNDR FIFTY

155.0	Oil Seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1200.000	100.000	150.000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED	ONE HUNDR
156.0	Power steering belt changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	200.000	1200.000	200.000	200.000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED	TWO HUNDR
157.0	Radiator Servicing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1500.000	3950.000	450.000	1100.000	ONE THOUSAND FIVE HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	FOUR HUNDR FIFTY
158.0	Removing & Fitting of spring assy (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	2450.000	550.000	400.000	FOUR HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	FIVE HUNDR FIFTY
159.0	Self starter overhauling (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1500.000	3450.000	1200.000	1100.000	ONE THOUSAND FIVE HUNDRED	THREE THOUSAND FOUR HUNDRED FIFTY	ONE THOUS. TWO HUNDR
160.0	Shock absorber changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1250.000	250.000	150.000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	TWO HUNDR FIFTY
161.0	Spring Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	350.000	1250.000	550.000	350.000	THREE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED FIFTY	FIVE HUNDR FIFTY
162.0	Spring Greasing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	275.000	1950.000	100.000	400.000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND NINE HUNDRED FIFTY	ONE HUNDR
163.0	Spring pad changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	120.000	1500.000	200.000	250.000	ONE HUNDRED TWENTY	ONE THOUSAND FIVE HUNDRED	TWO HUNDR

164.0	Stabilizer bush changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	1200.000	250.000	350.000	FIFTY	ONE THOUSAND TWO HUNDRED	TWO HUNDR FIFTY
165.0	Stabilizer link assy changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	1500.000	150.000	150.000	TWO HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	ONE HUNDR FIFTY
166.0	Steering Rack end assy (Link)changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1500.000	1950.000	350.000	THREE HUNDRED	ONE THOUSAND FIVE HUNDRED	ONE THOUS, NINE HUNDR FIFTY
167.0	suspension arm changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	1850.000	1250.000	450.000	FOUR HUNDRED	ONE THOUSAND EIGHT HUNDRED FIFTY	ONE THOUS, TWO HUNDR FIFTY
168.0	Tail pinion oil seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	325.000	1200.000	1550.000	250.000	THREE HUNDRED TWENTY FIVE	ONE THOUSAND TWO HUNDRED	ONE THOUS, FIVE HUNDR FIFTY
169.0	Tappet adjustement (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	500.000	2350.000	150.000	150.000	FIVE HUNDRED	TWO THOUSAND THREE HUNDRED FIFTY	ONE HUNDR FIFTY
170.0	Tie rod end changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	275.000	1450.000	700.000	250.000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND FOUR HUNDRED FIFTY	SEVEN HUNDR
171.0	Timing belt changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	1950.000	1200.000	750.000	SEVEN HUNDRED FIFTY	ONE THOUSAND NINE HUNDRED FIFTY	ONE THOUS, TWO HUNDR
172.0	Tyre Changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1450.000	200.000	200.000	THREE HUNDRED	ONE THOUSAND FOUR HUNDRED FIFTY	TWO HUNDR

173.0	Vane pump changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1500.000	3500.000	250.000	THREE HUNDRED	ONE THOUSAND FIVE HUNDRED	THREE THOUS. FIVE HUNDR
174.0	Welding (Service Charge)	M	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	2450.000	100.000	100.000	ZERO	TWO THOUSAND FOUR HUNDRED FIFTY	ONE HUNDR
175.0	Wheel Alignment (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	350.000	1500.000	350.000	400.000	THREE HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	THREE HUNDR FIFTY
176.0	Whole body greasing (Service Charge)	Whole body	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	600.000	5000.000	450.000	250.000	SIX HUNDRED	FIVE THOUSAND	FOUR HUNDR FIFTY
177.0	Wind shield glass fitting (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2000.000	5500.000	2500.000	550.000	TWO THOUSAND	FIVE THOUSAND FIVE HUNDRED	TWO THOUS. FIVE HUNDR
178.0	Wiper alignment (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	100.000	1200.000	100.000	20.000	ONE HUNDRED	ONE THOUSAND TWO HUNDRED	ONE HUNDR
179.0	Wiper blade changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	300.000	100.000	20.000	FIFTY	THREE HUNDRED	ONE HUNDR
							Grand Total											

⊗ DTC awarded to M/s Kuenzom Automobile

System Generated Report based on the tender submitted by the Bidders / Consultants

Home | About e-GP | Contact Us | Terms and Conditions | e-Learning

