



དཔལ་ལྷན་འབྲུག་གཞུང་། དངུལ་རྩིས་ལྷན་ཁག།  
 Royal Government of Bhutan, Ministry of Finance  
 མཐོ་སྤྱོད་འཛིན་སྐྱོང་དང་གོང་འཕེལ་ལྷན་ཚན། རྒྱལ་ཡོངས་གཞུང་ཆས་ལས་ཁུངས།  
**Procurement Management and Development Division**



Home Dashboard APP Tender CMS Workflow Committees My Account Help

Wednesday, 25 September, 2024, 12:23:35 BST

Last Login : Wednesday, 25 September, 2024, 10:21:09 BST

Welcome, Ngawang Chopel [Roles] | Logout

Tender >> My Tender >> My Tenders/Proposals (Live) >> Tender/Proposal Dashboard >> Opening Process >> View Comparative Report

**View Comparative Report**

Print Save As Excel Go Back To Dashboard

<b>Tender Detail</b>	
Tender ID : 18629	Invitation Reference No. : JKD/Pro-01/2024-2025/261-13
Closing Date and Time : 14-Sep-2024 16:10	Opening Date and Time : 14-Sep-2024 16:10
Procuring Agency : Dzongkhag Administration Bumthang	Procurement Category : Goods
Brief : <u>Supply of vehicle spare parts and maintenance for the FY 2024-2025</u>	<a href="#">View Notice</a>
Tender Status : Being evaluated	

Bid Submission Closing Date is thirty (30) minutes prior to Bid Opening Date. For Tender Id: 18629 the Closing Date is 14-Sep-2024 16:10 and Bid Opening Date is 14-Sep-2024 16:40

Package No	Package Description
JKD/Pro-01/2024-2025/261-13	Supply of vehicle spare parts and maintenance

The Bhutan Standards Bureau (BSB) certification requirements followed by words "or equivalent or higher" with which the goods, equipment, materials or workmanship shall comply in their pr  
 Schedule of Items and Priced Quotation **DCM,BUS (EICHER)**

Schedule of Items and Priced Quotation (Form e-SG-1)

Item No.	Name and Description of Item	Unit	Quantity	Point of Delivery	Delivery Period [In Days]	Technical Specification and Standards required	Warranty Period from the date of Acceptance [in days]	Make/Model and Country of Origin				Unit Price in Figure [In Nu.]				Unit Price in Word		
								Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works	Kuenzom Automobile Workshop	Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works	Kuenzom Automobile Workshop	Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Auto E Works
1.0	Arm Bush Lower	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	5000,000	1250,000	450,000	ZERO	FIVE THOUSAND	ONE THOUS TWO HUNDRED FIFTY

2.0	Arm Bush Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	5000.000	1250.000	550.000	ZERO	FIVE THOUSAND	ONE THOUSAND TWO HUNDRED FIFTY
3.0	Arm Lower	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	27500.000	0.000	6500.000	ZERO	TWENTY SEVEN THOUSAND FIVE HUNDRED	ZERO
4.0	Arm Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	27500.000	0.000	620.000	ZERO	TWENTY SEVEN THOUSAND FIVE HUNDRED	ZERO
5.0	AC Belt	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	8450.000	0.000	550.000	ZERO	EIGHT THOUSAND FOUR HUNDRED FIFTY	ZERO
6.0	Acceleator Cable	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	7950.000	750.000	750.000	FOUR HUNDRED	SEVEN THOUSAND NINE HUNDRED FIFTY	SEVEN HUNDRED FIFTY
7.0	Air Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2875.000	6450.000	2550.000	2950.000	TWO THOUSAND EIGHT HUNDRED SEVENTY FIVE	SIX THOUSAND FOUR HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED FIFTY
8.0	Anabond	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	185.000	450.000	70.000	90.000	ONE HUNDRED EIGHTY FIVE	FOUR HUNDRED FIFTY	SEVEN
9.0	Axle	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	6500.000	39500.000	6500.000	8500.000	SIX THOUSAND FIVE HUNDRED	THIRTY NINE THOUSAND FIVE HUNDRED	SIX THOUSAND FIVE HUNDRED
10.0	Axle Oil Seal Outer	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	3850.000	750.000	950.000	FOUR HUNDRED	THREE THOUSAND EIGHT HUNDRED FIFTY	SEVEN HUNDRED FIFTY

11.0	Axle Tube Oil Seal	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	3850.000	750.000	850.000	THREE HUNDRED	THREE THOUSAND EIGHT HUNDRED FIFTY	SEVEN THOUSAND FIFTY
12.0	Back Light	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1450.000	15950.000	1550.000	2200.000	ONE THOUSAND FOUR HUNDRED FIFTY	FIFTEEN THOUSAND NINE HUNDRED FIFTY	ONE THOUS FIVE HUND FIFTY
13.0	Back Light Bulb	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	75.000	750.000	25.000	20.000	SEVENTY FIVE	SEVEN HUNDRED FIFTY	TWEN FIVE
14.0	Battery	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	9500.000	19500.000	8750.000	8125.000	NINE THOUSAND FIVE HUNDRED	NINETEEN THOUSAND FIVE HUNDRED	EIGHT THOUS SEVEN HUND FIFTY
15.0	Ball Joint Lower	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	8500.000	0.000	2250.000	ZERO	EIGHT THOUSAND FIVE HUNDRED	ZERO
16.0	Ball Joint Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	8850.000	0.000	1950.000	ZERO	EIGHT THOUSAND EIGHT HUNDRED FIFTY	ZERO
17.0	Brake Booster	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	5500.000	17500.000	7500.000	29800.000	FIVE THOUSAND FIVE HUNDRED	SEVENTEEN THOUSAND FIVE HUNDRED	SEVEN THOUS FIVE HUND FIFTY
18.0	Brake Bucket Kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	8450.000	50.000	550.000	FIFTY	EIGHT THOUSAND FOUR HUNDRED FIFTY	FIFTY
19.0	Brake Hub Front	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3000.000	17500.000	2750.000	0.000	THREE THOUSAND	SEVENTEEN THOUSAND FIVE HUNDRED	TWO THOUS SEVEN HUND FIFTY

20.0	Brake Hub Rear	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	3000,000	18500,000	3200,000	0,000	THREE THOUSAND	EIGHTEEN THOUSAND FIVE HUNDRED	THREE THOUSAND TWO HUNDRED
21.0	Brake Oil	Lts	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	1350,000	190,000	350,000	THREE HUNDRED	ONE THOUSAND THREE HUNDRED FIFTY	ONE HUNDRED NINET
22.0	Brake Disc	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	21500,000	0,000	0,000	ZERO	TWENTY ONE THOUSAND FIVE HUNDRED	ZERO
23.0	Brake Pad	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	18950,000	0,000	5,000	ZERO	EIGHTEEN THOUSAND NINE HUNDRED FIFTY	ZERO
24.0	Brake Shoe	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2750,000	19500,000	2750,000	8500,000	TWO THOUSAND SEVEN HUNDRED FIFTY	NINETEEN THOUSAND FIVE HUNDRED	TWO THOUSAND SEVEN HUNDRED FIFTY
25.0	Cam Shaft Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	800,000	16500,000	2200,000	850,000	EIGHT HUNDRED	SIXTEEN THOUSAND FIVE HUNDRED	TWO THOUSAND TWO HUNDRED
26.0	Center Bolt	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	450,000	4500,000	250,000	50,000	FOUR HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRED	TWO HUNDRED FIFTY
27.0	Connecting Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	800,000	16450,000	3500,000	750,000	EIGHT HUNDRED	SIXTEEN THOUSAND FOUR HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED
28.0	Coolant	Lts	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	250,000	1200,000	380,000	225,000	TWO HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	THREE HUNDRED EIGHT

29.0	Cross Bearing	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	23350.000	4950.000	1350.000	2950.000	TWO THOUSAND THREE HUNDRED FIFTY	FOUR THOUSAND NINE HUNDRED FIFTY	ONE THOUS THREE HUND FIFTY
30.0	Crown & Tail Assy	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	4000.000	84500.000	15500.000	18500.000	FOUR THOUSAND	EIGHTY FOUR THOUSAND FIVE HUNDRED	FIFTEE THOUS FIVE HUND
31.0	CV Joint Assembly	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0.000	14500.000	0.000	5.000	FOURTEEN THOUSAND FIVE HUNDRED	ZERO	ZERO
32.0	Check nut lock	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	150.000	750.000	450.000	250.000	SEVEN HUNDRED FIFTY	ONE HUNDRED FIFTY	FOUR HUND FIFTY
33.0	Clutch Cylinder Lower	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	450.000	16500.000	1950.000	4950.000	SIXTEEN THOUSAND FIVE HUNDRED	FOUR THOUSAND FIVE HUNDRED	ONE THOUS NINE HUND FIFTY
34.0	Clutch Cylinder Upper	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	875.000	17500.000	2750.000	9800.000	SEVENTEEN THOUSAND FIVE HUNDRED	EIGHT HUNDRED SEVENTY FIVE	TWO THOUS SEVEN HUND FIFTY
35.0	Clutch Plate	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	8500.000	18500.000	2750.000	12500.000	EIGHTEEN THOUSAND FIVE HUNDRED	EIGHT THOUSAND FIVE HUNDRED	TWO THOUS SEVEN HUND FIFTY
36.0	Connection Rod	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1200.000	19500.000	0.000	6500.000	NINETEEN THOUSAND FIVE HUNDRED	ONE THOUSAND TWO HUNDRED	ZERO
37.0	Crank Shaft	set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	11000.000	68500.000	8500.000	0.000	ELEVEN THOUSAND	SIXTY EIGHT THOUSAND FIVE HUNDRED	EIGHT THOUS FIVE HUND

38.0	Dhoti	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	150.000	10.000	10.000	10.000	FIFTY	ONE HUNDRED FIFTY	TEN
39.0	Dust Guard	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	5450.000	2500.000	10.000	10.000	FOUR HUNDRED	FIVE THOUSAND FOUR HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED FIFTY
40.0	Disel Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	3850.000	1250.000	1250.000	1250.000	SIX HUNDRED FIFTY	THREE THOUSAND EIGHT HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED FIFTY
41.0	Engine Mounting	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	2300.000	4500.000	2895.000	2895.000	SEVEN HUNDRED FIFTY	TWO THOUSAND THREE HUNDRED	FOUR THOUSAND FIVE HUNDRED
42.0	Engine Oil Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	3850.000	1700.000	650.000	650.000	SIX HUNDRED FIFTY	THREE THOUSAND EIGHT HUNDRED FIFTY	ONE THOUSAND SEVEN HUNDRED
43.0	Fan Belt	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	600.000	4950.000	1950.000	2200.000	2200.000	SIX HUNDRED	FOUR THOUSAND NINE HUNDRED FIFTY	ONE THOUSAND NINE HUNDRED FIFTY
44.0	Feed Pump	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	49500.000	2850.000	1450.000	1450.000	SEVEN HUNDRED FIFTY	FORTY NINE THOUSAND FIVE HUNDRED	TWO THOUSAND EIGHT HUNDRED FIFTY
45.0	Fuel Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	600.000	3950.000	1700.000	1550.000	1550.000	SIX HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	ONE THOUSAND SEVEN HUNDRED
46.0	Fuel Supply Pump	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	49500.000	1200.000	650.000	650.000	SIX HUNDRED FIFTY	FORTY NINE THOUSAND FIVE HUNDRED	ONE THOUSAND TWO HUNDRED

47.0	Fog Light	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	19850,000	3600,000	2200,000	SEVEN HUNDRED FIFTY	NINETEEN THOUSAND EIGHT HUNDRED FIFTY	THREE THOUS SIX HUND F
48.0	Fuse	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	25,000	850,000	15,000	10,000	TWENTY FIVE	EIGHT HUNDRED FIFTY	FIFTEE
49.0	Bear Box	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	74500,000	0,000	0,000	THREE HUNDRED	SEVENTY FOUR THOUSAND FIVE HUNDRED	ZERO
50.0	Grease	Kg	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	450,000	850,000	380,000	450,000	FOUR HUNDRED FIFTY	EIGHT HUNDRED FIFTY	THREE HUND EIGHT
51.0	Glow Plug	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	700,000	4950,000	5900,000	1850,000	SEVEN HUNDRED	FOUR THOUSAND NINE HUNDRED FIFTY	FIVE THOUS NINE HUND F
52.0	Hand Brake Cable	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	3750,000	19500,000	5500,000	1250,000	THREE THOUSAND SEVEN HUNDRED FIFTY	NINETEEN THOUSAND FIVE HUNDRED	FIVE THOUS FIVE HUND F
53.0	Head Gasket	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1300,000	9500,000	5400,000	4500,000	ONE THOUSAND THREE HUNDRED	NINE THOUSAND FIVE HUNDRED	FIVE THOUS FOUR HUND F
54.0	Head light Set	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1650,000	18500,000	12500,000	3200,000	ONE THOUSAND SIX HUNDRED FIFTY	EIGHTEEN THOUSAND FIVE HUNDRED	TWEL THOUS FIVE HUND F
55.0	Head Light Bulb	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	375,000	750,000	400,000	150,000	THREE HUNDRED SEVENTY FIVE	SEVEN HUNDRED FIFTY	FOUR HUND

56.0	Hub Oil Seal	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	450.000	2750.000	10200.000	650.000	FOUR HUNDRED FIFTY	TWO THOUSAND SEVEN HUNDRED FIFTY	TEN THOUSAND TWO HUNDRED FIFTY
57.0	Hub Splender	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3500.000	19500.000	2300.000	20.000	THREE THOUSAND FIVE HUNDRED	NINETEEN THOUSAND FIVE HUNDRED	TWO THOUSAND THREE HUNDRED
58.0	Horn	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	12000.000	4500.000	850.000	SEVEN HUNDRED FIFTY	TWELVE THOUSAND	FOUR THOUSAND FIVE HUNDRED
59.0	Hub Bearing F Inner	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1950.000	16500.000	4100.000	1850.000	ONE THOUSAND NINE HUNDRED FIFTY	SIXTEEN THOUSAND FIVE HUNDRED	FOUR THOUSAND ONE HUNDRED
60.0	Hub Bearing F Out	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1950.000	16450.000	1750.000	1950.000	ONE THOUSAND NINE HUNDRED FIFTY	SIXTEEN THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND SEVEN HUNDRED FIFTY
61.0	Hub Check Nut	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	100.000	3950.000	0.000	250.000	ONE HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	ZERO
62.0	Intake valve	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	900.000	8950.000	9500.000	850.000	NINE HUNDRED	EIGHT THOUSAND NINE HUNDRED FIFTY	NINE THOUSAND FIVE HUNDRED
63.0	Key Lock Set	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1340.000	11000.000	1250.000	8500.000	ONE THOUSAND THREE HUNDRED FORTY	ELEVEN THOUSAND	ONE THOUSAND TWO HUNDRED FIFTY
64.0	Kimpin Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2650.000	9950.000	1250.000	4500.000	TWO THOUSAND SIX HUNDRED FIFTY	NINE THOUSAND NINE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED FIFTY



65.0	King Pin Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	900.000	13500.000	450.000	4500.000	NINE HUNDRED	THIRTEEN THOUSAND FIVE HUNDRED	FOUR HUND FIFTY
66.0	King pin kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	550.000	6450.000	1250.000	1200.000	FIVE HUNDRED FIFTY	SIX THOUSAND FOUR HUNDRED FIFTY	ONE THOUS TWO HUND FIFTY
67.0	Link Rod	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	23500.000	400.000	5.000	ZERO	TWENTY THREE THOUSAND FIVE HUNDRED	FOUR HUND
68.0	Link Bush Front	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	4450.000	200.000	5.000	ZERO	FOUR THOUSAND FOUR HUNDRED FIFTY	TWO HUND
69.0	Link Bush Rear	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	4550.000	250.000	5.000	ZERO	FOUR THOUSAND FIVE HUNDRED FIFTY	TWO HUND FIFTY
70.0	Master Cylinder Kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	450.000	7950.000	4500.000	4500.000	FOUR HUNDRED FIFTY	SEVEN THOUSAND NINE HUNDRED FIFTY	FOUR THOUS FIVE HUND
71.0	Master Cylinder	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	700.000	22450.000	4500.000	12500.000	SEVEN HUNDRED	TWENTY TWO THOUSAND FOUR HUNDRED FIFTY	FOUR THOUS FIVE HUND
72.0	Main Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	975.000	7450.000	3400.000	950.000	NINE HUNDRED SEVENTY FIVE	SEVEN THOUSAND FOUR HUNDRED FIFTY	THREE THOUS FOUR HUND
73.0	Main Bearing Oil Seal	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	950.000	2350.000	750.000	1450.000	NINE HUNDRED FIFTY	TWO THOUSAND THREE HUNDRED FIFTY	SEVEN HUND FIFTY

74.0	Mobile Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	3850.000	1700.000	950.000	SIX HUNDRED FIFTY	THREE THOUSAND EIGHT HUNDRED FIFTY	ONE THOUS SEVEN HUND FIFTY
75.0	Nuts and Bolts(4 Wheel)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	8500.000	200.000	10.000	THREE HUNDRED	EIGHT THOUSAND FIVE HUNDRED	TWO HUND F
76.0	Oil Supply Pump	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	975.000	32500.000	1250.000	550.000	NINE HUNDRED SEVENTY FIVE	THIRTY TWO THOUSAND FIVE HUNDRED	ONE THOUS TWO HUND FIFTY
77.0	Power Steering Belt	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	5450.000	2700.000	1250.000	SIX HUNDRED FIFTY	FIVE THOUSAND FOUR HUNDRED FIFTY	TWO THOUS SEVEN HUND F
78.0	Power Steering Oil	ltrs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	450.000	1200.000	380.000	550.000	FOUR HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	THREE HUND F EIGHT
79.0	Pressure Plate	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	8750.000	29500.000	8500.000	14500.000	EIGHT THOUSAND SEVEN HUNDRED FIFTY	TWENTY NINE THOUSAND FIVE HUNDRED	EIGHT THOUS FIVE HUND F
80.0	Piston	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	7000.000	19500.000	0.000	6500.000	SEVEN THOUSAND	NINETEEN THOUSAND FIVE HUNDRED	ZERO
81.0	Piston Ring	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	21500.000	10500.000	6500.000	SEVEN HUNDRED FIFTY	TWENTY ONE THOUSAND FIVE HUNDRED	TEN THOUS FIVE HUND F
82.0	Shaft yoke & Teeth	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3250.000	19500.000	2850.000	4580.000	THREE THOUSAND HUNDRED FIFTY	NINETEEN THOUSAND FIVE HUNDRED	TWO THOUS EIGHT HUND FIFTY

83.0	Radiator Cap	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	400.000	1450.000	250.000	450.000	FOUR HUNDRED	ONE THOUSAND FOUR HUNDRED FIFTY	TWO HUNDRED FIFTY
84.0	Rear Axle Corn	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	800.000	29500.000	650.000	1200.000	EIGHT HUNDRED	TWENTY NINE THOUSAND FIVE HUNDRED	SIX HUNDRED FIFTY
85.0	Rear Differential Assy	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	4500.000	68600.000	0.000	0.000	FOUR THOUSAND FIVE HUNDRED	SIXTY EIGHT THOUSAND SIX HUNDRED	ZERO
86.0	Release Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	1875.000	5450.000	1750.000	2250.000	ONE THOUSAND EIGHT HUNDRED SEVENTY FIVE	FIVE THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND SEVEN HUNDRED FIFTY
87.0	Spark Plug	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	4450.000	0.000	20.000	ZERO	FOUR THOUSAND FOUR HUNDRED FIFTY	ZERO
88.0	Self Armaure	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2100.000	18450.000	2500.000	4500.000	TWO THOUSAND ONE HUNDRED	EIGHTEEN THOUSAND FOUR HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED FIFTY
89.0	Self Carbon	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	700.000	3950.000	1250.000	1450.000	SEVEN HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED FIFTY
90.0	Self Carnon Rocker	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	800.000	4500.000	400.000	1250.000	EIGHT HUNDRED	FOUR THOUSAND FIVE HUNDRED	FOUR HUNDRED FIFTY
91.0	Self Plunge	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	975.000	5500.000	3450.000	1200.000	NINE HUNDRED SEVENTY FIVE	FIVE THOUSAND FIVE HUNDRED	THREE THOUSAND FOUR HUNDRED FIFTY

*JK*

*[Handwritten signature]*

*[Handwritten signature]*

*[Handwritten signature]*

*[Handwritten signature]*

*[Handwritten signature]*

92.0	Shock Absorber Bush	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	100.000	1450.000	50.000	120.000	ONE HUNDRED	ONE THOUSAND FOUR HUNDRED FIFTY	FIFTY
93.0	Shock Absorber Front	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2600.000	22450.000	8900.000	4550.000	TWO THOUSAND SIX HUNDRED	TWENTY TWO THOUSAND FOUR HUNDRED FIFTY	EIGHT THOUSAND NINE HUNDRED
94.0	Shock Absorber Rear	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2600.000	21500.000	7500.000	3950.000	TWO THOUSAND SIX HUNDRED	TWENTY ONE THOUSAND FIVE HUNDRED	SEVEN THOUSAND FIVE HUNDRED
95.0	Shackle Pin Assy	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	450.000	16450.000	2550.000	550.000	FOUR HUNDRED FIFTY	SIXTEEN THOUSAND FOUR HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED FIFTY
96.0	Spring Bush	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	150.000	2850.000	150.000	150.000	ONE HUNDRED FIFTY	TWO THOUSAND EIGHT HUNDRED FIFTY	ONE HUNDRED FIFTY
97.0	Spring Bush Metal	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	3500.000	450.000	950.000	SIX HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED	FOUR HUNDRED FIFTY
98.0	Spring Main Rear	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3650.000	9450.000	4500.000	3200.000	THREE THOUSAND SIX HUNDRED FIFTY	NINE THOUSAND FOUR HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRED
99.0	Spring Main -2nd	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3500.000	9000.000	3550.000	2800.000	THREE THOUSAND FIVE HUNDRED	NINE THOUSAND	THREE THOUSAND FIVE HUNDRED
100.0	Spring Main-3rd	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3200.000	9000.000	2500.000	2500.000	THREE THOUSAND TWO HUNDRED	NINE THOUSAND	TWO THOUSAND FIVE HUNDRED

101.0	Spring Main-4th	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2975.000	8850.000	2100.000	2200.000	TWO THOUSAND NINE HUNDRED SEVENTY FIVE	EIGHT THOUSAND EIGHT HUNDRED FIFTY	TWO THOUSAND ONE HUNDRED FIFTY
102.0	Spring Main-5th	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	2750.000	8500.000	950.000	1800.000	TWO THOUSAND SEVEN HUNDRED FIFTY	EIGHT THOUSAND FIVE HUNDRED	NINE HUNDRED FIFTY
103.0	Stabilizer Bar Bush -Front	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	100.000	3450.000	1750.000	20.000	ONE HUNDRED	THREE THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND SEVEN HUNDRED FIFTY
104.0	Stabilizer Bar Bush-Rear	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	100.000	3750.000	1750.000	20.000	ONE HUNDRED	THREE THOUSAND SEVEN HUNDRED FIFTY	ONE THOUSAND SEVEN HUNDRED FIFTY
105.0	Steering Damper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	3000.000	16450.000	3550.000	2250.000	THREE THOUSAND	SIXTEEN THOUSAND FOUR HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED FIFTY
106.0	Side Light	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	14500.000	1750.000	650.000	SIX HUNDRED FIFTY	FOURTEEN THOUSAND FIVE HUNDRED	ONE THOUSAND SEVEN HUNDRED FIFTY
107.0	Side Light Bulb	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	75.000	500.000	25.000	20.000	SEVENTY FIVE	FIVE HUNDRED	TWENTY FIVE
108.0	Side Light Clamp	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	8500.000	25.000	350.000	FIFTY	EIGHT THOUSAND FIVE HUNDRED	TWENTY FIVE
109.0	Spring Clamp	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	4500.000	50.000	450.000	TWO HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRED	FIFTY

110.0	Tail Inner Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	950,000	12500,000	1850,000	1850,000	1850,000	NINE HUNDRED FIFTY	TWELVE THOUSAND FIVE HUNDRED	ONE THOUS EIGHT HUND FIFTY
111.0	Tail Outer Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	950,000	12500,000	1950,000	2200,000	2200,000	NINE HUNDRED FIFTY	TWELVE THOUSAND FIVE HUNDRED	ONE THOUS NINE HUND FIFTY
112.0	Tail Oil Seal	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	550,000	2500,000	1750,000	550,000	550,000	FIVE HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED	ONE THOUS SEVEN HUND FIFTY
113.0	Tie Rod End-Big	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1850,000	18950,000	2500,000	3950,000	3950,000	ONE THOUSAND EIGHT HUNDRED FIFTY	EIGHTEEN THOUSAND NINE HUNDRED FIFTY	TWO THOUS FIVE HUND FIFTY
114.0	Tie Rod End-Small	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1850,000	18500,000	2500,000	3950,000	3950,000	ONE THOUSAND EIGHT HUNDRED FIFTY	EIGHTEEN THOUSAND FIVE HUNDRED	TWO THOUS FIVE HUND FIFTY
115.0	Timing Belt	Pos	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1850,000	4950,000	200,000	5,000	5,000	ONE THOUSAND EIGHT HUNDRED FIFTY	FOUR THOUSAND NINE HUNDRED FIFTY	TWO HUND FIFTY
116.0	U-Bolt	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	375,000	3950,000	450,000	550,000	550,000	THREE HUNDRED SEVENTY FIVE	THREE THOUSAND NINE HUNDRED FIFTY	FOUR HUND FIFTY
117.0	Water pump	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2500,000	16450,000	2850,000	6800,000	6800,000	TWO THOUSAND FIVE HUNDRED	SIXTEEN THOUSAND FOUR HUNDRED FIFTY	TWO THOUS EIGHT HUND FIFTY
118.0	Wheel Alignment	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	350,000	3350,000	350,000	400,000	400,000	THREE HUNDRED FIFTY	THREE THOUSAND THREE HUNDRED FIFTY	THREE HUND FIFTY

119.0	Wheel Cylinder Assy	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1900.000	265000.000	1950.000	5250.000	ONE THOUSAND NINE HUNDRED	ONE THOUSAND NINE HUNDRED FIFTY	ONE THOUSAND NINE HUNDRED FIFTY	20 TWENTY SIX THOUSAND FIVE HUNDRED	
120.0	Wheel Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1950.000	18950.000	2850.000	2950.000	ONE THOUSAND NINE HUNDRED FIFTY	EIGHT THOUSAND NINE HUNDRED FIFTY	TWO THOUSAND EIGHT HUNDRED FIFTY	18 EIGHTEEN THOUSAND NINE HUNDRED FIFTY	
121.0	Wiper Blade	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	850.000	3450.000	550.000	500.000	500.000	EIGHT HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED FIFTY	FIVE HUNDRED FIFTY	3 THREE THOUSAND FOUR HUNDRED FIFTY
122.0	Air cleaner filter changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	50.000	500.000	50.000	50.000	50.000	FIFTY	FIVE HUNDRED	FIFTY	5 FIVE HUNDRED
123.0	Axle oil seal changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300.000	500.000	650.000	250.000	250.000	THREE HUNDRED	FIVE HUNDRED	SIX HUNDRED FIFTY	5 FIVE HUNDRED
124.0	Ball joint changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0.000	950.000	0.000	450.000	0.000	ZERO	NINE HUNDRED FIFTY	ZERO	9 NINE HUNDRED FIFTY
125.0	Battery charging (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	100.000	500.000	250.000	50.000	250.000	ONE HUNDRED	FIVE HUNDRED	TWO HUNDRED FIFTY	5 FIVE HUNDRED
126.0	Brake adjusting (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	250.000	1500.000	400.000	200.000	400.000	TWO HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	FOUR HUNDRED	1 ONE THOUSAND FIVE HUNDRED
127.0	Brake cable changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	275.000	1200.000	0.000	150.000	0.000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND TWO HUNDRED	ZERO	1 ONE THOUSAND TWO HUNDRED

128.0	Brake Pad changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	400,000	1200,000	0,000	5,000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED	ZERO
129.0	Brake servicing 4 wheel (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	800,000	2450,000	1500,000	200,000	EIGHT HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED
130.0	Brake Shoe Changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	400,000	1450,000	750,000	300,000	FOUR HUNDRED	ONE THOUSAND FOUR HUNDRED FIFTY	SEVEN HUNDRED FIFTY
131.0	Chain sprocket changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	650,000	1450,000	0,000	500,000	SIX HUNDRED FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	ZERO
132.0	Clutch cable changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	250,000	1450,000	0,000	250,000	TWO HUNDRED FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	ZERO
133.0	Clutch Kit Changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	200,000	1200,000	450,000	50,000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED	FOUR HUNDRED FIFTY
134.0	Clutch plate/pressure plate changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	5000,000	4500,000	3500,000	2400,000	FIVE THOUSAND	FOUR THOUSAND FIVE HUNDRED	THREE THOUSAND FIVE HUNDRED
135.0	Clutch release bearing changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1500,000	1200,000	3500,000	1100,000	ONE THOUSAND FIVE HUNDRED	ONE THOUSAND TWO HUNDRED	THREE THOUSAND FIVE HUNDRED
136.0	Complete electrical line checking (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	350,000	3500,000	2500,000	200,000	THREE HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED	TWO THOUSAND FIVE HUNDRED



137.0	Cross bearing Changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	1200,000	450,000	250,000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED	FOUR HUND FIFTY
138.0	Crown overhauling (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	750,000	3850,000	6500,000	980,000	SEVEN HUNDRED FIFTY	THREE THOUSAND EIGHT HUNDRED FIFTY	SIX THOUS FIVE HUND FIFTY
139.0	CV joint Boot changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	1200,000	0,000	5,000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO
140.0	CV Joint changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	1200,000	0,000	5,000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO
141.0	CV joint oil seal changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	1200,000	0,000	350,000	ZERO	ONE THOUSAND TWO HUNDRED	ZERO
142.0	Diesel filter Changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	250,000	1200,000	150,000	150,000	TWO HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	ONE HUND FIFTY
143.0	Driver shaft oil seal changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	365,000	1200,000	0,000	20,000	THREE HUNDRED SIXTY FIVE	ONE THOUSAND TWO HUNDRED	ZERO
144.0	Engine Oil Changing with oil filter (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	400,000	1200,000	350,000	200,000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED	THREE HUND FIFTY
145.0	Engine over hauling (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	6500,000	5950,000	35000,000	2400,000	SIX THOUSAND FIVE HUNDRED	FIVE THOUSAND NINE HUNDRED FIFTY	THIRT FIVE THOUS

146.0	Fan belt changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	200.000	1200.000	350.000	250.000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED	THREE HUNDRED FIFTY
147.0	Front bumper opening & fitting (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	500.000	2450.000	450.000	350.000	FIVE HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	FOUR HUNDRED FIFTY
148.0	Gear Box mounting & dismounting (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	275.000	5500.000	1250.000	550.000	TWO HUNDRED SEVENTY FIVE	FIVE THOUSAND FIVE HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY
149.0	Gear oil changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	200.000	1250.000	250.000	200.000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	TWO HUNDRED FIFTY
150.0	Hub greasing (Service Charge)	4 Side	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	900.000	2500.000	2800.000	550.000	NINE HUNDRED	TWO THOUSAND FIVE HUNDRED	TWO THOUSAND EIGHT HUNDRED FIFTY
151.0	King pin greasing (Service Charge)	2 Side	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	800.000	1500.000	2950.000	250.000	EIGHT HUNDRED	ONE THOUSAND FIVE HUNDRED	TWO THOUSAND NINE HUNDRED FIFTY
152.0	Knuckle arm fitting (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	1450.000	1250.000	20.000	TWO HUNDRED FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED FIFTY
153.0	Master Cylinder Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	175.000	1950.000	750.000	450.000	ONE HUNDRED SEVENTY FIVE	ONE THOUSAND NINE HUNDRED FIFTY	SEVEN HUNDRED FIFTY
154.0	Number Plate new making (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	650.000	2450.000	350.000	400.000	SIX HUNDRED FIFTY	TWO THOUSAND FOUR HUNDRED FIFTY	THREE HUNDRED FIFTY

155.0	Oil Seal changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	1200,000	250,000	350,000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED	TWO HUND FIFTY
156.0	Power steering belt changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	200,000	1200,000	550,000	250,000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED	FIVE HUND FIFTY
157.0	Radiator Servicing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1500,000	3950,000	650,000	1100,000	ONE THOUSAND FIVE HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	SIX HUND FIFTY
158.0	Removing & Fitting of spring assy (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	400,000	2450,000	1250,000	450,000	FOUR HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	ONE THOUS HUND FIFTY
159.0	Self starter overhauling (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	1500,000	3450,000	1250,000	1100,000	ONE THOUSAND FIVE HUNDRED	THREE THOUSAND FOUR HUNDRED FIFTY	ONE THOUS HUND FIFTY
160.0	Shock absorber changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	1250,000	650,000	150,000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	SIX HUND FIFTY
161.0	Spring Changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	350,000	1250,000	1250,000	450,000	THREE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED FIFTY	ONE THOUS HUND FIFTY
162.0	Spring Greasing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	275,000	1950,000	450,000	200,000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND NINE HUNDRED FIFTY	FOUR HUND FIFTY
163.0	Spring pad changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	120,000	1500,000	750,000	400,000	ONE HUNDRED TWENTY	ONE THOUSAND FIVE HUNDRED	SEVEN HUND FIFTY

164.0	Stabilizer bush changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	50.000	1200.000	650.000	20.000	FIFTY	ONE THOUSAND TWO HUNDRED	SIX HUND FIFTY
165.0	Stabilizer link assy changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	250.000	1500.000	950.000	20.000	TWO HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	NINE HUND FIFTY
166.0	Steering Rack end assy (Link)changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	300.000	1500.000	1250.000	350.000	THREE HUNDRED	ONE THOUSAND FIVE HUNDRED	ONE THOUS TWO HUND FIFTY
167.0	suspension arm changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	0.000	1850.000	0.000	250.000	ZERO	ONE THOUSAND EIGHT HUNDRED FIFTY	ZERO
168.0	Tail pinion oil seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	325.000	1200.000	1950.000	250.000	THREE HUNDRED TWENTY FIVE	ONE THOUSAND TWO HUNDRED	ONE THOUS NINE HUND FIFTY
169.0	Tappet adjustement (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	500.000	2350.000	550.000	200.000	FIVE HUNDRED	TWO THOUSAND THREE HUNDRED FIFTY	FIVE HUND FIFTY
170.0	Tie rod end changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	275.000	1450.000	1250.000	350.000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND FOUR HUNDRED FIFTY	ONE THOUS TWO HUND FIFTY
171.0	Timing belt changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	1950.000	1550.000	850.000	SEVEN HUNDRED FIFTY	ONE THOUSAND NINE HUNDRED FIFTY	ONE THOUS FIVE HUND FIFTY
172.0	Tyre Changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	india	India	Bhutan	INDIA	750.000	1450.000	200.000	200.000	SEVEN HUNDRED FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	TWO HUND FIFTY

173.0	Vane pump changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	300,000	1500,000	4500,000	250,000	THREE HUNDRED	ONE THOUSAND FIVE HUNDRED	FOUR THOUSAND FIVE HUNDRED
174.0	Welding (Service Charge)	M	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	0,000	2450,000	100,000	100,000	ZERO	TWO THOUSAND FOUR HUNDRED FIFTY	ONE HUNDRED
175.0	Wheel Alignment (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	350,000	1500,000	350,000	400,000	THREE HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	THREE HUNDRED FIFTY
176.0	Whole body greasing (Service Charge)	Whole body	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	800,000	5000,000	550,000	250,000	EIGHT HUNDRED	FIVE THOUSAND	FIVE HUNDRED FIFTY
177.0	Wind shield glass fitting (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	2500,000	5500,000	3500,000	1200,000	TWO THOUSAND FIVE HUNDRED	FIVE THOUSAND FIVE HUNDRED	THREE THOUSAND FIVE HUNDRED
178.0	Wiper alignment (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	100,000	1200,000	50,000	50,000	ONE HUNDRED	ONE THOUSAND TWO HUNDRED	FIFTY
179.0	Wiper blade changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	india	India	Bhutan	INDIA	50,000	300,000	50,000	20,000	FIFTY	THREE HUNDRED	FIFTY
							<b>Grand Total</b>											

Handwritten notes in blue ink:

- Next to 179.0: "awarded to DSC" (with a circled 'DSC')
- Next to 179.0: "H/S Kuenzom" (with a circled "H/S")
- Next to 179.0: "Audinbill" (with a circled "Audinbill")

Large handwritten signature in blue ink at the top right of the table.

System Generated Report based on the tender submitted by the Bidders / Consultants

Home | About e-GP | Contact Us | Terms and Conditions | e-Learning



Version: 3.3.1

Handwritten signature in blue ink at the bottom center.