



དཔལ་ལྷན་འབྲུག་གཞུང་། དངུལ་རྩིས་ལྷན་ཁག།  
Royal Government of Bhutan, Ministry of Finance



མགོ་གྲུབ་འཛིན་རྒྱུ་དང་གོང་འཕེལ་གྱི་ཚན། རྒྱལ་ཡོངས་གཞུང་ཚན་ལས་ཁུངས།  
Procurement Management and Development Division

Home Dashboard APP Tender CMS Workflow Committees My Account Help

Wednesday, 25 September, 2024, 12:30:37 BST

Last Login : Wednesday, 25 September, 2024, 10:21:09 BST

Welcome, Ngawang Chopel [Roles] | Logout

Tender >> My Tender >> My Tenders/Proposals (Live) >> Tender/Proposal Dashboard >> Opening Process >> View Comparative Report

View Comparative Report

Print Save As Excel Go Back To Dashboard

Tender Detail	
Tender ID : 18629	Invitation Reference No. : JKD/Pro-01/2024-2025/261-13
Closing Date and Time : 14-Sep-2024 16:10	Opening Date and Time : 14-Sep-2024 16:10
Procuring Agency : Dzongkhag Administration Bumthang	Procurement Category : Goods
Brief : <u>Supply of vehicle spare parts and maintenance for the FY 2024-2025</u>	
Tender Status : Being evaluated	<a href="#">View Notice</a>

Bid Submission Closing Date is thirty (30) minutes prior to Bid Opening Date. For Tender Id: 18629 the Closing Date is 14-Sep-2024 16:10 and Bid Opening Date is 14-Sep-2024 16:40

Package No	Package Description
JKD/Pro-01/2024-2025/261-13	Supply of vehicle spare parts and maintenance

Schedule of Items and Priced Quotation FORTUNER

The Bhutan Standards Bureau (BSB) certification requirements followed by words "or equivalent or higher" with which the goods, equipment, materials or workmanship shall comply in their p

Schedule of Items and Priced Quotation (Form e-SG-1)

Item No.	Name and Description of Item	Unit	Quantity	Point of Delivery	Delivery Period [In Days]	Technical Specification and Standards required	Warranty Period from the date of Acceptance [in days]	Make/Model and Country of Origin				Unit Price in Figure [In Nu.]			Unit Price in Wo			
								Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works	Kuenzom Automobile Workshop	Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Leki Auto Engg Works	Kuenzom Automobile Workshop	Namsay Automobile Workshop	YANKA AUTO SPARE PARTS SHOP	Karma Auto I Works
1.0	Arm Bush Lower	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1650.000	4950.000	2950.000	1600.000	ONE THOUSAND SIX HUNDRED FIFTY	FOUR THOUSAND NINE HUNDRED FIFTY	TWO THOU HUND FIFTY
2.0	Arm Bush Upper	Set	1.000	Respective Procuring Agency	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1650.000	4950.000	2950.000	1550.000	ONE THOUSAND SIX	FOUR THOUSAND NINE	TWO THOU NINE

*[Handwritten signature]*

*[Handwritten signature]*

				Office under Bumthang Dzongkhag												HUNDRED FIFTY	HUNDRED FIFTY	HUND FIFTY
3.0	Arm Lower	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1700.000	26450.000	3500.000	<del>12500.000</del>	ONE THOUSAND SEVEN HUNDRED	TWENTY SIX THOUSAND FOUR HUNDRED FIFTY	THRE THOU FIVE HUND
4.0	Arm Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	6500.000	26450.000	3500.000	14500.000	SIX THOUSAND FIVE HUNDRED	TWENTY SIX THOUSAND FOUR HUNDRED FIFTY	THRE THOU FIVE HUND
5.0	AC Belt	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	7500.000	8500.000	2500.000	2750.000	SEVEN THOUSAND FIVE HUNDRED	EIGHT THOUSAND FIVE HUNDRED	TWO THOU FIVE HUND
6.0	Acceleator Cable	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	650.000	7950.000	1250.000	20.000	SIX HUNDRED FIFTY	SEVEN THOUSAND NINE HUNDRED FIFTY	ONE THOU TWO HUND FIFTY
7.0	Air Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2500.000	6450.000	3500.000	2700.000	TWO THOUSAND FIVE HUNDRED	SIX THOUSAND FOUR HUNDRED FIFTY	THRE THOU FIVE HUND
8.0	Anabond	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	185.000	450.000	70.000	90.000	ONE HUNDRED EIGHTY FIVE	FOUR HUNDRED FIFTY	SEVEI
9.0	Axle	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	6500.000	33450.000	12500.000	20.000	SIX THOUSAND FIVE HUNDRED	THIRTY THREE THOUSAND FOUR HUNDRED FIFTY	TWEL' THOU FIVE HUND
10.0	Axle Oil Seal Outer	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	650.000	3450.000	2200.000	550.000	SIX HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED FIFTY	TWO THOU TWO HUND

*[Handwritten signatures and initials in blue ink on the left margin]*

*[Handwritten signatures and initials in blue ink at the bottom right]*



11.0	Axle Tube Oil Seal	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	650.000	3450.000	750.000	950.000	SIX HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED FIFTY	SEVE HUND FIFTY
12.0	Back Light	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	3500.000	14500.000	6500.000	5200.000	THREE THOUSAND FIVE HUNDRED	FOURTEEN THOUSAND FIVE HUNDRED	SIX THOU FIVE HUND
13.0	Back Light Bulb	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	75.000	500.000	50.000	250.000	SEVENTY FIVE	FIVE HUNDRED	FIFTY
14.0	Battery	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	9500.000	18500.000	8700.000	8125.000	NINE THOUSAND FIVE HUNDRED	EIGHTEEN THOUSAND FIVE HUNDRED	EIGHT THOU SEVE HUND
15.0	Ball Joint Lower	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	3750.000	7850.000	3500.000	3400.000	THREE THOUSAND SEVEN HUNDRED FIFTY	SEVEN THOUSAND EIGHT HUNDRED FIFTY	THRE THOU FIVE HUND
16.0	Ball Joint Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	3500.000	7850.000	3500.000	3450.000	THREE THOUSAND FIVE HUNDRED	SEVEN THOUSAND EIGHT HUNDRED FIFTY	THRE THOU FIVE HUND
17.0	Brake Booster	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	9500.000	24500.000	7500.000	17800.000	NINE THOUSAND FIVE HUNDRED	TWENTY FOUR THOUSAND FIVE HUNDRED	SEVE THOU FIVE HUND
18.0	Brake Bucket Kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	50.000	7500.000	50.000	550.000	FIFTY	SEVEN THOUSAND FIVE HUNDRED	FIFTY
19.0	Brake Hub Front	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	6500.000	19500.000	2500.000	0.000	SIX THOUSAND FIVE HUNDRED	NINETEEN THOUSAND FIVE HUNDRED	TWO THOU FIVE HUND

20.0	Brake Hub Rear	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	5000.000	19950.000	2500.000	0.000	FIVE THOUSAND	NINETEEN THOUSAND NINE HUNDRED FIFTY	TWO THOU FIVE HUND
21.0	Brake Oil	Lts	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	550.000	1350.000	250.000	750.000	FIVE HUNDRED FIFTY	ONE THOUSAND THREE HUNDRED FIFTY	TWO HUND FIFTY
22.0	Brake Disc	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	5500.000	21950.000	6500.000	0.000	FIVE THOUSAND FIVE HUNDRED	TWENTY ONE THOUSAND NINE HUNDRED FIFTY	SIX THOU FIVE HUND
23.0	Brake Pad	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	8000.000	16950.000	9500.000	9500.000	EIGHT THOUSAND	SIXTEEN THOUSAND NINE HUNDRED FIFTY	NINE THOU FIVE HUND
24.0	Brake Shoe	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	8250.000	17450.000	4500.000	5400.000	EIGHT THOUSAND TWO HUNDRED FIFTY	SEVENTEEN THOUSAND FOUR HUNDRED FIFTY	FOUR THOU FIVE HUND
25.0	Cam Shaft Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1450.000	11450.000	0.000	850.000	ONE THOUSAND FOUR HUNDRED FIFTY	ELEVEN THOUSAND FOUR HUNDRED FIFTY	ZERO
26.0	Center Bolt	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	375.000	2950.000	150.000	5.000	THREE HUNDRED SEVENTY FIVE	TWO THOUSAND NINE HUNDRED FIFTY	ONE HUND FIFTY
27.0	Connecting Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1750.000	12500.000	0.000	950.000	ONE THOUSAND SEVEN HUNDRED FIFTY	TWELVE THOUSAND FIVE HUNDRED	ZERO
28.0	Coolant	Lts	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	250.000	1200.000	450.000	850.000	TWO HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	FOUR HUND FIFTY

Handwritten signatures and initials in blue ink on the left margin, including a large signature at the top, a signature in the middle, and a signature at the bottom.

Handwritten signature in blue ink at the bottom right corner of the page.



29.0	Cross Bearing	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2350.000	4950.000	0.000	4950.000	TWO THOUSAND THREE HUNDRED FIFTY	FOUR THOUSAND NINE HUNDRED FIFTY	ZERO
30.0	Crown & Tail Assy	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	6500.000	74500.000	0.000	0.000	SIX THOUSAND FIVE HUNDRED	SEVENTY FOUR THOUSAND FIVE HUNDRED	ZERO
31.0	CV Joint Assembly	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	12500.000	12500.000	0.000	28500.000	TWELVE THOUSAND FIVE HUNDRED	TWELVE THOUSAND FIVE HUNDRED	ZERO
32.0	Check nut lock	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	100.000	550.000	550.000	250.000	ONE HUNDRED	FIVE HUNDRED FIFTY	FIVE HUND FIFTY
33.0	Clutch Cylinder Lower	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1650.000	16450.000	4500.000	5400.000	ONE THOUSAND SIX HUNDRED FIFTY	SIXTEEN THOUSAND FOUR HUNDRED FIFTY	FOUR THOU FIVE HUND
34.0	Clutch Cylinder Upper	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1975.000	17450.000	2500.000	8500.000	ONE THOUSAND NINE HUNDRED SEVENTY FIVE	SEVENTEEN THOUSAND FOUR HUNDRED FIFTY	TWO THOU FIVE HUND
35.0	Clutch Plate	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	11500.000	17950.000	9500.000	9400.000	ELEVEN THOUSAND FIVE HUNDRED	SEVENTEEN THOUSAND NINE HUNDRED FIFTY	NINE THOU FIVE HUND
36.0	Connection Rod	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2500.000	17500.000	0.000	850.000	TWO THOUSAND FIVE HUNDRED	SEVENTEEN THOUSAND FIVE HUNDRED	ZERO
37.0	Crank Shaft	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	11000.000	74500.000	0.000	0.000	ELEVEN THOUSAND	SEVENTY FOUR THOUSAND FIVE HUNDRED	ZERO

*Handwritten signature*

*Handwritten signature*

*Handwritten signature*

*Handwritten signature*

38.0	Dhoti	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	50.000	150.000	10.000	10.000	FIFTY	ONE HUNDRED FIFTY	TEN
39.0	Dust Guard	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	750.000	4850.000	3500.000	2200.000	SEVEN HUNDRED FIFTY	FOUR THOUSAND EIGHT HUNDRED FIFTY	THRE THOU FIVE HUND
40.0	Disel Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1500.000	2350.000	1750.000	2400.000	ONE THOUSAND FIVE HUNDRED	TWO THOUSAND THREE HUNDRED FIFTY	ONE THOU SEVE HUND FIFTY
41.0	Engine Mounting	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2650.000	2000.000	0.000	950.000	TWO THOUSAND SIX HUNDRED FIFTY	TWO THOUSAND	ZERO
42.0	Engine Oil Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1500.000	2450.000	1750.000	850.000	ONE THOUSAND FIVE HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	ONE THOU SEVE HUND FIFTY
43.0	Fan Belt	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2300.000	3950.000	2750.000	2650.000	TWO THOUSAND THREE HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	TWO THOU SEVE HUND FIFTY
44.0	Feed Pump	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2500.000	44500.000	2200.000	1650.000	TWO THOUSAND FIVE HUNDRED	FORTY FOUR THOUSAND FIVE HUNDRED	TWO THOU TWO HUND
45.0	Fuel Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1500.000	2350.000	1650.000	2400.000	ONE THOUSAND FIVE HUNDRED	TWO THOUSAND THREE HUNDRED FIFTY	ONE THOU SIX HUND FIFTY
46.0	Fuel Supply Pump	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	3500.000	43500.000	1350.000	550.000	THREE THOUSAND FIVE HUNDRED	FORTY THREE THOUSAND FIVE HUNDRED	ONE THOU THREE HUND FIFTY

Handwritten signatures and initials in blue ink on the left side of the page, including a large signature and a circular stamp.

Handwritten signature in blue ink at the bottom right corner of the page.



47.0	Fog Light	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	1200,000	13500,000	3500,000	3300,000	ONE THOUSAND TWO HUNDRED	THIRTEEN THOUSAND FIVE HUNDRED	THRE THOU FIVE HUND
48.0	Fuse	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	25,000	550,000	15,000	10,000	TWENTY FIVE	FIVE HUNDRED FIFTY	FIFTE
49.0	Bear Box	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	250,000	64500,000	0,000	0,000	TWO HUNDRED FIFTY	SIXTY FOUR THOUSAND FIVE HUNDRED	ZERO
50.0	Grease	Kg	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	450,000	850,000	380,000	550,000	FOUR HUNDRED FIFTY	EIGHT HUNDRED FIFTY	THRE HUND EIGHT
51.0	Glow Plug	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	3200,000	4250,000	10500,000	2850,000	THREE THOUSAND TWO HUNDRED	FOUR THOUSAND TWO HUNDRED FIFTY	TEN THOU FIVE HUND
52.0	Hand Brake Cable	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	3500,000	14500,000	7500,000	3700,000	THREE THOUSAND FIVE HUNDRED	FOURTEEN THOUSAND FIVE HUNDRED	SEVE THOU FIVE HUND
53.0	Head Gasket	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	1975,000	8950,000	1350,000	3400,000	ONE THOUSAND NINE HUNDRED SEVENTY FIVE	EIGHT THOUSAND NINE HUNDRED FIFTY	ONE THOU THREE HUND FIFTY
54.0	Head light Set	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	3650,000	19950,000	18000,000	0,000	THREE THOUSAND SIX HUNDRED FIFTY	NINETEEN THOUSAND NINE HUNDRED FIFTY	EIGHT THOU
55.0	Head Light Bulb	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	375,000	550,000	300,000	150,000	THREE HUNDRED SEVENTY FIVE	FIVE HUNDRED FIFTY	THRE HUND

56.0	Hub Oil Seal	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	850.000	3450.000	1250.000	450.000	EIGHT HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED FIFTY	ONE THOU TWO HUND FIFTY
57.0	Hub Splender	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	6500.000	19500.000	1800.000	0.000	SIX THOUSAND FIVE HUNDRED	NINETEEN THOUSAND FIVE HUNDRED	ONE THOU EIGHT HUND
58.0	Horn	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1200.000	14500.000	1550.000	800.000	ONE THOUSAND TWO HUNDRED	FOURTEEN THOUSAND FIVE HUNDRED	ONE THOU FIVE HUND FIFTY
59.0	Hub Bearing F Inner	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	9500.000	13500.000	4500.000	8400.000	NINE THOUSAND FIVE HUNDRED	THIRTEEN THOUSAND FIVE HUNDRED	FOUR THOU FIVE HUND
60.0	Hub Bearing F Out	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	0.000	13500.000	4500.000	0.000	ZERO	THIRTEEN THOUSAND FIVE HUNDRED	FOUR THOU FIVE HUND
61.0	Hub Check Nut	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	100.000	3950.000	450.000	250.000	ONE HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	FOUR HUND FIFTY
62.0	Intake valve	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2275.000	9950.000	0.000	850.000	TWO THOUSAND TWO HUNDRED SEVENTY FIVE	NINE THOUSAND NINE HUNDRED FIFTY	ZERO
63.0	Key Lock Set	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2750.000	13500.000	0.000	10500.000	TWO THOUSAND SEVEN HUNDRED FIFTY	THIRTEEN THOUSAND FIVE HUNDRED	ZERO
64.0	Kimpin Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	0.000	8950.000	0.000	20.000	ZERO	EIGHT THOUSAND NINE HUNDRED FIFTY	ZERO



65.0	King Pin Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	0.000	9500.000	0.000	20.000	ZERO	NINE THOUSAND FIVE HUNDRED	ZERO
66.0	King pin kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	0.000	7850.000	0.000	20.000	ZERO	SEVEN THOUSAND EIGHT HUNDRED FIFTY	ZERO
67.0	Link Rod	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	3875.000	24500.000	2550.000	2900.000	THREE THOUSAND EIGHT HUNDRED SEVENTY FIVE	TWENTY FOUR THOUSAND FIVE HUNDRED	TWO THOU FIVE HUND FIFTY
68.0	Link Bush Front	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	100.000	4450.000	550.000	120.000	ONE HUNDRED	FOUR THOUSAND FOUR HUNDRED FIFTY	FIVE HUND FIFTY
69.0	Link Bush Rear	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	100.000	4550.000	550.000	550.000	ONE HUNDRED	FOUR THOUSAND FIVE HUNDRED FIFTY	FIVE HUND FIFTY
70.0	Master Cylinder Kit	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	450.000	7950.000	250.000	300.000	FOUR HUNDRED FIFTY	SEVEN THOUSAND NINE HUNDRED FIFTY	TWO HUND FIFTY
71.0	Master Cylinder	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1200.000	19950.000	6500.000	14200.000	ONE THOUSAND TWO HUNDRED	NINETEEN THOUSAND NINE HUNDRED FIFTY	SIX THOU FIVE HUND
72.0	Main Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2750.000	14500.000	0.000	850.000	TWO THOUSAND SEVEN HUNDRED FIFTY	FOURTEEN THOUSAND FIVE HUNDRED	ZERO
73.0	Main Bearing Oil Seal	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	950.000	3450.000	0.000	1400.000	NINE HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED FIFTY	ZERO

74.0	Mobile Filter	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1500.000	2350.000	1550.000	850.000	ONE THOUSAND FIVE HUNDRED	TWO THOUSAND THREE HUNDRED FIFTY	ONE THOU FIVE HUND FIFTY
75.0	Nuts and Bolts(4 Wheel)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	300.000	6450.000	200.000	10.000	THREE HUNDRED	SIX THOUSAND FOUR HUNDRED FIFTY	TWO HUND
76.0	Oil Supply Pump	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1300.000	42500.000	1200.000	550.000	ONE THOUSAND THREE HUNDRED	FORTY TWO THOUSAND FIVE HUNDRED	ONE THOU TWO HUND
77.0	Power Steering Belt	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2300.000	4950.000	2500.000	2200.000	TWO THOUSAND THREE HUNDRED	FOUR THOUSAND NINE HUNDRED FIFTY	TWO THOU FIVE HUND
78.0	Power Steering Oil	ltrs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	550.000	1200.000	350.000	750.000	FIVE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	THRE HUND FIFTY
79.0	Pressure Plate	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	12750.000	19500.000	6500.000	10500.000	TWELVE THOUSAND SEVEN HUNDRED FIFTY	NINETEEN THOUSAND FIVE HUNDRED	SIX THOU FIVE HUND
80.0	Piston	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	9500.000	14500.000	0.000	7500.000	NINE THOUSAND FIVE HUNDRED	FOURTEEN THOUSAND FIVE HUNDRED	ZERO
81.0	Piston Ring	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	875.000	14950.000	0.000	7400.000	EIGHT HUNDRED SEVENTY FIVE	FOURTEEN THOUSAND NINE HUNDRED FIFTY	ZERO
82.0	Shaft yoke & Teeth	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	5500.000	17500.000	1250.000	4250.000	FIVE THOUSAND FIVE HUNDRED	SEVENTEEN THOUSAND FIVE HUNDRED	ONE THOU TWO HUND FIFTY

Handwritten signatures and initials in blue ink on the left side of the page, including a large signature and several smaller initials.

Handwritten signature in blue ink at the bottom right corner of the page.



83.0	Radiator Cap	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	600,000	1450,000	350,000	450,000	SIX HUNDRED	ONE THOUSAND FOUR HUNDRED FIFTY	THREE HUND FIFTY
84.0	Rear Axle Corn	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	1300,000	24500,000	0,000	1250,000	ONE THOUSAND THREE HUNDRED	TWENTY FOUR THOUSAND FIVE HUNDRED	ZERO
85.0	Rear Differential Assy	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	6500,000	68600,000	0,000	0,000	SIX THOUSAND FIVE HUNDRED	SIXTY EIGHT THOUSAND SIX HUNDRED	ZERO
86.0	Release Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	4500,000	5250,000	1950,000	3300,000	FOUR THOUSAND FIVE HUNDRED	FIVE THOUSAND TWO HUNDRED FIFTY	ONE THOU NINE HUND FIFTY
87.0	Spark Plug	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	0,000	3850,000	0,000	5,000	ZERO	THREE THOUSAND EIGHT HUNDRED FIFTY	ZERO
88.0	Self Armaure	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	3000,000	14500,000	2550,000	3300,000	THREE THOUSAND	FOURTEEN THOUSAND FIVE HUNDRED	TWO THOU FIVE HUND FIFTY
89.0	Self Carbon	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	750,000	2950,000	1200,000	1100,000	SEVEN HUNDRED FIFTY	TWO THOUSAND NINE HUNDRED FIFTY	ONE THOU TWO HUND
90.0	Self Carmon Rocker	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	975,000	4500,000	550,000	250,000	NINE HUNDRED SEVENTY FIVE	FOUR THOUSAND FIVE HUNDRED	FIVE HUND FIFTY
91.0	Self Plunge	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	1900,000	6950,000	2300,000	550,000	ONE THOUSAND NINE HUNDRED	SIX THOUSAND NINE HUNDRED FIFTY	TWO THOU THRE HUND

92.0	Shock Absorber Bush	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	150.000	1200.000	250.000	120.000	ONE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	TWO HUND FIFTY
93.0	Shock Absover Front	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	8500.000	17500.000	5500.000	5400.000	EIGHT THOUSAND FIVE HUNDRED	SEVENTEEN THOUSAND FIVE HUNDRED	FIVE THOU FIVE HUND
94.0	Shock Absover Rear	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	7500.000	18500.000	5500.000	2700.000	SEVEN THOUSAND FIVE HUNDRED	EIGHTEEN THOUSAND FIVE HUNDRED	FIVE THOU FIVE HUND
95.0	Shakle Pin Assy	set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	450.000	14500.000	0.000	5.000	FOUR HUNDRED FIFTY	FOURTEEN THOUSAND FIVE HUNDRED	ZERO
96.0	Spring Bush	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	150.000	2350.000	0.000	20.000	ONE HUNDRED FIFTY	TWO THOUSAND THREE HUNDRED FIFTY	ZERO
97.0	Spring Bush Metal	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	650.000	2500.000	0.000	20.000	SIX HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED	ZERO
98.0	Spring Main Rear	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2950.000	7950.000	0.000	5.000	TWO THOUSAND NINE HUNDRED FIFTY	SEVEN THOUSAND NINE HUNDRED FIFTY	ZERO
99.0	Spring Main -2nd	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2750.000	7600.000	0.000	5.000	TWO THOUSAND SEVEN HUNDRED FIFTY	SEVEN THOUSAND SIX HUNDRED	ZERO
100.0	Spring Main-3rd	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2550.000	7450.000	0.000	5.000	TWO THOUSAND FIVE HUNDRED FIFTY	SEVEN THOUSAND FOUR HUNDRED FIFTY	ZERO

Handwritten signatures and initials in blue ink on the left side of the page, including a large signature at the top and several smaller ones below.

Handwritten signature in blue ink at the bottom right corner of the page.



101.0	Spring Main-4th	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	2350,000	7000,000	0,000	5,000	TWO THOUSAND THREE HUNDRED FIFTY	SEVEN THOUSAND	ZERO
102.0	Spring Main-5th	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	2100,000	7000,000	0,000	5,000	TWO THOUSAND ONE HUNDRED	SEVEN THOUSAND	ZERO
103.0	Stabilizer Bar Bush -Front	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	100,000	3450,000	1650,000	650,000	ONE HUNDRED	THREE THOUSAND FOUR HUNDRED FIFTY	ONE THOU SIX HUND FIFTY
104.0	Stabilizer Bar Bush-Rear	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	100,000	3450,000	2500,000	450,000	ONE HUNDRED	THREE THOUSAND FOUR HUNDRED FIFTY	TWO THOU FIVE HUND
105.0	Steering Damper	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	5500,000	16500,000	0,000	4250,000	FIVE THOUSAND FIVE HUNDRED	SIXTEEN THOUSAND FIVE HUNDRED	ZERO
106.0	Side Light	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	1200,000	13500,000	0,000	20,000	ONE THOUSAND TWO HUNDRED	THIRTEEN THOUSAND FIVE HUNDRED	ZERO
107.0	Side Light Bulb	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	75,000	500,000	50,000	20,000	SEVENTY FIVE	FIVE HUNDRED	FIFTY
108.0	Side Light Clamp	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	100,000	8500,000	50,000	20,000	ONE HUNDRED	EIGHT THOUSAND FIVE HUNDRED	FIFTY
109.0	Spring Clamp	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	250,000	4500,000	50,000	50,000	TWO HUNDRED FIFTY	FOUR THOUSAND FIVE HUNDRED	FIFTY

110.0	Tail Inner Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	950.000	9500.000	0.000	1450.000	NINE HUNDRED FIFTY	NINE THOUSAND FIVE HUNDRED	ZERO
111.0	Tail Outer Bearing	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	950.000	9500.000	0.000	400.000	NINE HUNDRED FIFTY	NINE THOUSAND FIVE HUNDRED	ZERO
112.0	Tail Oil Seal	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	850.000	3350.000	0.000	650.000	EIGHT HUNDRED FIFTY	THREE THOUSAND THREE HUNDRED FIFTY	ZERO
113.0	Tie Rod End-Big	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2850.000	14500.000	2550.000	3750.000	TWO THOUSAND EIGHT HUNDRED FIFTY	FOURTEEN THOUSAND FIVE HUNDRED	TWO THOU FIVE HUND FIFTY
114.0	Tie Rod End-Small	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2850.000	14950.000	2550.000	3750.000	TWO THOUSAND EIGHT HUNDRED FIFTY	FOURTEEN THOUSAND NINE HUNDRED FIFTY	TWO THOU FIVE HUND FIFTY
115.0	Timing Belt	Pcs	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2975.000	4350.000	4500.000	<del>3400.000</del>	TWO THOUSAND NINE HUNDRED SEVENTY FIVE	FOUR THOUSAND THREE HUNDRED FIFTY	FOUR THOU FIVE HUND
116.0	U-Bolt	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	275.000	3950.000	0.000	20.000	TWO HUNDRED SEVENTY FIVE	THREE THOUSAND NINE HUNDRED FIFTY	ZERO
117.0	Water pump	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	5500.000	18950.000	6500.000	7200.000	FIVE THOUSAND FIVE HUNDRED	EIGHTEEN THOUSAND NINE HUNDRED FIFTY	SIX THOU FIVE HUND
118.0	Wheel Alignment	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	350.000	1650.000	350.000	400.000	THREE HUNDRED FIFTY	ONE THOUSAND SIX HUNDRED FIFTY	THRE HUND FIFTY

AM  
  






119.0	Wheel Cylinder Assy	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	3500,000	28500,000	0,000	4250,000	THREE THOUSAND FIVE HUNDRED	TWENTY EIGHT THOUSAND FIVE HUNDRED	ZERO
120.0	Wheel Bearing	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	0,000	18950,000	5500,000	250,000	ZERO	EIGHTEEN THOUSAND NINE HUNDRED FIFTY	FIVE THOU FIVE HUND
121.0	Wiper Blade	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	1650,000	3450,000	500,000	650,000	ONE THOUSAND SIX HUNDRED FIFTY	THREE THOUSAND FOUR HUNDRED FIFTY	FIVE HUND
122.0	Air cleaner filter changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	50,000	500,000	50,000	50,000	FIFTY	FIVE HUNDRED	FIFTY
123.0	Axle oil seal changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	300,000	500,000	350,000	200,000	THREE HUNDRED	FIVE HUNDRED	THRE HUND FIFTY
124.0	Ball joint changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	0,000	950,000	1450,000	350,000	ZERO	NINE HUNDRED FIFTY	ONE THOU FOUR HUND FIFTY
125.0	Battery charging (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	100,000	500,000	200,000	50,000	ONE HUNDRED	FIVE HUNDRED	TWO HUND
126.0	Brake adjusting (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	250,000	1500,000	50,000	200,000	TWO HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	FIFTY
127.0	Brake cable changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	275,000	1200,000	250,000	300,000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND TWO HUNDRED	TWO HUND FIFTY

128.0	Brake Pad changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	400.000	1200.000	400.000	200.000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED	FOUR HUND
129.0	Brake servicing 4 wheel (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	800.000	2450.000	400.000	200.000	EIGHT HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	FOUR HUND
130.0	Brake Shoe Changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	400.000	1450.000	700.000	300.000	FOUR HUNDRED	ONE THOUSAND FOUR HUNDRED FIFTY	SEVEI HUND
131.0	Chain spocket changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	650.000	1450.000	0.000	550.000	SIX HUNDRED FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	ZERO
132.0	Clutch cable changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	250.000	1450.000	0.000	20.000	TWO HUNDRED FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	ZERO
133.0	Clutch Kit Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	200.000	1200.000	450.000	300.000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED	FOUR HUND FIFTY
134.0	Clutch plate/pressure plate changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	5000.000	4500.000	4500.000	2400.000	FIVE THOUSAND	FOUR THOUSAND FIVE HUNDRED	FOUR THOU FIVE HUND
135.0	Clutch release bearing changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	1500.000	1200.000	4500.000	1100.000	ONE THOUSAND FIVE HUNDRED	ONE THOUSAND TWO HUNDRED	FOUR THOU FIVE HUND
136.0	Complete electrical line checking (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	350.000	3500.000	1500.000	200.000	THREE HUNDRED FIFTY	THREE THOUSAND FIVE HUNDRED	ONE THOU FIVE HUND

Handwritten signatures and initials in blue ink on the left side of the page, including a large signature and several smaller initials.

Handwritten signature in blue ink at the bottom right corner of the page.



137.0	Cross bearing Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	300.000	1200.000	0.000	250.000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED	ZERO
138.0	Crown overhauling (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	750.000	3850.000	3500.000	2400.000	SEVEN HUNDRED FIFTY	THREE THOUSAND EIGHT HUNDRED FIFTY	THRE THOU FIVE HUND
139.0	CV joint Boot changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	350.000	1200.000	450.000	250.000	THREE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	FOUR HUND FIFTY
140.0	CV Joint changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	400.000	1200.000	450.000	250.000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED	FOUR HUND FIFTY
141.0	CV joint oil seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	300.000	1200.000	450.000	150.000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED	FOUR HUND FIFTY
142.0	Diesel filter Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	250.000	1200.000	150.000	200.000	TWO HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED	ONE HUND FIFTY
143.0	Driver shaft oil seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	365.000	1200.000	550.000	300.000	THREE HUNDRED SIXTY FIVE	ONE THOUSAND TWO HUNDRED	FIVE HUND FIFTY
144.0	Engine Oil Changing with oil filter (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	400.000	1200.000	200.000	200.000	FOUR HUNDRED	ONE THOUSAND TWO HUNDRED	TWO HUND
145.0	Engine over hauling (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	6500.000	5450.000	25000.000	2400.000	SIX THOUSAND FIVE HUNDRED	FIVE THOUSAND FOUR HUNDRED FIFTY	TWEN FIVE THOU

146.0	Fan belt changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	200.000	1200.000	750.000	200.000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED	SEVE HUND FIFTY
147.0	Front bumper opening & fitting (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	500.000	2450.000	750.000	350.000	FIVE HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	SEVE HUND FIFTY
148.0	Gear Box mounting & dismounting (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	275.000	5500.000	2500.000	550.000	TWO HUNDRED SEVENTY FIVE	FIVE THOUSAND FIVE HUNDRED	TWO THOU FIVE HUND
149.0	Gear oil changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	200.000	1250.000	250.000	200.000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	TWO HUND FIFTY
150.0	Hub greasing (Service Charge)	4 Side	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	450.000	2500.000	1800.000	550.000	FOUR HUNDRED FIFTY	TWO THOUSAND FIVE HUNDRED	ONE THOU EIGHT HUND
151.0	King pin greasing (Service Charge)	2 Side	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	400.000	1500.000	1950.000	20.000	FOUR HUNDRED	ONE THOUSAND FIVE HUNDRED	ONE THOU NINE HUND FIFTY
152.0	Knuckle arm fitting (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	250.000	1450.000	1500.000	20.000	TWO HUNDRED FIFTY	ONE THOUSAND FOUR HUNDRED FIFTY	ONE THOU FIVE HUND
153.0	Master Cylinder Changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	175.000	1950.000	750.000	300.000	ONE HUNDRED SEVENTY FIVE	ONE THOUSAND NINE HUNDRED FIFTY	SEVE HUND FIFTY
154.0	Number Plate new making (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	650.000	2450.000	350.000	400.000	SIX HUNDRED FIFTY	TWO THOUSAND FOUR HUNDRED FIFTY	THRE HUND FIFTY

Handwritten blue ink marks and signatures on the left side of the page, including a large '7' and several scribbles.

Handwritten blue ink signature at the bottom right corner of the page.



155.0	Oil Seal changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	300,000	1200,000	350,000	200,000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED	THREE HUNDRED FIFTY
156.0	Power steering belt changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	200,000	1200,000	1250,000	150,000	TWO HUNDRED	ONE THOUSAND TWO HUNDRED	ONE THOU TWO HUND FIFTY
157.0	Radiator Servicing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	1500,000	3950,000	650,000	1100,000	ONE THOUSAND FIVE HUNDRED	THREE THOUSAND NINE HUNDRED FIFTY	SIX HUND FIFTY
158.0	Removing & Fitting of spring assy (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	400,000	2450,000	0,000	400,000	FOUR HUNDRED	TWO THOUSAND FOUR HUNDRED FIFTY	ZERO
159.0	Self starter overhauling (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	1500,000	3450,000	1250,000	1200,000	ONE THOUSAND FIVE HUNDRED	THREE THOUSAND FOUR HUNDRED FIFTY	ONE THOU TWO HUND FIFTY
160.0	Shock absorber changing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	300,000	1250,000	550,000	250,000	THREE HUNDRED	ONE THOUSAND TWO HUNDRED FIFTY	FIVE HUND FIFTY
161.0	Spring Changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	350,000	1250,000	0,000	20,000	THREE HUNDRED FIFTY	ONE THOUSAND TWO HUNDRED FIFTY	ZERO
162.0	Spring Greasing (Service Charge)	Set	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	275,000	1950,000	0,000	400,000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND NINE HUNDRED FIFTY	ZERO
163.0	Spring pad changing (Service Charge)	No	1,000	Respective Procuring Agency Office under Bumthang Dzongkhag	45,000	as per BoQ	365,000	japan	Thailand /Japan	Bhutan	THAILAND	120,000	1500,000	0,000	20,000	ONE HUNDRED TWENTY	ONE THOUSAND FIVE HUNDRED	ZERO

164.0	Stabilizer bush changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	50.000	1200.000	750.000	250.000	FIFTY	ONE THOUSAND TWO HUNDRED	SEVE HUND FIFTY
165.0	Stabilizer link assy changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	250.000	1500.000	300.000	200.000	TWO HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	THRE HUND
166.0	Steering Rack end assy (Link)changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	300.000	1500.000	1750.000	450.000	THREE HUNDRED	ONE THOUSAND FIVE HUNDRED	ONE THOU SEVE HUND FIFTY
167.0	suspension arm changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	350.000	1850.000	550.000	350.000	THREE HUNDRED FIFTY	ONE THOUSAND EIGHT HUNDRED FIFTY	FIVE HUND FIFTY
168.0	Tail pinion oil seal changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	325.000	1200.000	0.000	350.000	THREE HUNDRED TWENTY FIVE	ONE THOUSAND TWO HUNDRED	ZERO
169.0	Tappet adjustement (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	500.000	2350.000	550.000	200.000	FIVE HUNDRED	TWO THOUSAND THREE HUNDRED FIFTY	FIVE HUND FIFTY
170.0	Tie rod end changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	275.000	1450.000	450.000	300.000	TWO HUNDRED SEVENTY FIVE	ONE THOUSAND FOUR HUNDRED FIFTY	FOUR HUND FIFTY
171.0	Timing belt changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	750.000	1950.000	1850.000	850.000	SEVEN HUNDRED FIFTY	ONE THOUSAND NINE HUNDRED FIFTY	ONE THOU EIGHT HUND FIFTY
172.0	tyre Changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	300.000	1450.000	150.000	200.000	THREE HUNDRED	ONE THOUSAND FOUR HUNDRED FIFTY	ONE HUND FIFTY

Handwritten signatures and initials in blue ink on the left side of the page, including a large signature and several smaller initials.

Handwritten signature in blue ink at the bottom right corner of the page.



173.0	Vane pump changing (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	300.000	1500.000	2500.000	200.000	THREE HUNDRED	ONE THOUSAND FIVE HUNDRED	TWO THOU FIVE HUND
174.0	Welding (Service Charge)	M	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	0.000	2450.000	100.000	100.000	ZERO	TWO THOUSAND FOUR HUNDRED FIFTY	ONE HUND
175.0	Wheel Alignment (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	350.000	1500.000	350.000	400.000	THREE HUNDRED FIFTY	ONE THOUSAND FIVE HUNDRED	THRE THOU FIFTY
176.0	Whole body greasing (Service Charge)	Whole body	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	800.000	5000.000	450.000	400.000	EIGHT HUNDRED	FIVE THOUSAND	FOUR HUND FIFTY
177.0	Wind shield glass fitting (Service Charge)	No	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	2500.000	5500.000	3500.000	1800.000	TWO THOUSAND FIVE HUNDRED	FIVE THOUSAND FIVE HUNDRED	THRE THOU FIVE HUND
178.0	Wiper alignment (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	100.000	1200.000	100.000	50.000	ONE HUNDRED	ONE THOUSAND TWO HUNDRED	ONE HUND
179.0	Wiper blade changing (Service Charge)	Set	1.000	Respective Procuring Agency Office under Bumthang Dzongkhag	45.000	as per BoQ	365.000	japan	Thailand /Japan	Bhutan	THAILAND	50.000	300.000	50.000	50.000	FIFTY	THREE HUNDRED	FIFTY
							<b>Grand Total</b>											

⊕ etc awarded to Kuemman Administrative

System Generated Report based on the tender submitted by the Bidders / Consultants

Home | About e-GP | Contact Us | Terms and Conditions | e-Learning



Version: 3.3.1